

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
ABRA				
Total	45,497	41,989	221	1,451
Concrete/Brick/Stone	19,030	18,761	184	63
Wood	3,977	3,869	3	33
Half Concrete/Brick/Stone and Half Wood	10,482	9,464	20	961
Galvanized Iron/Aluminum	627	499	8	59
Bamboo/Sawali/Cogon/Nipa	11,122	9,235	-	331
Asbestos	9	9	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	27	17	-	2
Others/Not Reported	221	133	6	2
No Walls	-	-	-	-
BANGUED (Capital)				
Total	9,076	8,235	109	355
Concrete/Brick/Stone	5,031	4,918	96	10
Wood	380	333	-	16
Half Concrete/Brick/Stone and Half Wood	2,057	1,821	9	214
Galvanized Iron/Aluminum	356	267	3	40
Bamboo/Sawali/Cogon/Nipa	1,214	877	-	75
Asbestos	1	1	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	8	4	-	-
Others/Not Reported	27	12	1	-
No Walls	-	-	-	-
BOLINEY				
Total	729	727	-	-
Concrete/Brick/Stone	50	50	-	-
Wood	257	257	-	-
Half Concrete/Brick/Stone and Half Wood	210	210	-	-
Galvanized Iron/Aluminum	6	6	-	-
Bamboo/Sawali/Cogon/Nipa	203	202	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	3	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
BUWAY				
Total	3,304	3,139	2	21
Concrete/Brick/Stone	1,865	1,861	1	1
Wood	115	110	-	-
Half Concrete/Brick/Stone and Half Wood	446	440	-	4
Galvanized Iron/Aluminum	21	20	-	1
Bamboo/Sawali/Cogon/Nipa	842	696	-	15
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	15	12	1	-
No Walls	-	-	-	-
BUCLOC				
Total	393	386	-	-
Concrete/Brick/Stone	34	34	-	-
Wood	112	111	-	-
Half Concrete/Brick/Stone and Half Wood	160	159	-	-
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	85	81	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	2	1	-	-
No Walls	-	-	-	-
DAGUIOMAN				
Total	363	363	-	-
Concrete/Brick/Stone	54	54	-	-
Wood	90	90	-	-
Half Concrete/Brick/Stone and Half Wood	140	140	-	-
Galvanized Iron/Aluminum	3	3	-	-
Bamboo/Sawali/Cogon/Nipa	76	76	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	-	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

DANGLAS

Total	951	920	-	14
Concrete/Brick/Stone	168	168	-	-
Wood	5	4	-	1
Half Concrete/Brick/Stone and Half Wood	403	399	-	2
Galvanized Iron/Aluminum	7	7	-	-
Bamboo/Sawali/Cogon/Nipa	359	336	-	11
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	9	6	-	-
No Walls	-	-	-	-

DOLORES

Total	2,213	1,972	60	20
Concrete/Brick/Stone	898	831	57	9
Wood	24	18	-	-
Half Concrete/Brick/Stone and Half Wood	499	490	2	6
Galvanized Iron/Aluminum	6	3	-	3
Bamboo/Sawali/Cogon/Nipa	778	626	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	8	4	1	-
No Walls	-	-	-	-

LA PAZ

Total	2,898	2,749	1	38
Concrete/Brick/Stone	1,387	1,386	-	-
Wood	258	256	1	-
Half Concrete/Brick/Stone and Half Wood	459	424	-	34
Galvanized Iron/Aluminum	14	9	-	2
Bamboo/Sawali/Cogon/Nipa	776	672	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	3	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
LACUB				
Total	564	558	1	-
Concrete/Brick/Stone	69	68	1	-
Wood	261	261	-	-
Half Concrete/Brick/Stone and Half Wood	119	119	-	-
Galvanized Iron/Aluminum	2	2	-	-
Bamboo/Sawali/Cogon/Nipa	109	106	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	4	2	-	-
No Walls	-	-	-	-
LAGANGILANG				
Total	2,731	2,442	2	225
Concrete/Brick/Stone	1,153	1,148	2	2
Wood	75	72	-	2
Half Concrete/Brick/Stone and Half Wood	637	492	-	144
Galvanized Iron/Aluminum	11	10	-	1
Bamboo/Sawali/Cogon/Nipa	827	700	-	76
Asbestos	5	5	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	22	14	-	-
No Walls	-	-	-	-
LAGAYAN				
Total	816	787	-	7
Concrete/Brick/Stone	354	353	-	1
Wood	27	27	-	-
Half Concrete/Brick/Stone and Half Wood	111	110	-	-
Galvanized Iron/Aluminum	1	1	-	-
Bamboo/Sawali/Cogon/Nipa	313	287	-	6
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	10	9	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
LANGIDEN				
Total	608	536	1	14
Concrete/Brick/Stone	191	190	1	-
Wood	1	1	-	-
Half Concrete/Brick/Stone and Half Wood	155	148	-	7
Galvanized Iron/Aluminum	11	5	-	3
Bamboo/Sawali/Cogon/Nipa	248	192	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	2	-	-	-
No Walls	-	-	-	-
LICUAN-BAAY (LICUAN)				
Total	776	724	3	1
Concrete/Brick/Stone	156	154	2	-
Wood	227	222	1	-
Half Concrete/Brick/Stone and Half Wood	162	162	-	-
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	223	179	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	3	-	-
Others/Not Reported	5	4	-	-
No Walls	-	-	-	-
LUBA				
Total	1,239	1,184	2	2
Concrete/Brick/Stone	319	315	2	2
Wood	183	176	-	-
Half Concrete/Brick/Stone and Half Wood	465	465	-	-
Galvanized Iron/Aluminum	6	6	-	-
Bamboo/Sawali/Cogon/Nipa	263	220	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	3	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
MALIBCONG				
Total	663	649	-	1
Concrete/Brick/Stone	16	16	-	-
Wood	353	353	-	-
Half Concrete/Brick/Stone and Half Wood	171	169	-	1
Galvanized Iron/Aluminum	4	4	-	-
Bamboo/Sawali/Cogon/Nipa	116	107	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	3	-	-	-
No Walls	-	-	-	-
MANABO				
Total	2,072	1,945	4	26
Concrete/Brick/Stone	1,056	1,052	3	1
Wood	87	82	-	1
Half Concrete/Brick/Stone and Half Wood	509	499	1	8
Galvanized Iron/Aluminum	12	12	-	-
Bamboo/Sawali/Cogon/Nipa	373	286	-	14
Asbestos	3	3	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	10	5	-	2
Others/Not Reported	22	6	-	-
No Walls	-	-	-	-
PEÑARRUBIA				
Total	1,245	1,197	-	5
Concrete/Brick/Stone	657	656	-	1
Wood	16	15	-	-
Half Concrete/Brick/Stone and Half Wood	122	118	-	3
Galvanized Iron/Aluminum	36	36	-	-
Bamboo/Sawali/Cogon/Nipa	404	368	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	10	4	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
PIDIGAN				
Total	2,195	1,772	2	396
Concrete/Brick/Stone	1,171	1,146	1	24
Wood	72	62	-	10
Half Concrete/Brick/Stone and Half Wood	515	211	-	303
Galvanized Iron/Aluminum	6	4	1	1
Bamboo/Sawali/Cogon/Nipa	426	349	-	57
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	5	-	-	1
No Walls	-	-	-	-
PILAR				
Total	1,980	1,924	1	1
Concrete/Brick/Stone	762	760	-	-
Wood	186	186	-	-
Half Concrete/Brick/Stone and Half Wood	257	255	1	1
Galvanized Iron/Aluminum	34	33	-	-
Bamboo/Sawali/Cogon/Nipa	727	676	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	13	13	-	-
No Walls	-	-	-	-
SALLAPADAN				
Total	1,183	1,160	1	3
Concrete/Brick/Stone	222	219	1	2
Wood	205	205	-	-
Half Concrete/Brick/Stone and Half Wood	518	518	-	-
Galvanized Iron/Aluminum	11	10	-	1
Bamboo/Sawali/Cogon/Nipa	218	205	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	9	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
SAN ISIDRO				
Total	940	905	4	1
Concrete/Brick/Stone	410	410	-	-
Wood	147	145	-	-
Half Concrete/Brick/Stone and Half Wood	118	117	-	-
Galvanized Iron/Aluminum	16	5	4	1
Bamboo/Sawali/Cogon/Nipa	246	225	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	2	2	-	-
No Walls	-	-	-	-
SAN JUAN				
Total	1,986	1,950	1	10
Concrete/Brick/Stone	730	727	1	2
Wood	39	37	-	2
Half Concrete/Brick/Stone and Half Wood	629	625	-	2
Galvanized Iron/Aluminum	8	8	-	-
Bamboo/Sawali/Cogon/Nipa	579	553	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	1	-	-	-
No Walls	-	-	-	-
SAN QUINTIN				
Total	1,082	1,067	-	-
Concrete/Brick/Stone	467	467	-	-
Wood	35	35	-	-
Half Concrete/Brick/Stone and Half Wood	406	406	-	-
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	171	158	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	2	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
TAYUM				
Total	2,725	2,144	20	305
Concrete/Brick/Stone	1,262	1,246	10	3
Wood	261	258	-	-
Half Concrete/Brick/Stone and Half Wood	554	307	7	232
Galvanized Iron/Aluminum	14	6	-	6
Bamboo/Sawali/Cogon/Nipa	606	304	-	63
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	28	23	3	1
No Walls	-	-	-	-
TINEG				
Total	702	535	1	-
Concrete/Brick/Stone	10	10	-	-
Wood	231	225	1	-
Half Concrete/Brick/Stone and Half Wood	32	32	-	-
Galvanized Iron/Aluminum	2	2	-	-
Bamboo/Sawali/Cogon/Nipa	425	264	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	2	2	-	-
No Walls	-	-	-	-
TUBO				
Total	996	978	5	4
Concrete/Brick/Stone	184	176	5	3
Wood	128	127	-	1
Half Concrete/Brick/Stone and Half Wood	409	409	-	-
Galvanized Iron/Aluminum	27	27	-	-
Bamboo/Sawali/Cogon/Nipa	244	236	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	4	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

VILLAVICIOSA

Total	1,067	1,041	1	2
Concrete/Brick/Stone	354	346	1	2
Wood	202	201	-	-
Half Concrete/Brick/Stone and Half Wood	219	219	-	-
Galvanized Iron/Aluminum	13	13	-	-
Bamboo/Sawali/Cogon/Nipa	271	254	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	7	7	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ABRA					
Total	224	1,461	15	28	108
Concrete/Brick/Stone	3	6	-	6	7
Wood	30	34	4	2	2
Half Concrete/Brick/Stone and Half Wood	21	7	2	-	7
Galvanized Iron/Aluminum	56	3	-	-	2
Bamboo/Sawali/Cogon/Nipa	113	1,401	6	20	16
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	4	3	-	-
Others/Not Reported	-	6	-	-	74
No Walls	-	-	-	-	-
BANGUED (Capital)					
Total	96	252	7	1	21
Concrete/Brick/Stone	1	2	-	1	3
Wood	17	11	3	-	-
Half Concrete/Brick/Stone and Half Wood	12	1	-	-	-
Galvanized Iron/Aluminum	44	1	-	-	1
Bamboo/Sawali/Cogon/Nipa	22	236	1	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	3	-	-
Others/Not Reported	-	-	-	-	14
No Walls	-	-	-	-	-
BOLINEY					
Total	-	1	-	-	1
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	1	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BUCA Y					
Total	1	137	-	-	4
Concrete/Brick/Stone	-	1	-	-	1
Wood	-	5	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	130	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
BUCLOC					
Total	-	-	-	5	2
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	-	-	4	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-
DAGUIOMAN					
Total	-	-	-	-	-
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	-	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
DANGLAS					
Total	-	10	-	-	7
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	2
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	10	-	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	3
No Walls	-	-	-	-	-
DOLORES					
Total	61	96	1	-	3
Concrete/Brick/Stone	-	1	-	-	-
Wood	6	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	54	94	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	2
No Walls	-	-	-	-	-
LA PAZ					
Total	3	102	3	-	2
Concrete/Brick/Stone	-	-	-	-	1
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	2	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	99	3	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LACUB					
Total	-	3	-	-	2
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	3	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
LAGANGILANG					
Total	1	52	3	2	4
Concrete/Brick/Stone	-	1	-	-	-
Wood	-	-	1	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	1	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	46	1	2	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	5	-	-	3
No Walls	-	-	-	-	-
LAGAYAN					
Total	-	21	-	-	1
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	20	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LANGIDEN					
Total	5	50	-	-	2
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	3	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	50	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
LICUAN-BAAY (LICUAN)					
Total	5	35	-	5	3
Concrete/Brick/Stone	-	-	-	-	-
Wood	2	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	33	-	5	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-
LUBA					
Total	-	50	-	-	1
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	7	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	43	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MALIBCONG					
Total	-	10	-	-	3
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	9	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	3
No Walls	-	-	-	-	-
MANABO					
Total	10	69	1	1	16
Concrete/Brick/Stone	-	-	-	-	-
Wood	3	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	1	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	65	-	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	-	-	-	16
No Walls	-	-	-	-	-
PEÑARRUBIA					
Total	-	36	-	-	7
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	35	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PIDIGAN					
Total	4	15	-	-	6
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	15	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	4
No Walls	-	-	-	-	-
PILAR					
Total	-	51	-	1	2
Concrete/Brick/Stone	-	-	-	1	1
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	1
Bamboo/Sawali/Cogon/Nipa	-	51	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-
SALLAPADAN					
Total	-	7	-	6	6
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	7	-	6	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAN ISIDRO					
Total	6	23	-	-	1
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	6	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	20	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-
SAN JUAN					
Total	2	21	-	-	2
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	20	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-
SAN QUINTIN					
Total	-	13	-	-	2
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	13	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
TAYUM					
Total	26	226	-	1	3
Concrete/Brick/Stone	2	1	-	-	-
Wood	2	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	8	-	-	-	-
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	13	223	-	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-
TINEG					
Total	1	160	-	-	5
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	3	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	157	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-
TUBO					
Total	-	8	-	-	1
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	8	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

VILLAVICIOSA

Total	3	13	-	6	1
Concrete/Brick/Stone	-	-	-	4	1
Wood	-	-	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	13	-	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-