

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
APAYAO				
Total	20,923	17,571	34	311
Concrete/Brick/Stone	5,948	5,867	25	21
Wood	7,717	6,396	5	92
Half Concrete/Brick/Stone and Half Wood	3,904	3,618	1	164
Galvanized Iron/Aluminum	83	65	1	4
Bamboo/Sawali/Cogon/Nipa	3,117	1,561	-	28
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	22	9	-	-
Others/Not Reported	129	54	2	2
No Walls	2	1	-	-
CALANASAN (BAYAG)				
Total	1,890	1,768	2	7
Concrete/Brick/Stone	343	340	1	-
Wood	1,160	1,109	1	5
Half Concrete/Brick/Stone and Half Wood	219	215	-	2
Galvanized Iron/Aluminum	3	3	-	-
Bamboo/Sawali/Cogon/Nipa	159	99	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	6	2	-	-
No Walls	-	-	-	-
CONNER				
Total	4,317	3,833	2	28
Concrete/Brick/Stone	674	669	-	3
Wood	1,428	1,368	1	2
Half Concrete/Brick/Stone and Half Wood	1,072	1,057	-	11
Galvanized Iron/Aluminum	29	27	-	1
Bamboo/Sawali/Cogon/Nipa	1,082	697	-	10
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	2	-	-
Others/Not Reported	30	13	1	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
FLORA				
Total	3,378	2,795	2	55
Concrete/Brick/Stone	1,022	1,013	-	5
Wood	1,679	1,363	2	32
Half Concrete/Brick/Stone and Half Wood	328	305	-	15
Galvanized Iron/Aluminum	4	3	-	-
Bamboo/Sawali/Cogon/Nipa	324	101	-	3
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	14	5	-	-
Others/Not Reported	7	5	-	-
No Walls	-	-	-	-
KABUGAO (Capital)				
Total	2,819	2,404	21	22
Concrete/Brick/Stone	494	474	18	2
Wood	1,158	1,122	1	3
Half Concrete/Brick/Stone and Half Wood	406	397	1	6
Galvanized Iron/Aluminum	7	6	-	1
Bamboo/Sawali/Cogon/Nipa	701	391	-	9
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	51	13	1	1
No Walls	2	1	-	-
LUNA				
Total	3,436	2,676	4	43
Concrete/Brick/Stone	1,069	1,046	4	4
Wood	1,079	624	-	7
Half Concrete/Brick/Stone and Half Wood	1,018	946	-	30
Galvanized Iron/Aluminum	25	16	-	1
Bamboo/Sawali/Cogon/Nipa	230	39	-	1
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	13	5	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

PUDTOL

Total	2,537	1,883	2	119
Concrete/Brick/Stone	859	849	1	3
Wood	709	379	-	28
Half Concrete/Brick/Stone and Half Wood	687	547	-	85
Galvanized Iron/Aluminum	13	9	1	1
Bamboo/Sawali/Cogon/Nipa	263	97	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	6	2	-	-
No Walls	-	-	-	-

SANTA MARCELA

Total	2,546	2,212	1	37
Concrete/Brick/Stone	1,487	1,476	1	4
Wood	504	431	-	15
Half Concrete/Brick/Stone and Half Wood	174	151	-	15
Galvanized Iron/Aluminum	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	358	137	-	3
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	2	-	-
Others/Not Reported	16	14	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
APAYAO					
Total	109	2,323	8	478	89
Concrete/Brick/Stone	1	26	-	2	6
Wood	25	1,133	-	59	7
Half Concrete/Brick/Stone and Half Wood	7	109	-	2	3
Galvanized Iron/Aluminum	2	10	-	1	-
Bamboo/Sawali/Cogon/Nipa	74	1,034	3	409	8
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	5	-	-
Others/Not Reported	-	2	-	4	65
No Walls	-	1	-	-	-
CALANASAN (BAYAG)					
Total	3	103	-	-	7
Concrete/Brick/Stone	-	1	-	-	1
Wood	1	42	-	-	2
Half Concrete/Brick/Stone and Half Wood	2	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	60	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	4
No Walls	-	-	-	-	-
CONNER					
Total	27	107	1	300	19
Concrete/Brick/Stone	-	-	-	2	-
Wood	4	11	-	41	1
Half Concrete/Brick/Stone and Half Wood	-	2	-	1	1
Galvanized Iron/Aluminum	-	-	-	1	-
Bamboo/Sawali/Cogon/Nipa	23	93	1	255	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	14
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
FLORA					
Total	4	501	5	12	4
Concrete/Brick/Stone	-	4	-	-	-
Wood	2	270	-	8	2
Half Concrete/Brick/Stone and Half Wood	-	7	-	1	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	213	2	2	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	3	-	-
Others/Not Reported	-	-	-	1	1
No Walls	-	-	-	-	-
KABUGAO (Capital)					
Total	45	123	-	165	39
Concrete/Brick/Stone	-	-	-	-	-
Wood	4	17	-	10	1
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	41	104	-	152	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	3	33
No Walls	-	1	-	-	-
LUNA					
Total	18	681	-	1	13
Concrete/Brick/Stone	1	11	-	-	3
Wood	7	440	-	-	1
Half Concrete/Brick/Stone and Half Wood	2	39	-	-	1
Galvanized Iron/Aluminum	2	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	184	-	-	-
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	-	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

PUDTOL

Total	10	517	-	-	6
Concrete/Brick/Stone	-	4	-	-	2
Wood	6	296	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	53	-	-	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	162	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	4
No Walls	-	-	-	-	-

SANTA MARCELA

Total	2	291	2	-	1
Concrete/Brick/Stone	-	6	-	-	-
Wood	1	57	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	7	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	218	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	2	-	-
Others/Not Reported	-	1	-	-	1
No Walls	-	-	-	-	-