

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
DINAGAT ISLANDS				
Total	23,516	14,441	40	439
Concrete/Brick/Stone	3,599	3,463	27	21
Wood	12,883	8,004	6	68
Half Concrete/Brick/Stone and Half Wood	2,998	2,466	7	317
Galvanized Iron/Aluminum	131	86	-	21
Bamboo/Sawali/Cogon/Nipa	3,456	355	-	11
Asbestos	3	3	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	105	20	-	-
Others/Not Reported	339	44	-	1
No Walls	1	-	-	-
BASILISA (RIZAL)				
Total	5,914	3,845	6	21
Concrete/Brick/Stone	480	468	2	1
Wood	4,309	2,803	4	8
Half Concrete/Brick/Stone and Half Wood	521	494	-	7
Galvanized Iron/Aluminum	9	7	-	-
Bamboo/Sawali/Cogon/Nipa	560	70	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	2	-	-
Others/Not Reported	28	1	-	-
No Walls	-	-	-	-
CAGDIANAO				
Total	2,890	1,495	1	150
Concrete/Brick/Stone	552	537	1	1
Wood	1,381	626	-	11
Half Concrete/Brick/Stone and Half Wood	367	215	-	120
Galvanized Iron/Aluminum	47	29	-	15
Bamboo/Sawali/Cogon/Nipa	520	84	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	23	4	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
DINAGAT				
Total	2,163	1,024	1	3
Concrete/Brick/Stone	467	444	1	-
Wood	452	260	-	1
Half Concrete/Brick/Stone and Half Wood	290	228	-	1
Galvanized Iron/Aluminum	3	2	-	-
Bamboo/Sawali/Cogon/Nipa	861	70	-	1
Asbestos	-	-	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	60	15	-	-
Others/Not Reported	29	5	-	-
No Walls	-	-	-	-
LIBJO (ALBOR)				
Total	3,708	2,369	20	141
Concrete/Brick/Stone	482	460	15	3
Wood	2,160	1,593	1	14
Half Concrete/Brick/Stone and Half Wood	352	214	4	118
Galvanized Iron/Aluminum	38	31	-	4
Bamboo/Sawali/Cogon/Nipa	583	63	-	2
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	-	-	-
Others/Not Reported	88	6	-	-
No Walls	-	-	-	-
LORETO				
Total	1,729	1,052	-	4
Concrete/Brick/Stone	567	548	-	1
Wood	657	326	-	2
Half Concrete/Brick/Stone and Half Wood	191	166	-	1
Galvanized Iron/Aluminum	2	2	-	-
Bamboo/Sawali/Cogon/Nipa	303	7	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	9	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SAN JOSE

Total	5,513	3,653	12	119
Concrete/Brick/Stone	753	711	8	15
Wood	2,924	1,836	1	31
Half Concrete/Brick/Stone and Half Wood	1,119	1,007	3	70
Galvanized Iron/Aluminum	31	15	-	2
Bamboo/Sawali/Cogon/Nipa	523	60	-	1
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	16	2	-	-
Others/Not Reported	145	21	-	-
No Walls	1	-	-	-

UBAJON

Total	1,599	1,003	-	1
Concrete/Brick/Stone	298	295	-	-
Wood	1,000	560	-	1
Half Concrete/Brick/Stone and Half Wood	158	142	-	-
Galvanized Iron/Aluminum	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	106	1	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	19	1	-	-
Others/Not Reported	17	4	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
DINAGAT ISLANDS					
Total	414	7,831	39	8	304
Concrete/Brick/Stone	1	76	-	2	9
Wood	261	4,528	2	3	11
Half Concrete/Brick/Stone and Half Wood	21	179	2	2	4
Galvanized Iron/Aluminum	11	12	-	-	1
Bamboo/Sawali/Cogon/Nipa	113	2,965	2	1	9
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	1	51	33	-	-
Others/Not Reported	5	20	-	-	269
No Walls	1	-	-	-	-
BASILISA (RIZAL)					
Total	44	1,977	-	2	19
Concrete/Brick/Stone	-	9	-	-	-
Wood	35	1,457	-	2	-
Half Concrete/Brick/Stone and Half Wood	1	19	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	1
Bamboo/Sawali/Cogon/Nipa	8	477	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	-	-	-
Others/Not Reported	-	9	-	-	18
No Walls	-	-	-	-	-
CAGDIANAO					
Total	52	1,174	-	-	18
Concrete/Brick/Stone	-	13	-	-	-
Wood	28	714	-	-	2
Half Concrete/Brick/Stone and Half Wood	3	29	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	21	412	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	3	-	-	15
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
DINAGAT					
Total	14	1,052	32	3	34
Concrete/Brick/Stone	-	16	-	2	4
Wood	11	178	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	59	-	1	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	783	1	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	14	31	-	-
Others/Not Reported	-	1	-	-	23
No Walls	-	-	-	-	-
LIBJO (ALBOR)					
Total	213	880	1	-	84
Concrete/Brick/Stone	1	2	-	-	1
Wood	129	423	-	-	-
Half Concrete/Brick/Stone and Half Wood	8	7	1	-	-
Galvanized Iron/Aluminum	2	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	71	445	-	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	2	-	-	-
Others/Not Reported	1	-	-	-	81
No Walls	-	-	-	-	-
LORETO					
Total	7	660	1	-	5
Concrete/Brick/Stone	-	18	-	-	-
Wood	7	322	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	24	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	295	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	5
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAN JOSE					
Total	76	1,519	4	3	127
Concrete/Brick/Stone	-	17	-	-	2
Wood	44	1,004	2	1	5
Half Concrete/Brick/Stone and Half Wood	9	25	1	1	3
Galvanized Iron/Aluminum	9	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	9	449	-	1	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	13	1	-	-
Others/Not Reported	4	6	-	-	114
No Walls	1	-	-	-	-
UBAJON					
Total	8	569	1	-	17
Concrete/Brick/Stone	-	1	-	-	2
Wood	7	430	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	16	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	104	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	17	1	-	-
Others/Not Reported	-	-	-	-	13
No Walls	-	-	-	-	-