

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

ISABELA

Total	303,365	258,411	944	12,300
Concrete/Brick/Stone	152,495	150,664	465	734
Wood	25,367	20,880	38	863
Half Concrete/Brick/Stone and Half Wood	54,712	46,232	326	7,356
Galvanized Iron/Aluminum	4,812	3,818	29	709
Bamboo/Sawali/Cogon/Nipa	63,449	35,420	-	2,574
Asbestos	49	35	2	4
Glass	33	28	-	3
Makeshift/Salvaged/Improvised Materials	843	495	-	32
Others/Not Reported	1,604	839	84	25
No Walls	1	-	-	-

ALICIA

Total	13,604	12,447	22	243
Concrete/Brick/Stone	7,955	7,900	17	18
Wood	648	583	1	24
Half Concrete/Brick/Stone and Half Wood	1,482	1,358	2	102
Galvanized Iron/Aluminum	385	339	1	31
Bamboo/Sawali/Cogon/Nipa	3,017	2,188	-	66
Asbestos	10	10	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	43	27	-	2
Others/Not Reported	64	42	1	-
No Walls	-	-	-	-

ANGADANAN

Total	8,394	7,304	6	464
Concrete/Brick/Stone	4,011	3,993	3	7
Wood	434	390	1	35
Half Concrete/Brick/Stone and Half Wood	1,528	1,195	2	325
Galvanized Iron/Aluminum	82	67	-	13
Bamboo/Sawali/Cogon/Nipa	2,269	1,618	-	82
Asbestos	2	1	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	33	27	-	1
Others/Not Reported	35	13	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

AURORA

Total	7,157	5,625	2	1,017
Concrete/Brick/Stone	3,827	3,671	1	148
Wood	291	178	-	82
Half Concrete/Brick/Stone and Half Wood	1,642	1,103	1	519
Galvanized Iron/Aluminum	76	36	-	39
Bamboo/Sawali/Cogon/Nipa	1,249	603	-	226
Asbestos	3	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	22	10	-	-
Others/Not Reported	47	24	-	3
No Walls	-	-	-	-

BENITO SOLIVEN

Total	5,554	4,665	1	125
Concrete/Brick/Stone	2,346	2,342	-	-
Wood	474	457	-	5
Half Concrete/Brick/Stone and Half Wood	529	515	-	11
Galvanized Iron/Aluminum	40	32	-	8
Bamboo/Sawali/Cogon/Nipa	2,121	1,289	-	101
Asbestos	2	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	6	-	-
Others/Not Reported	33	23	1	-
No Walls	-	-	-	-

BURGOS

Total	4,833	3,843	1	372
Concrete/Brick/Stone	2,291	2,276	1	8
Wood	90	53	-	22
Half Concrete/Brick/Stone and Half Wood	1,051	806	-	234
Galvanized Iron/Aluminum	29	25	-	1
Bamboo/Sawali/Cogon/Nipa	1,314	664	-	106
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	29	9	-	1
Others/Not Reported	29	10	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

CABAGAN

Total	8,298	7,024	22	549
Concrete/Brick/Stone	3,742	3,711	16	7
Wood	492	393	-	46
Half Concrete/Brick/Stone and Half Wood	2,208	1,697	5	482
Galvanized Iron/Aluminum	68	64	1	2
Bamboo/Sawali/Cogon/Nipa	1,657	1,060	-	12
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	22	7	-	-
Others/Not Reported	109	92	-	-
No Walls	-	-	-	-

CABATUAN

Total	7,489	7,002	14	228
Concrete/Brick/Stone	4,852	4,830	12	2
Wood	173	168	-	2
Half Concrete/Brick/Stone and Half Wood	1,417	1,210	2	194
Galvanized Iron/Aluminum	50	43	-	6
Bamboo/Sawali/Cogon/Nipa	956	731	-	24
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	2	-	-
Others/Not Reported	37	18	-	-
No Walls	-	-	-	-

CITY OF CAUAYAN

Total	24,777	21,058	44	1,889
Concrete/Brick/Stone	11,890	11,769	19	46
Wood	1,079	892	15	77
Half Concrete/Brick/Stone and Half Wood	6,253	5,015	6	1,178
Galvanized Iron/Aluminum	409	333	2	63
Bamboo/Sawali/Cogon/Nipa	5,002	2,970	-	510
Asbestos	6	2	-	2
Glass	3	3	-	-
Makeshift/Salvaged/Improvised Materials	40	28	-	8
Others/Not Reported	95	46	2	5
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

CORDON

Total	8,662	6,975	5	240
Concrete/Brick/Stone	4,246	4,190	4	25
Wood	936	606	1	16
Half Concrete/Brick/Stone and Half Wood	1,047	894	-	122
Galvanized Iron/Aluminum	426	400	-	3
Bamboo/Sawali/Cogon/Nipa	1,819	793	-	72
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	36	13	-	2
Others/Not Reported	152	79	-	-
No Walls	-	-	-	-

DINAPIGUE

Total	1,046	703	-	9
Concrete/Brick/Stone	302	299	-	1
Wood	626	323	-	3
Half Concrete/Brick/Stone and Half Wood	82	75	-	5
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	20	3	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	-	-	-
Others/Not Reported	9	3	-	-
No Walls	-	-	-	-

DIVILICAN

Total	857	384	1	5
Concrete/Brick/Stone	39	39	-	-
Wood	603	283	-	4
Half Concrete/Brick/Stone and Half Wood	63	61	-	-
Galvanized Iron/Aluminum	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	118	-	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	8	-	-	-
Others/Not Reported	25	1	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

ECHAGUE

Total	15,135	12,834	28	674
Concrete/Brick/Stone	7,630	7,584	20	12
Wood	1,968	1,747	-	70
Half Concrete/Brick/Stone and Half Wood	2,565	2,019	4	486
Galvanized Iron/Aluminum	158	125	4	14
Bamboo/Sawali/Cogon/Nipa	2,726	1,316	-	86
Asbestos	2	2	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	41	18	-	3
Others/Not Reported	44	23	-	3
No Walls	-	-	-	-

GAMU

Total	6,050	4,942	426	96
Concrete/Brick/Stone	3,577	3,441	114	10
Wood	197	183	1	1
Half Concrete/Brick/Stone and Half Wood	805	517	237	39
Galvanized Iron/Aluminum	51	33	7	5
Bamboo/Sawali/Cogon/Nipa	1,304	742	-	39
Asbestos	4	2	2	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	3	-	-
Others/Not Reported	106	21	65	2
No Walls	-	-	-	-

ILAGAN (Capital)

Total	28,531	25,847	111	488
Concrete/Brick/Stone	14,102	13,948	66	43
Wood	2,699	2,480	5	35
Half Concrete/Brick/Stone and Half Wood	6,706	6,299	32	321
Galvanized Iron/Aluminum	317	265	6	36
Bamboo/Sawali/Cogon/Nipa	4,538	2,762	-	50
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	75	55	-	1
Others/Not Reported	94	38	2	2
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

JONES

Total	9,045	8,258	15	370
Concrete/Brick/Stone	3,274	3,248	9	15
Wood	1,388	1,253	-	93
Half Concrete/Brick/Stone and Half Wood	2,842	2,666	2	164
Galvanized Iron/Aluminum	146	123	1	18
Bamboo/Sawali/Cogon/Nipa	1,333	925	-	80
Asbestos	4	4	-	-
Glass	7	7	-	-
Makeshift/Salvaged/Improvised Materials	26	21	-	-
Others/Not Reported	25	11	3	-
No Walls	-	-	-	-

LUNA

Total	3,734	3,637	-	5
Concrete/Brick/Stone	2,816	2,812	-	-
Wood	65	64	-	-
Half Concrete/Brick/Stone and Half Wood	373	368	-	3
Galvanized Iron/Aluminum	18	17	-	-
Bamboo/Sawali/Cogon/Nipa	450	374	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	12	2	-	-
No Walls	-	-	-	-

MACONACON

Total	844	723	-	3
Concrete/Brick/Stone	130	129	-	-
Wood	618	508	-	2
Half Concrete/Brick/Stone and Half Wood	84	82	-	1
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	-	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	1	-	-
Others/Not Reported	6	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

DELFIN ALBANO (MAGSAYSAY)

Total	5,479	4,636	7	24
Concrete/Brick/Stone	3,227	3,171	7	5
Wood	96	63	-	-
Half Concrete/Brick/Stone and Half Wood	493	453	-	10
Galvanized Iron/Aluminum	91	87	-	1
Bamboo/Sawali/Cogon/Nipa	1,544	844	-	8
Asbestos	-	-	-	-
Glass	6	6	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	20	12	-	-
No Walls	-	-	-	-

MALLIG

Total	5,903	3,498	11	688
Concrete/Brick/Stone	2,462	2,328	4	39
Wood	153	73	-	25
Half Concrete/Brick/Stone and Half Wood	1,005	445	7	454
Galvanized Iron/Aluminum	406	291	-	82
Bamboo/Sawali/Cogon/Nipa	1,834	343	-	84
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	11	7	-	-
Others/Not Reported	32	11	-	4
No Walls	-	-	-	-

NAGUILIAN

Total	6,110	5,123	43	179
Concrete/Brick/Stone	2,713	2,657	43	10
Wood	354	292	-	16
Half Concrete/Brick/Stone and Half Wood	1,081	979	-	93
Galvanized Iron/Aluminum	63	37	-	10
Bamboo/Sawali/Cogon/Nipa	1,856	1,125	-	50
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	4	-	-
Others/Not Reported	35	28	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

PALANAN

Total	3,117	2,043	2	165
Concrete/Brick/Stone	66	66	-	-
Wood	2,209	1,597	1	34
Half Concrete/Brick/Stone and Half Wood	495	370	1	122
Galvanized Iron/Aluminum	10	1	-	5
Bamboo/Sawali/Cogon/Nipa	319	9	-	4
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	-	-	-
Others/Not Reported	9	-	-	-
No Walls	-	-	-	-

QUEZON

Total	4,856	3,093	7	26
Concrete/Brick/Stone	2,557	2,484	6	6
Wood	322	141	-	-
Half Concrete/Brick/Stone and Half Wood	250	206	-	12
Galvanized Iron/Aluminum	33	24	1	-
Bamboo/Sawali/Cogon/Nipa	1,658	225	-	8
Asbestos	5	5	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	10	5	-	-
Others/Not Reported	21	3	-	-
No Walls	-	-	-	-

QUIRINO

Total	5,073	3,934	-	138
Concrete/Brick/Stone	3,229	3,078	-	80
Wood	125	83	-	4
Half Concrete/Brick/Stone and Half Wood	322	249	-	19
Galvanized Iron/Aluminum	18	13	-	2
Bamboo/Sawali/Cogon/Nipa	1,351	495	-	33
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	18	11	-	-
Others/Not Reported	10	5	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

RAMON

Total	10,290	8,828	4	371
Concrete/Brick/Stone	5,584	5,566	3	9
Wood	407	337	1	5
Half Concrete/Brick/Stone and Half Wood	1,633	1,406	-	205
Galvanized Iron/Aluminum	204	155	-	37
Bamboo/Sawali/Cogon/Nipa	2,388	1,318	-	113
Asbestos	1	-	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	49	32	-	1
Others/Not Reported	24	14	-	-
No Walls	-	-	-	-

REINA MERCEDES

Total	4,645	4,470	3	24
Concrete/Brick/Stone	2,750	2,744	2	-
Wood	118	116	-	-
Half Concrete/Brick/Stone and Half Wood	819	805	-	10
Galvanized Iron/Aluminum	33	33	-	-
Bamboo/Sawali/Cogon/Nipa	873	732	-	12
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	11	8	-	2
Others/Not Reported	41	32	1	-
No Walls	-	-	-	-

ROXAS

Total	12,139	10,598	25	204
Concrete/Brick/Stone	6,496	6,446	16	13
Wood	639	597	2	2
Half Concrete/Brick/Stone and Half Wood	1,700	1,556	7	105
Galvanized Iron/Aluminum	235	191	-	36
Bamboo/Sawali/Cogon/Nipa	3,013	1,781	-	48
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	38	20	-	-
Others/Not Reported	17	7	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SAN AGUSTIN

Total	4,510	3,907	12	429
Concrete/Brick/Stone	2,311	2,300	6	3
Wood	372	263	2	77
Half Concrete/Brick/Stone and Half Wood	1,405	1,152	4	245
Galvanized Iron/Aluminum	54	23	-	30
Bamboo/Sawali/Cogon/Nipa	347	152	-	74
Asbestos	3	3	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	5	5	-	-
Others/Not Reported	13	9	-	-
No Walls	-	-	-	-

SAN GUILLERMO

Total	3,634	2,877	-	495
Concrete/Brick/Stone	931	901	-	30
Wood	974	901	-	14
Half Concrete/Brick/Stone and Half Wood	649	450	-	198
Galvanized Iron/Aluminum	18	15	-	3
Bamboo/Sawali/Cogon/Nipa	1,045	606	-	250
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	17	4	-	-
No Walls	-	-	-	-

SAN ISIDRO

Total	4,680	4,249	2	26
Concrete/Brick/Stone	2,951	2,942	-	1
Wood	170	140	-	1
Half Concrete/Brick/Stone and Half Wood	336	310	-	9
Galvanized Iron/Aluminum	97	88	-	1
Bamboo/Sawali/Cogon/Nipa	1,091	756	-	13
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	24	13	-	1
Others/Not Reported	11	-	2	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SAN MANUEL

Total	6,445	4,870	9	509
Concrete/Brick/Stone	2,938	2,878	4	43
Wood	362	182	-	16
Half Concrete/Brick/Stone and Half Wood	953	690	1	232
Galvanized Iron/Aluminum	317	191	2	106
Bamboo/Sawali/Cogon/Nipa	1,813	905	-	109
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	20	7	-	2
Others/Not Reported	41	17	2	1
No Walls	-	-	-	-

SAN MARIANO

Total	9,327	7,243	3	132
Concrete/Brick/Stone	2,625	2,619	-	4
Wood	2,024	1,673	1	38
Half Concrete/Brick/Stone and Half Wood	1,499	1,446	2	44
Galvanized Iron/Aluminum	32	26	-	3
Bamboo/Sawali/Cogon/Nipa	3,102	1,462	-	43
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	2	-	-
Others/Not Reported	40	15	-	-
No Walls	1	-	-	-

SAN MATEO

Total	12,832	11,715	7	524
Concrete/Brick/Stone	7,967	7,935	4	16
Wood	455	423	1	-
Half Concrete/Brick/Stone and Half Wood	2,436	2,000	1	419
Galvanized Iron/Aluminum	243	202	-	33
Bamboo/Sawali/Cogon/Nipa	1,671	1,115	-	54
Asbestos	-	-	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	30	23	-	1
Others/Not Reported	29	17	1	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SAN PABLO

Total	4,063	3,255	4	477
Concrete/Brick/Stone	2,124	2,022	2	98
Wood	209	99	2	67
Half Concrete/Brick/Stone and Half Wood	989	748	-	236
Galvanized Iron/Aluminum	43	25	-	16
Bamboo/Sawali/Cogon/Nipa	678	355	-	59
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	20	6	-	1
No Walls	-	-	-	-

SANTA MARIA

Total	3,895	2,623	10	37
Concrete/Brick/Stone	1,671	1,635	7	8
Wood	144	117	-	-
Half Concrete/Brick/Stone and Half Wood	539	459	-	25
Galvanized Iron/Aluminum	28	22	1	1
Bamboo/Sawali/Cogon/Nipa	1,479	369	-	3
Asbestos	-	-	-	-
Glass	9	9	-	-
Makeshift/Salvaged/Improvised Materials	3	-	-	-
Others/Not Reported	22	12	2	-
No Walls	-	-	-	-

CITY OF SANTIAGO

Total	26,858	25,219	44	444
Concrete/Brick/Stone	16,146	16,073	34	10
Wood	2,623	2,498	3	21
Half Concrete/Brick/Stone and Half Wood	4,140	3,805	4	308
Galvanized Iron/Aluminum	442	388	2	29
Bamboo/Sawali/Cogon/Nipa	3,127	2,175	-	69
Asbestos	-	-	-	-
Glass	3	3	-	-
Makeshift/Salvaged/Improvised Materials	181	123	-	7
Others/Not Reported	196	154	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SANTO TOMAS

Total	4,388	3,936	45	94
Concrete/Brick/Stone	1,862	1,812	38	7
Wood	430	405	-	3
Half Concrete/Brick/Stone and Half Wood	936	880	6	43
Galvanized Iron/Aluminum	43	28	1	12
Bamboo/Sawali/Cogon/Nipa	1,099	799	-	29
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	17	11	-	-
No Walls	-	-	-	-

TUMAUNI

Total	11,111	9,023	8	537
Concrete/Brick/Stone	4,855	4,825	7	10
Wood	400	319	1	23
Half Concrete/Brick/Stone and Half Wood	2,355	1,943	-	381
Galvanized Iron/Aluminum	146	76	-	63
Bamboo/Sawali/Cogon/Nipa	3,267	1,816	-	54
Asbestos	4	4	-	-
Glass	3	-	-	3
Makeshift/Salvaged/Improvised Materials	14	7	-	-
Others/Not Reported	67	33	-	3
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

ISABELA

Total	1,555	28,921	224	324	686
Concrete/Brick/Stone	60	449	5	34	84
Wood	520	2,975	23	39	29
Half Concrete/Brick/Stone and Half Wood	96	621	15	15	51
Galvanized Iron/Aluminum	65	185	1	2	3
Bamboo/Sawali/Cogon/Nipa	794	24,350	60	182	69
Asbestos	2	-	-	6	-
Glass	-	-	-	1	1
Makeshift/Salvaged/Improvised Materials	5	187	119	4	1
Others/Not Reported	13	153	1	41	448
No Walls	-	1	-	-	-

ALICIA

Total	11	845	4	4	28
Concrete/Brick/Stone	2	10	-	1	7
Wood	1	38	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	17	-	-	3
Galvanized Iron/Aluminum	7	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	761	-	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	10	4	-	-
Others/Not Reported	-	2	-	1	18
No Walls	-	-	-	-	-

ANGADANAN

Total	12	571	8	1	28
Concrete/Brick/Stone	2	1	-	-	5
Wood	1	6	1	-	-
Half Concrete/Brick/Stone and Half Wood	2	3	-	-	1
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	558	2	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	5	-	-
Others/Not Reported	-	2	-	-	20
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
AURORA					
Total	39	405	23	20	26
Concrete/Brick/Stone	-	3	1	1	2
Wood	7	24	-	-	-
Half Concrete/Brick/Stone and Half Wood	9	6	-	-	4
Galvanized Iron/Aluminum	-	-	-	1	-
Bamboo/Sawali/Cogon/Nipa	22	368	13	14	3
Asbestos	-	-	-	3	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	9	-	-
Others/Not Reported	1	1	-	1	17
No Walls	-	-	-	-	-
BENITO SOLIVEN					
Total	35	633	3	67	25
Concrete/Brick/Stone	1	1	-	1	1
Wood	2	8	-	2	-
Half Concrete/Brick/Stone and Half Wood	1	2	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	31	619	3	63	15
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	-	-	-	9
No Walls	-	-	-	-	-
BURGOS					
Total	3	577	14	2	21
Concrete/Brick/Stone	-	5	-	-	1
Wood	-	15	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	10	-	-	1
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	533	4	2	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	9	10	-	-
Others/Not Reported	-	2	-	-	17
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
CABAGAN					
Total	23	648	-	-	32
Concrete/Brick/Stone	-	1	-	-	7
Wood	11	41	-	-	1
Half Concrete/Brick/Stone and Half Wood	2	18	-	-	4
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	572	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	15	-	-	-
Others/Not Reported	-	-	-	-	17
No Walls	-	-	-	-	-
CABATUAN					
Total	16	199	2	2	26
Concrete/Brick/Stone	-	2	-	2	4
Wood	2	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	9	-	-	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	13	185	1	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	-	-	-	19
No Walls	-	-	-	-	-
CITY OF CAUAYAN					
Total	141	1,560	4	14	67
Concrete/Brick/Stone	13	23	-	7	13
Wood	58	33	-	1	3
Half Concrete/Brick/Stone and Half Wood	14	30	-	-	10
Galvanized Iron/Aluminum	4	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	47	1,462	1	5	7
Asbestos	1	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	3	-	-
Others/Not Reported	4	4	-	-	34
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

CORDON

Total	17	1,355	10	48	12
Concrete/Brick/Stone	-	24	-	2	1
Wood	12	284	4	12	1
Half Concrete/Brick/Stone and Half Wood	3	25	-	3	-
Galvanized Iron/Aluminum	-	22	-	1	-
Bamboo/Sawali/Cogon/Nipa	2	937	1	11	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	16	5	-	-
Others/Not Reported	-	47	-	19	7
No Walls	-	-	-	-	-

DINAPIGUE

Total	23	286	10	12	3
Concrete/Brick/Stone	-	1	-	-	1
Wood	23	260	6	11	-
Half Concrete/Brick/Stone and Half Wood	-	2	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	16	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	4	-	-
Others/Not Reported	-	4	-	1	1
No Walls	-	-	-	-	-

DIVILICAN

Total	26	436	-	4	1
Concrete/Brick/Stone	-	-	-	-	-
Wood	25	291	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	2	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	117	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	-	1	-
Others/Not Reported	1	18	-	3	1
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ECHAGUE					
Total	73	1,481	22	2	21
Concrete/Brick/Stone	-	10	1	-	3
Wood	18	133	-	-	-
Half Concrete/Brick/Stone and Half Wood	16	29	9	-	2
Galvanized Iron/Aluminum	8	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	30	1,292	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	1	-
Makeshift/Salvaged/Improvised Materials	1	8	11	-	-
Others/Not Reported	-	2	-	1	15
No Walls	-	-	-	-	-
GAMU					
Total	5	561	-	2	18
Concrete/Brick/Stone	-	10	-	1	1
Wood	-	12	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	12	-	-	-
Galvanized Iron/Aluminum	1	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	516	-	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	-	-	-
Others/Not Reported	-	3	-	-	15
No Walls	-	-	-	-	-
ILAGAN (Capital)					
Total	98	1,879	21	11	76
Concrete/Brick/Stone	9	20	1	1	14
Wood	39	129	3	-	8
Half Concrete/Brick/Stone and Half Wood	8	30	4	3	9
Galvanized Iron/Aluminum	3	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	37	1,674	7	4	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	14	5	-	-
Others/Not Reported	2	5	1	3	41
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
JONES					
Total	18	362	4	6	12
Concrete/Brick/Stone	-	-	-	1	1
Wood	6	35	1	-	-
Half Concrete/Brick/Stone and Half Wood	4	5	-	1	-
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	315	2	3	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	1	1	-
Others/Not Reported	-	-	-	-	11
No Walls	-	-	-	-	-
LUNA					
Total	4	79	-	-	9
Concrete/Brick/Stone	-	4	-	-	-
Wood	-	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	1	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	71	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	9
No Walls	-	-	-	-	-
MACONACON					
Total	2	113	-	1	2
Concrete/Brick/Stone	-	-	-	1	-
Wood	2	106	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	1	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	-	-	-
Others/Not Reported	-	1	-	-	2
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

DELFIN ALBANO (MAGSAYSAY)

Total	3	793	1	4	11
Concrete/Brick/Stone	1	40	-	1	2
Wood	1	32	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	26	-	2	1
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	689	-	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	2	-	-	6
No Walls	-	-	-	-	-

MALLIG

Total	22	1,658	-	18	8
Concrete/Brick/Stone	3	82	-	5	1
Wood	-	54	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	97	-	-	2
Galvanized Iron/Aluminum	1	32	-	-	-
Bamboo/Sawali/Cogon/Nipa	18	1,380	-	8	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	-	-	-
Others/Not Reported	-	9	-	4	4
No Walls	-	-	-	-	-

NAGUILIAN

Total	80	662	1	13	9
Concrete/Brick/Stone	-	2	-	1	-
Wood	33	13	-	-	-
Half Concrete/Brick/Stone and Half Wood	3	4	-	1	1
Galvanized Iron/Aluminum	13	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	31	638	-	10	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	1	-	-
Others/Not Reported	-	-	-	1	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PALANAN					
Total	41	845	13	-	8
Concrete/Brick/Stone	-	-	-	-	-
Wood	36	535	5	-	1
Half Concrete/Brick/Stone and Half Wood	-	2	-	-	-
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	301	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	8	-	-
Others/Not Reported	-	2	-	-	7
No Walls	-	-	-	-	-
QUEZON					
Total	8	1,708	-	5	9
Concrete/Brick/Stone	2	54	-	5	-
Wood	-	181	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	32	-	-	-
Galvanized Iron/Aluminum	-	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	1,418	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	-	-	-
Others/Not Reported	-	10	-	-	8
No Walls	-	-	-	-	-
QUIRINO					
Total	43	951	3	-	4
Concrete/Brick/Stone	20	51	-	-	-
Wood	10	28	-	-	-
Half Concrete/Brick/Stone and Half Wood	9	45	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	817	2	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	1	-	-
Others/Not Reported	-	1	-	-	4
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
RAMON					
Total	12	1,054	7	2	12
Concrete/Brick/Stone	-	6	-	-	-
Wood	1	63	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	20	-	-	-
Galvanized Iron/Aluminum	2	10	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	944	1	1	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	10	6	-	-
Others/Not Reported	-	1	-	1	8
No Walls	-	-	-	-	-
REINA MERCEDES					
Total	-	133	2	1	12
Concrete/Brick/Stone	-	-	-	-	4
Wood	-	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	3	-	1	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	127	2	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	-	8
No Walls	-	-	-	-	-
ROXAS					
Total	8	1,273	10	7	14
Concrete/Brick/Stone	-	18	-	1	2
Wood	1	36	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	30	1	-	1
Galvanized Iron/Aluminum	1	7	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	1,171	2	3	3
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	9	7	1	-
Others/Not Reported	-	2	-	-	8
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAN AGUSTIN					
Total	23	130	-	2	7
Concrete/Brick/Stone	-	-	-	1	1
Wood	3	27	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	-	-	1	1
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	17	103	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	4
No Walls	-	-	-	-	-
SAN GUILLERMO					
Total	5	228	1	12	16
Concrete/Brick/Stone	-	-	-	-	-
Wood	1	55	-	2	1
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	172	1	10	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	12
No Walls	-	-	-	-	-
SAN ISIDRO					
Total	3	387	3	-	10
Concrete/Brick/Stone	-	8	-	-	-
Wood	1	27	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	16	1	-	-
Galvanized Iron/Aluminum	-	8	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	320	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	2	-	-
Others/Not Reported	-	-	-	-	9
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

SAN MANUEL

Total	140	893	2	1	21
Concrete/Brick/Stone	-	13	-	-	-
Wood	122	40	-	-	2
Half Concrete/Brick/Stone and Half Wood	1	27	-	1	1
Galvanized Iron/Aluminum	9	8	-	-	1
Bamboo/Sawali/Cogon/Nipa	7	792	-	-	-
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	9	2	-	-
Others/Not Reported	-	4	-	-	17
No Walls	-	-	-	-	-

SAN MARIANO

Total	461	1,437	11	32	8
Concrete/Brick/Stone	-	2	-	-	-
Wood	36	270	1	4	1
Half Concrete/Brick/Stone and Half Wood	2	5	-	-	-
Galvanized Iron/Aluminum	2	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	417	1,142	10	27	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-	-
Others/Not Reported	3	15	-	1	6
No Walls	-	1	-	-	-

SAN MATEO

Total	15	550	5	1	15
Concrete/Brick/Stone	1	9	-	-	2
Wood	5	25	-	-	1
Half Concrete/Brick/Stone and Half Wood	1	14	-	1	-
Galvanized Iron/Aluminum	6	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	497	1	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	2	4	-	-
Others/Not Reported	-	1	-	-	9
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAN PABLO					
Total	57	255	-	-	15
Concrete/Brick/Stone	-	1	-	-	1
Wood	33	8	-	-	-
Half Concrete/Brick/Stone and Half Wood	2	1	-	-	2
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	22	242	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	12
No Walls	-	-	-	-	-
SANTA MARIA					
Total	6	1,195	3	17	4
Concrete/Brick/Stone	-	21	-	-	-
Wood	-	26	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	53	-	-	2
Galvanized Iron/Aluminum	1	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	5	1,089	-	13	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	1	-
Others/Not Reported	-	4	-	2	2
No Walls	-	-	-	-	-
CITY OF SANTIAGO					
Total	34	1,026	35	11	45
Concrete/Brick/Stone	5	17	2	1	4
Wood	9	84	2	3	3
Half Concrete/Brick/Stone and Half Wood	4	16	-	1	2
Galvanized Iron/Aluminum	2	21	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	862	5	4	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	22	26	-	1
Others/Not Reported	-	4	-	2	35
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

SANTO TOMAS

Total	16	283	-	-	14
Concrete/Brick/Stone	-	3	-	-	2
Wood	12	4	-	-	6
Half Concrete/Brick/Stone and Half Wood	2	5	-	-	-
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	270	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	6
No Walls	-	-	-	-	-

TUMAUNI

Total	32	1,470	2	2	37
Concrete/Brick/Stone	1	7	-	1	4
Wood	9	48	-	-	-
Half Concrete/Brick/Stone and Half Wood	6	23	-	-	2
Galvanized Iron/Aluminum	2	3	-	-	2
Bamboo/Sawali/Cogon/Nipa	12	1,379	1	-	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	1	-	-
Others/Not Reported	2	4	-	1	24
No Walls	-	-	-	-	-