Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

		Construction Materials of the Roof				
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete		
KALINGA						
Total	34,645	30,112	477	311		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	10,114 10,823 5,008 1,820 6,510 3 1 91 275	9,478 10,066 4,882 1,663 3,779 3 1 69 171	449 11 12 2 - - - 3	125 28 75 52 31 - - -		
BALBALAN						
Total	2,076	1,952	1	5		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	144 1,449 246 23 206 - - 2 6	142 1,420 243 23 121 - - 1 2	- 1 - - - - - -	1 1 3 - - - - -		
LUBUAGAN						
Total	1,867	1,824	24	8		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	146 1,159 321 71 163 - - 3 4	123 1,152 316 69 157 - - 3 4	20 1 3 - - - - -	3 2 2 1 - - -		

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

		Construction Materials of the Roof				
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete		
PASIL						
Total	1,678	1,637	6	8		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported	73 924 367 70 231 - - 13	61 916 364 70 213 - - 13	6	5 - 3 - - - - -		
No Walls	-	-	-	-		
PINUKPUK						
Total	5,122	4,547	8	8		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	606 1,944 678 91 1,726 - - 5 72	598 1,894 672 85 1,233 - - 4 61	7 1 - - - - - -	1 3 3 1 - - - -		
RIZAL (LIWAN)						
Total	3,075	2,159	42	15		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1,214 428 284 153 963 1 - 11 21	1,140 257 277 119 353 1 - 5 7	41 - - - - - 1	5 1 2 1 6 - -		

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

		Construction Materials of the Roof				
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Tile Iron/ Concrete/ Aluminum Clay Tile		Half Galvanized Iron and Half Concrete		
TABUK (Capital)						
Total	17,164	14,681	375	238		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	7,783 2,658 2,459 1,169 2,872 1 - 57 165	7,294 2,357 2,371 1,054 1,468 1 - 43 93	362 5 5 2 - - 1	95 20 54 49 20 - -		
TANUDAN						
Total	1,453	1,343	3	2		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	15 1,008 130 10 285 - - - 5	14 977 128 10 211 - - 3	1 1 1 - - - -	- 1 - 1 - - -		
TINGLAYAN						
Total	2,210	1,969	18	27		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	133 1,253 523 233 64 1 1 -	106 1,093 511 233 23 1 1 -	12 2 3 - - - - 1	15 1 7 - 4 - - -		

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

	Construction Materials of the Roof				
Construction Materials of the Outer Walls and City/Municipality	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
KALINGA					
Total	371	3,124	29	108	113
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1 117 1 11 235 - - 2 4	30 585 30 91 2,361 - - 15 12	11 - 5 - 9 - - 4 -	9 12 1 - 86 - - -	11 4 2 1 9 - 1 85
BALBALAN					
Total	56	39	1	18	4
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	- 13 - - 43 - - -	9 - 29 - 1 -	- - - 1 - - -	1 5 - 12 - - -	- - - - - - 4
LUBUAGAN					
Total	2	8	-	-	1
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	- 1 - 1 - - - -	- 2 - - 6 - - -	- - - - - - -	- - - - - - -	- 1 - - - - - -

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

	Construction Materials of the Roof				
Construction Materials of the Outer Walls and City/Municipality	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PASIL					
Total	2	23	1	1	-
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported	- 1 - - 1 - -	- 7 - - 16 - -	1 - - - - - -	- - - 1 - -	- - - - - -
No Walls PINUKPUK	-	-	-	-	-
Total	127	340	2	77	13
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	- 4 - 1 122 - - - -	34 1 4 298 - - - 3	- - - 1 - - 1	- 6 1 - 70 - - - -	2 1 - 2 - - - 8
RIZAL (LIWAN)					
Total	4	836	1	5	13
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	- - 1 2 - - 1	23 169 5 32 598 - - 4 5	- - - - - 1 -	3 1 - - 1 - - -	2 - - 3 - - 8

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

	Construction Materials of the Roof				
Construction Materials of the Outer Walls and City/Municipality	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
TABUK (Capital)					
Total	174	1,586	24	6	80
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1 93 1 8 66 - 1 4	7 182 22 55 1,307 - 10 3	10 - 5 - 7 - - 2 -	5 - - 1 - - -	9 1 1 3 - - 1 64
TANUDAN					
Total	2	100	-	1	2
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	- 1 - - 1 - - -	- 29 - - 70 - - - 1	- - - - - - -	- - - 1 - - -	- - - 1 - - - 1
TINGLAYAN					
Total	4	192	-	-	-
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	- 4 - - - - - -	153 2 - 37 - - -	- - - - - - -	- - - - - - -	- - - - - - - -