

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
LANAO DEL SUR				
Total	132,805	111,509	3,075	4,456
Concrete/Brick/Stone	21,718	17,746	2,200	999
Wood	74,899	65,822	403	845
Half Concrete/Brick/Stone and Half Wood	24,678	20,903	372	2,413
Galvanized Iron/Aluminum	1,501	1,187	80	143
Bamboo/Sawali/Cogon/Nipa	8,255	5,490	-	24
Asbestos	41	17	1	1
Glass	23	9	8	5
Makeshift/Salvaged/Improvised Materials	136	44	-	2
Others/Not Reported	1,554	291	11	24
No Walls	-	-	-	-
BACOLOD-KALAWI (BACOLOD GRANDE)				
Total	2,522	2,325	65	43
Concrete/Brick/Stone	552	456	58	36
Wood	1,080	1,055	3	1
Half Concrete/Brick/Stone and Half Wood	404	392	4	4
Galvanized Iron/Aluminum	10	10	-	-
Bamboo/Sawali/Cogon/Nipa	440	406	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	36	6	-	-
No Walls	-	-	-	-
BALABAGAN				
Total	5,533	2,647	29	67
Concrete/Brick/Stone	782	479	23	6
Wood	3,321	1,648	5	45
Half Concrete/Brick/Stone and Half Wood	819	442	1	12
Galvanized Iron/Aluminum	4	2	-	1
Bamboo/Sawali/Cogon/Nipa	558	70	-	3
Asbestos	10	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	38	5	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BALINDONG (WATU)				
Total	3,274	2,428	274	140
Concrete/Brick/Stone	1,050	732	270	7
Wood	1,251	964	2	1
Half Concrete/Brick/Stone and Half Wood	471	315	1	130
Galvanized Iron/Aluminum	21	19	-	2
Bamboo/Sawali/Cogon/Nipa	417	382	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	64	16	1	-
No Walls	-	-	-	-
BAYANG				
Total	1,699	1,544	12	29
Concrete/Brick/Stone	318	306	12	-
Wood	759	707	-	-
Half Concrete/Brick/Stone and Half Wood	444	416	-	28
Galvanized Iron/Aluminum	21	21	-	-
Bamboo/Sawali/Cogon/Nipa	118	79	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	-	-	1
Others/Not Reported	30	15	-	-
No Walls	-	-	-	-
BINIDAYAN				
Total	1,891	1,770	67	11
Concrete/Brick/Stone	248	211	34	2
Wood	955	930	7	1
Half Concrete/Brick/Stone and Half Wood	378	345	24	8
Galvanized Iron/Aluminum	11	9	2	-
Bamboo/Sawali/Cogon/Nipa	291	272	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	8	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
BUBONG				
Total	1,816	1,729	24	13
Concrete/Brick/Stone	268	245	19	3
Wood	1,212	1,203	3	1
Half Concrete/Brick/Stone and Half Wood	271	261	1	8
Galvanized Iron/Aluminum	8	7	-	1
Bamboo/Sawali/Cogon/Nipa	10	6	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	47	7	1	-
No Walls	-	-	-	-
BUTIG				
Total	2,723	2,400	96	17
Concrete/Brick/Stone	354	266	81	6
Wood	1,531	1,504	8	4
Half Concrete/Brick/Stone and Half Wood	565	553	5	6
Galvanized Iron/Aluminum	19	17	1	1
Bamboo/Sawali/Cogon/Nipa	54	54	-	-
Asbestos	3	2	1	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	195	2	-	-
No Walls	-	-	-	-
GANASSI				
Total	2,125	2,010	55	11
Concrete/Brick/Stone	354	300	52	2
Wood	1,028	1,019	3	6
Half Concrete/Brick/Stone and Half Wood	452	449	-	3
Galvanized Iron/Aluminum	3	2	-	-
Bamboo/Sawali/Cogon/Nipa	278	236	-	-
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	7	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
KAPAI				
Total	2,513	2,444	15	30
Concrete/Brick/Stone	49	30	8	9
Wood	2,151	2,136	5	1
Half Concrete/Brick/Stone and Half Wood	230	210	1	19
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	66	63	-	1
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	16	4	1	-
No Walls	-	-	-	-
LUMBA-BAYABAO (MAGUING)				
Total	5,648	4,439	258	551
Concrete/Brick/Stone	1,470	1,033	141	277
Wood	1,960	1,790	8	11
Half Concrete/Brick/Stone and Half Wood	1,426	1,132	55	235
Galvanized Iron/Aluminum	156	77	49	20
Bamboo/Sawali/Cogon/Nipa	488	393	-	-
Asbestos	1	1	-	-
Glass	10	1	5	4
Makeshift/Salvaged/Improvised Materials	18	-	-	-
Others/Not Reported	119	12	-	4
No Walls	-	-	-	-
LUMBATAN				
Total	2,652	2,497	60	30
Concrete/Brick/Stone	186	167	9	10
Wood	1,320	1,311	6	2
Half Concrete/Brick/Stone and Half Wood	714	651	45	18
Galvanized Iron/Aluminum	3	3	-	-
Bamboo/Sawali/Cogon/Nipa	362	361	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	67	4	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MADALUM				
Total	3,748	3,707	19	4
Concrete/Brick/Stone	327	312	11	4
Wood	2,511	2,505	4	-
Half Concrete/Brick/Stone and Half Wood	461	457	4	-
Galvanized Iron/Aluminum	14	14	-	-
Bamboo/Sawali/Cogon/Nipa	425	419	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	10	-	-	-
No Walls	-	-	-	-
MADAMBA				
Total	2,541	2,258	20	59
Concrete/Brick/Stone	168	149	10	7
Wood	1,699	1,603	9	20
Half Concrete/Brick/Stone and Half Wood	166	143	1	11
Galvanized Iron/Aluminum	40	11	-	15
Bamboo/Sawali/Cogon/Nipa	446	341	-	6
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	8	7	-	-
Others/Not Reported	13	3	-	-
No Walls	-	-	-	-
MALABANG				
Total	6,095	3,303	151	313
Concrete/Brick/Stone	561	198	126	40
Wood	4,316	2,521	10	100
Half Concrete/Brick/Stone and Half Wood	958	562	9	158
Galvanized Iron/Aluminum	38	11	6	12
Bamboo/Sawali/Cogon/Nipa	171	6	-	2
Asbestos	9	1	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	22	-	-	1
Others/Not Reported	19	4	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
MARANTAO				
Total	3,499	3,105	74	109
Concrete/Brick/Stone	886	807	63	13
Wood	1,295	1,139	1	1
Half Concrete/Brick/Stone and Half Wood	1,080	973	9	93
Galvanized Iron/Aluminum	61	58	-	2
Bamboo/Sawali/Cogon/Nipa	150	118	-	-
Asbestos	-	-	-	-
Glass	1	-	1	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	26	10	-	-
No Walls	-	-	-	-
MARAWI CITY (Capital)				
Total	22,092	19,540	777	890
Concrete/Brick/Stone	5,451	4,377	617	317
Wood	10,335	9,877	53	71
Half Concrete/Brick/Stone and Half Wood	5,552	4,821	90	452
Galvanized Iron/Aluminum	245	155	14	43
Bamboo/Sawali/Cogon/Nipa	297	229	-	1
Asbestos	3	2	-	1
Glass	5	4	1	-
Makeshift/Salvaged/Improvised Materials	29	3	-	-
Others/Not Reported	175	72	2	5
No Walls	-	-	-	-
MASIU				
Total	3,079	2,902	51	46
Concrete/Brick/Stone	1,060	946	43	27
Wood	1,238	1,218	5	2
Half Concrete/Brick/Stone and Half Wood	550	519	3	16
Galvanized Iron/Aluminum	4	2	-	1
Bamboo/Sawali/Cogon/Nipa	216	215	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	11	2	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MULONDO				
Total	1,259	1,003	5	208
Concrete/Brick/Stone	137	131	4	1
Wood	602	582	1	5
Half Concrete/Brick/Stone and Half Wood	504	285	-	199
Galvanized Iron/Aluminum	3	1	-	2
Bamboo/Sawali/Cogon/Nipa	2	2	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	11	2	-	1
No Walls	-	-	-	-
PAGAYAWAN (TATARIKAN)				
Total	1,936	1,906	11	2
Concrete/Brick/Stone	226	224	1	-
Wood	948	940	6	-
Half Concrete/Brick/Stone and Half Wood	509	503	4	2
Galvanized Iron/Aluminum	2	2	-	-
Bamboo/Sawali/Cogon/Nipa	235	224	-	-
Asbestos	1	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	14	12	-	-
No Walls	-	-	-	-
PIAGAPO				
Total	4,635	4,498	26	35
Concrete/Brick/Stone	677	652	16	7
Wood	3,319	3,268	8	-
Half Concrete/Brick/Stone and Half Wood	315	290	1	24
Galvanized Iron/Aluminum	15	11	-	4
Bamboo/Sawali/Cogon/Nipa	289	275	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	20	2	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
POONA BAYABAO (GATA)				
Total	1,945	1,900	36	7
Concrete/Brick/Stone	337	299	33	4
Wood	1,280	1,277	2	1
Half Concrete/Brick/Stone and Half Wood	184	180	1	2
Galvanized Iron/Aluminum	3	3	-	-
Bamboo/Sawali/Cogon/Nipa	141	141	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	-	-	-	-
No Walls	-	-	-	-
PUALAS				
Total	2,882	2,818	5	6
Concrete/Brick/Stone	234	229	1	4
Wood	1,981	1,970	2	1
Half Concrete/Brick/Stone and Half Wood	522	518	2	1
Galvanized Iron/Aluminum	3	3	-	-
Bamboo/Sawali/Cogon/Nipa	97	90	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	45	8	-	-
No Walls	-	-	-	-
DITSAAN-RAMAIN				
Total	2,502	2,381	31	5
Concrete/Brick/Stone	422	393	23	4
Wood	1,603	1,582	7	-
Half Concrete/Brick/Stone and Half Wood	380	372	1	1
Galvanized Iron/Aluminum	4	4	-	-
Bamboo/Sawali/Cogon/Nipa	34	23	-	-
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	58	7	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
SAGUIARAN				
Total	3,119	2,770	55	24
Concrete/Brick/Stone	652	604	43	5
Wood	1,955	1,721	10	6
Half Concrete/Brick/Stone and Half Wood	351	320	2	13
Galvanized Iron/Aluminum	2	2	-	-
Bamboo/Sawali/Cogon/Nipa	147	121	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	12	2	-	-
No Walls	-	-	-	-
TAMPARAN				
Total	2,237	2,029	73	33
Concrete/Brick/Stone	542	496	35	11
Wood	1,306	1,257	32	8
Half Concrete/Brick/Stone and Half Wood	207	186	5	12
Galvanized Iron/Aluminum	8	6	1	-
Bamboo/Sawali/Cogon/Nipa	85	81	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	89	3	-	1
No Walls	-	-	-	-
TARAKA				
Total	2,246	1,855	193	111
Concrete/Brick/Stone	523	374	127	17
Wood	1,195	1,102	44	6
Half Concrete/Brick/Stone and Half Wood	336	229	21	85
Galvanized Iron/Aluminum	48	46	1	1
Bamboo/Sawali/Cogon/Nipa	101	90	-	1
Asbestos	-	-	-	-
Glass	1	-	-	1
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	42	14	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
TUBARAN				
Total	1,688	1,481	16	52
Concrete/Brick/Stone	131	120	7	4
Wood	452	353	3	3
Half Concrete/Brick/Stone and Half Wood	982	906	3	44
Galvanized Iron/Aluminum	71	62	3	1
Bamboo/Sawali/Cogon/Nipa	33	32	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	6	-	-
Others/Not Reported	13	2	-	-
No Walls	-	-	-	-
TUGAYA				
Total	2,522	2,265	119	100
Concrete/Brick/Stone	736	629	101	5
Wood	1,282	1,250	12	5
Half Concrete/Brick/Stone and Half Wood	356	257	5	90
Galvanized Iron/Aluminum	8	7	1	-
Bamboo/Sawali/Cogon/Nipa	120	119	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	20	3	-	-
No Walls	-	-	-	-
WAO				
Total	8,369	7,419	21	155
Concrete/Brick/Stone	632	615	7	4
Wood	6,287	5,544	10	97
Half Concrete/Brick/Stone and Half Wood	950	887	3	52
Galvanized Iron/Aluminum	15	10	1	1
Bamboo/Sawali/Cogon/Nipa	355	306	-	-
Asbestos	3	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	31	25	-	-
Others/Not Reported	96	30	-	1
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MAROGONG				
Total	2,237	2,138	7	8
Concrete/Brick/Stone	205	197	2	5
Wood	1,813	1,752	2	1
Half Concrete/Brick/Stone and Half Wood	147	143	3	1
Galvanized Iron/Aluminum	3	2	-	1
Bamboo/Sawali/Cogon/Nipa	37	34	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	32	10	-	-
No Walls	-	-	-	-
CALANOGAS				
Total	2,506	2,144	20	7
Concrete/Brick/Stone	123	121	-	2
Wood	1,911	1,741	17	4
Half Concrete/Brick/Stone and Half Wood	179	176	1	1
Galvanized Iron/Aluminum	4	3	1	-
Bamboo/Sawali/Cogon/Nipa	277	99	-	-
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	2	-	-
Others/Not Reported	9	1	1	-
No Walls	-	-	-	-
BUADIPOSO-BUNTONG				
Total	2,089	1,704	72	115
Concrete/Brick/Stone	324	252	67	5
Wood	1,393	1,280	4	32
Half Concrete/Brick/Stone and Half Wood	214	150	-	63
Galvanized Iron/Aluminum	20	3	-	14
Bamboo/Sawali/Cogon/Nipa	123	13	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	15	6	1	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MAGUING				
Total	3,114	2,524	218	310
Concrete/Brick/Stone	947	696	127	121
Wood	1,610	1,471	69	48
Half Concrete/Brick/Stone and Half Wood	459	310	22	125
Galvanized Iron/Aluminum	46	36	-	7
Bamboo/Sawali/Cogon/Nipa	17	11	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	34	-	-	9
No Walls	-	-	-	-
PICONG (SULTAN GUMANDER)				
Total	2,352	1,833	1	13
Concrete/Brick/Stone	154	151	-	1
Wood	1,495	1,298	1	2
Half Concrete/Brick/Stone and Half Wood	376	364	-	9
Galvanized Iron/Aluminum	1	-	-	1
Bamboo/Sawali/Cogon/Nipa	317	16	-	-
Asbestos	3	3	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	4	-	-	-
No Walls	-	-	-	-
LUMBAYANAGUE				
Total	2,520	1,977	77	353
Concrete/Brick/Stone	242	202	21	14
Wood	424	330	12	64
Half Concrete/Brick/Stone and Half Wood	1,707	1,389	41	268
Galvanized Iron/Aluminum	17	13	-	4
Bamboo/Sawali/Cogon/Nipa	31	26	-	-
Asbestos	-	-	-	-
Glass	1	-	1	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	98	17	2	3
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete
BUMBARAN				
Total	2,358	1,278	1	31
Concrete/Brick/Stone	23	20	-	-
Wood	1,285	681	1	-
Half Concrete/Brick/Stone and Half Wood	70	40	-	29
Galvanized Iron/Aluminum	527	522	-	2
Bamboo/Sawali/Cogon/Nipa	431	14	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	6	-	-	-
Others/Not Reported	16	1	-	-
No Walls	-	-	-	-
TAGOLOAN II				
Total	1,330	981	14	39
Concrete/Brick/Stone	4	3	1	-
Wood	1,041	958	12	14
Half Concrete/Brick/Stone and Half Wood	43	14	-	21
Galvanized Iron/Aluminum	4	-	-	2
Bamboo/Sawali/Cogon/Nipa	234	5	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	4	1	1	-
No Walls	-	-	-	-
KAPATAGAN				
Total	3,366	1,662	16	306
Concrete/Brick/Stone	106	86	3	7
Wood	2,669	1,299	12	277
Half Concrete/Brick/Stone and Half Wood	207	177	1	13
Galvanized Iron/Aluminum	9	3	-	5
Bamboo/Sawali/Cogon/Nipa	334	94	-	4
Asbestos	2	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	38	3	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SULTAN DUMALONDONG

Total	957	906	9	31
Concrete/Brick/Stone	204	197	3	4
Wood	441	426	3	3
Half Concrete/Brick/Stone and Half Wood	305	277	3	24
Galvanized Iron/Aluminum	2	2	-	-
Bamboo/Sawali/Cogon/Nipa	4	3	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	1	1	-	-
No Walls	-	-	-	-

LUMBACA UNAYAN

Total	1,186	989	2	142
Concrete/Brick/Stone	53	41	1	8
Wood	645	610	1	1
Half Concrete/Brick/Stone and Half Wood	434	289	-	133
Galvanized Iron/Aluminum	28	28	-	-
Bamboo/Sawali/Cogon/Nipa	24	21	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	2	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LANAO DEL SUR					
Total	3,212	4,096	137	4,506	1,814
Concrete/Brick/Stone	74	44	7	553	95
Wood	2,577	1,729	44	3,269	210
Half Concrete/Brick/Stone and Half Wood	182	115	7	604	82
Galvanized Iron/Aluminum	59	23	1	6	2
Bamboo/Sawali/Cogon/Nipa	271	2,168	22	48	232
Asbestos	3	-	-	18	1
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	5	-	55	1	29
Others/Not Reported	41	17	1	7	1,162
No Walls	-	-	-	-	-
BACOLOD-KALAWI (BACOLOD GRANDE)					
Total	18	30	-	1	40
Concrete/Brick/Stone	-	-	-	-	2
Wood	16	4	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	4
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	26	-	1	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	30
No Walls	-	-	-	-	-
BALABAGAN					
Total	49	848	3	1,732	158
Concrete/Brick/Stone	4	1	-	268	1
Wood	40	466	1	1,109	7
Half Concrete/Brick/Stone and Half Wood	2	16	2	343	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	361	-	-	122
Asbestos	-	-	-	9	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-	-
Others/Not Reported	-	3	-	3	27
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BALINDONG (WATU)					
Total	344	2	-	5	81
Concrete/Brick/Stone	24	1	-	5	11
Wood	262	1	-	-	21
Half Concrete/Brick/Stone and Half Wood	24	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	13	-	-	-	22
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	21	-	-	-	26
No Walls	-	-	-	-	-
BAYANG					
Total	52	40	8	-	14
Concrete/Brick/Stone	-	-	-	-	-
Wood	50	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	38	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	7	-	-
Others/Not Reported	1	-	-	-	14
No Walls	-	-	-	-	-
BINIDAYAN					
Total	16	16	-	4	7
Concrete/Brick/Stone	-	-	-	1	-
Wood	14	2	-	-	1
Half Concrete/Brick/Stone and Half Wood	1	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	14	-	3	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	-	-	-	4
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BUBONG					
Total	4	4	-	1	41
Concrete/Brick/Stone	-	-	-	1	-
Wood	2	-	-	-	3
Half Concrete/Brick/Stone and Half Wood	1	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	4	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	-	-	-	38
No Walls	-	-	-	-	-
BUTIG					
Total	10	1	-	-	199
Concrete/Brick/Stone	1	-	-	-	-
Wood	9	1	-	-	5
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	-	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	193
No Walls	-	-	-	-	-
GANASSI					
Total	41	2	-	-	6
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	40	2	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
KAPAI					
Total	8	4	-	-	12
Concrete/Brick/Stone	2	-	-	-	-
Wood	5	3	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	1	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	11
No Walls	-	-	-	-	-
LUMBA-BAYABAO (MAGUING)					
Total	128	116	23	1	132
Concrete/Brick/Stone	6	-	4	-	9
Wood	110	24	-	1	16
Half Concrete/Brick/Stone and Half Wood	1	-	-	-	3
Galvanized Iron/Aluminum	7	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	89	1	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	18	-	-
Others/Not Reported	-	-	-	-	103
No Walls	-	-	-	-	-
LUMBATAN					
Total	1	1	-	-	63
Concrete/Brick/Stone	-	-	-	-	-
Wood	1	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	1	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	63
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MADALUM					
Total	-	6	-	-	12
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	-	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	6	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	10
No Walls	-	-	-	-	-
MADAMBA					
Total	90	73	2	28	11
Concrete/Brick/Stone	-	2	-	-	-
Wood	40	21	1	4	1
Half Concrete/Brick/Stone and Half Wood	10	1	-	-	-
Galvanized Iron/Aluminum	4	10	-	-	-
Bamboo/Sawali/Cogon/Nipa	36	39	-	23	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	-	-	1	9
No Walls	-	-	-	-	-
MALABANG					
Total	101	740	64	1,348	75
Concrete/Brick/Stone	3	3	-	185	6
Wood	69	513	29	1,048	26
Half Concrete/Brick/Stone and Half Wood	17	92	3	105	12
Galvanized Iron/Aluminum	3	1	1	2	2
Bamboo/Sawali/Cogon/Nipa	6	130	13	-	14
Asbestos	2	-	-	6	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	1	-	18	-	2
Others/Not Reported	-	1	-	2	12
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MARANTAO					
Total	174	16	1	2	18
Concrete/Brick/Stone	2	-	-	1	-
Wood	151	-	-	-	3
Half Concrete/Brick/Stone and Half Wood	3	1	-	1	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	17	15	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	1	-	15
No Walls	-	-	-	-	-
MARAWI CITY (Capital)					
Total	163	135	-	348	239
Concrete/Brick/Stone	14	34	-	41	51
Wood	85	40	-	172	37
Half Concrete/Brick/Stone and Half Wood	22	1	-	134	32
Galvanized Iron/Aluminum	29	3	-	1	-
Bamboo/Sawali/Cogon/Nipa	5	55	-	-	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	26
Others/Not Reported	8	2	-	-	86
No Walls	-	-	-	-	-
MASIU					
Total	12	1	11	46	10
Concrete/Brick/Stone	-	-	2	41	1
Wood	5	-	8	-	-
Half Concrete/Brick/Stone and Half Wood	7	-	1	4	-
Galvanized Iron/Aluminum	-	-	-	1	-
Bamboo/Sawali/Cogon/Nipa	-	1	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	9
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MULONDO					
Total	30	-	-	-	13
Concrete/Brick/Stone	-	-	-	-	1
Wood	10	-	-	-	4
Half Concrete/Brick/Stone and Half Wood	20	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	-	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	8
No Walls	-	-	-	-	-
PAGAYAWAN (TATARIKAN)					
Total	-	9	-	1	7
Concrete/Brick/Stone	-	-	-	-	1
Wood	-	-	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	9	-	-	2
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-
PIAGAPO					
Total	41	12	-	-	23
Concrete/Brick/Stone	-	-	-	-	2
Wood	40	-	-	-	3
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	12	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	17
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
POONA BAYABAO (GATA)					
Total	-	-	-	1	1
Concrete/Brick/Stone	-	-	-	-	1
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	1	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	-	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-
PUALAS					
Total	4	2	-	1	46
Concrete/Brick/Stone	-	-	-	-	-
Wood	4	-	-	-	4
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	2	-	1	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	37
No Walls	-	-	-	-	-
DITSAAN-RAMAIN					
Total	13	11	-	-	61
Concrete/Brick/Stone	-	-	-	-	2
Wood	10	-	-	-	4
Half Concrete/Brick/Stone and Half Wood	2	-	-	-	4
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	11	-	-	-
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	51
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SAGUIARAN					
Total	239	16	-	-	15
Concrete/Brick/Stone	-	-	-	-	-
Wood	208	6	-	-	4
Half Concrete/Brick/Stone and Half Wood	15	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	10	-	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	2	-	-	-	8
No Walls	-	-	-	-	-
TAMPARAN					
Total	6	3	-	1	92
Concrete/Brick/Stone	-	-	-	-	-
Wood	6	-	-	1	2
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	4
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	2	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	85
No Walls	-	-	-	-	-
TARAKA					
Total	49	8	2	-	28
Concrete/Brick/Stone	5	-	-	-	-
Wood	41	-	2	-	-
Half Concrete/Brick/Stone and Half Wood	1	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	8	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	28
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
TUBARAN					
Total	119	1	-	-	19
Concrete/Brick/Stone	-	-	-	-	-
Wood	86	-	-	-	7
Half Concrete/Brick/Stone and Half Wood	27	-	-	-	2
Galvanized Iron/Aluminum	5	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	1	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	-	-	-	10
No Walls	-	-	-	-	-
TUGAYA					
Total	14	2	-	-	22
Concrete/Brick/Stone	-	-	-	-	1
Wood	14	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	4
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	1	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	17
No Walls	-	-	-	-	-
WAO					
Total	536	136	11	3	88
Concrete/Brick/Stone	6	-	-	-	-
Wood	509	91	3	3	30
Half Concrete/Brick/Stone and Half Wood	5	-	-	-	3
Galvanized Iron/Aluminum	1	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	37	4	-	-
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	4	-	-
Others/Not Reported	5	6	-	-	54
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MAROGONG					
Total	12	47	-	-	25
Concrete/Brick/Stone	1	-	-	-	-
Wood	10	45	-	-	3
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	2	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	22
No Walls	-	-	-	-	-
CALANOGAS					
Total	3	320	-	2	10
Concrete/Brick/Stone	-	-	-	-	-
Wood	2	143	-	2	2
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	176	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	7
No Walls	-	-	-	-	-
BUADIPOSO-BUNTONG					
Total	66	123	-	1	8
Concrete/Brick/Stone	-	-	-	-	-
Wood	61	13	-	1	2
Half Concrete/Brick/Stone and Half Wood	1	-	-	-	-
Galvanized Iron/Aluminum	2	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	108	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	1	1	-	-	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
MAGUING					
Total	21	12	2	-	27
Concrete/Brick/Stone	1	-	1	-	1
Wood	16	6	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	-	-	-	1
Galvanized Iron/Aluminum	3	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	6	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	-	-	-	25
No Walls	-	-	-	-	-
PICONG (SULTAN GUMANDER)					
Total	22	449	-	28	6
Concrete/Brick/Stone	1	1	-	-	-
Wood	16	152	-	25	1
Half Concrete/Brick/Stone and Half Wood	-	-	-	3	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	296	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	1
Others/Not Reported	-	-	-	-	4
No Walls	-	-	-	-	-
LUMBAYANAGUE					
Total	17	7	1	-	88
Concrete/Brick/Stone	-	-	-	-	5
Wood	15	2	-	-	1
Half Concrete/Brick/Stone and Half Wood	1	1	1	-	6
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	4	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	76
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
BUMBARAN					
Total	607	415	9	2	15
Concrete/Brick/Stone	2	1	-	-	-
Wood	602	1	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	2	-	-	1	-
Bamboo/Sawali/Cogon/Nipa	1	413	3	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	6	-	-
Others/Not Reported	-	-	-	1	14
No Walls	-	-	-	-	-
TAGOLOAN II					
Total	115	178	-	-	3
Concrete/Brick/Stone	-	-	-	-	-
Wood	17	38	-	-	2
Half Concrete/Brick/Stone and Half Wood	8	-	-	-	-
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	89	138	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	1
No Walls	-	-	-	-	-
KAPATAGAN					
Total	32	306	-	950	94
Concrete/Brick/Stone	-	-	-	10	-
Wood	11	154	-	903	13
Half Concrete/Brick/Stone and Half Wood	1	2	-	13	-
Galvanized Iron/Aluminum	-	-	-	1	-
Bamboo/Sawali/Cogon/Nipa	20	147	-	20	49
Asbestos	-	-	-	2	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	1	-
Others/Not Reported	-	3	-	-	32
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SULTAN DUMALONDONG					
Total	8	-	-	-	3
Concrete/Brick/Stone	-	-	-	-	-
Wood	7	-	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	-	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	-
No Walls	-	-	-	-	-
LUMBACA UNAYAN					
Total	47	4	-	-	2
Concrete/Brick/Stone	2	1	-	-	-
Wood	33	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	12	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	3	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-