		Construction Materials of the Roof					
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete			
MOUNTAIN PROVINCE							
Total	30,298	27,709	1,113	263			
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	4,591 7,239 3,721 12,989 1,308 1 0 15 434 0	3,441 6,812 3,569 12,943 586 1 0 7 350 0	1,052 8 44 6 0 0 0 0 3 3 0	74 62 100 22 1 0 0 0 0 4			
BARLIG							
Total	1,448	1,417	3	2			
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	20 705 96 622 1 0 0 0 4	17 681 95 622 0 0 0 0 2 0	2 1 0 0 0 0 0 0 0 0 0	1 0 1 0 0 0 0 0 0 0 0 0			
BAUKO							
Total	5,666	5,337	52	143			
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1,049 677 711 3,004 5 0 0 1 219 0	969 535 663 2,986 5 0 0 1 178 0	48 0 2 1 0 0 0 1 0	23 57 46 14 0 0 0 0 0 3 0			

	1	Construction Materials of the Roof						
		Construction Materials of the Roof						
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete				
BESAO								
Total	1,640	1,615	2	9				
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	34 463 51 1,022 15 0 0 0 55 0	31 455 48 1,020 8 0 0 0 53 0	2 0 0 0 0 0 0 0 0 0	1 3 2 0 0 0 0 0 0 0 0 0				
BONTOC (Capital)								
Total	5,413	4,430	906	53				
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1,533 505 795 2,532 2 0 0 1 45 0	643 493 729 2,524 1 0 0 0 40 0	867 2 34 3 0 0 0 0 0 0 0	21 0 28 4 0 0 0 0 0 0 0 0				
NATONIN								
Total	1,877	1,767	7	7				
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	24 852 58 882 50 0 0 1 10 0	15 790 55 880 25 0 0 0 0 2 0	6 1 0 0 0 0 0 0 0 0	3 0 3 1 0 0 0 0 0 0 0				

		Construction Materials of the Roof					
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete			
PARACELIS							
Total	4,615	3,778	6	7			
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	652 1,946 536 254 1,198 1 0 6 22 0	646 1,814 531 252 521 1 0 4 9 0	3 1 0 1 0 0 0 1 0	2 1 2 0 1 0 0 0 0 1 0			
SABANGAN							
Total	1,928	1,887	34	2			
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	374 513 454 571 0 0 0 2 14	342 509 451 569 0 0 0 0 2 14 0	31 1 1 0 0 0 0 0 0	1 0 0 0 0 0 0 0 0 0			
SADANGA							
Total	1,825	1,769	28	14			
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	119 510 215 954 6 0 0 4 17 0	89 507 205 951 0 0 0 0 17 0	25 0 3 0 0 0 0 0 0 0 0	5 1 7 1 0 0 0 0 0 0 0 0			

		Construction Materials of the Roo				
Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete		
SAGADA						
Total	2,322	2,307	0	1		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	93 142 298 1,768 2 0 0 0 19 0	90 135 297 1,766 2 0 0 0 17 0	0 0 0 0 0 0 0 0 0 0	0 0 1 0 0 0 0 0 0 0 0		
TADIAN						
Total	3,564	3,402	75	25		
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	693 926 507 1,380 29 0 0 0 29 0 29 0	599 893 495 1,373 24 0 0 0 18 0	68 2 4 0 0 0 0 0 1	17 0 8 0 0 0 0 0 0 0 0		

	Construction Materials of the Roof					
Construction Materials of the Outer Walls and City/Municipality	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported	
MOUNTAIN PROVINCE						
Total	21	1,054	4	35	99	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	2 9 3 1 5 0 0 0 1	0 339 3 6 700 0 0 4 2 0	0 0 0 0 0 0 0 4 0 0	12 8 0 1 14 0 0 0 0 0 0	10 1 2 10 2 0 0 0 74 0	
BARLIG						
Total	0	24	0	0	2	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	0 0 0 0 0 0 0 0 0 0	0 23 0 1 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 2 0	
BAUKO						
Total	2	84	0	6	42	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	0 2 0 0 0 0 0 0 0 0 0	0 83 0 1 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0	6 0 0 0 0 0 0 0 0 0	3 0 2 0 0 0 0 37 0	

	Construction Materials of the Roof					
Construction Materials of the Outer Walls and City/Municipality	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported	
BESAO						
Total	0	12	0	0	2	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	0 0 0 0 0 0 0 0 0 0	0 5 0 7 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 2 0	
BONTOC (Capital)						
Total	10	6	1	0	7	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1 5 3 0 0 0 0 1 0	0 5 0 1 0 0 0 0 0	0 0 0 0 0 0 1 0 0	0 0 0 0 0 0 0 0 0 0	1 0 1 1 0 0 0 0 4 0	
NATONIN						
Total	0	88	0	0	8	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	0 0 0 0 0 0 0 0 0 0	0 61 0 1 25 0 0 1 0 0	0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 8 0	

	Construction Materials of the Roof					
Construction Materials of the Outer Walls and City/Municipality	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported	
PARACELIS						
Total	7	784	0	21	12	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	0 2 0 5 0 0 0 0 0 0	0 121 3 1 655 0 0 2 2 2 0	0 0 0 0 0 0 0 0 0 0 0 0	0 7 0 14 0 0 0 0 0	1 0 0 2 0 0 0 9 0	
SABANGAN						
Total	0	3	0	0	2	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	0 0 0 0 0 0 0 0 0 0 0	0 3 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0	0 0 1 1 0 0 0 0 0 0 0	
SADANGA						
Total	0	8	3	2	1	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	0 0 0 0 0 0 0 0 0 0	0 1 0 6 0 0 1 0 0	0 0 0 0 0 0 0 3 0 0	0 1 0 1 0 0 0 0 0 0 0 0	0 0 1 0 0 0 0 0 0	

	Construction Materials of the Roof					
Construction Materials of the Outer Walls and City/Municipality	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported	
SAGADA	-					
Total	0	7	0	2	5	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	0 0 0 0 0 0 0 0 0	0 7 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0	2 0 0 0 0 0 0 0 0 0 0	1 0 2 0 0 0 0 2 0	
TADIAN						
Total	2	38	0	4	18	
Concrete/Brick/Stone Wood Half Concrete/Brick/Stone and Half Wood Galvanized Iron/Aluminum Bamboo/Sawali/Cogon/Nipa Asbestos Glass Makeshift/Salvaged/Improvised Materials Others/Not Reported No Walls	1 0 1 0 0 0 0 0 0	0 30 0 3 5 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0	4 0 0 0 0 0 0 0 0 0 0	4 1 0 3 0 0 0 0 10 0	