

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |
| PAMPANGA | | | | |
| Total | 374,307 | 322,451 | 2,965 | 28,471 |
| Concrete/Brick/Stone | 243,111 | 235,249 | 1,983 | 2,926 |
| Wood | 25,899 | 20,389 | 246 | 1,813 |
| Half Concrete/Brick/Stone and Half Wood | 81,952 | 56,381 | 584 | 22,204 |
| Galvanized Iron/Aluminum | 2,509 | 1,578 | 85 | 578 |
| Bamboo/Sawali/Cogon/Nipa | 14,465 | 6,575 | - | 813 |
| Asbestos | 15 | 10 | 1 | - |
| Glass | 265 | 192 | 20 | 20 |
| Makeshift/Salvaged/Improvised Materials | 1,124 | 633 | - | 30 |
| Others/Not Reported | 4,965 | 1,443 | 46 | 87 |
| No Walls | 2 | 1 | - | - |
| APALIT | | | | |
| Total | 18,792 | 16,814 | 84 | 737 |
| Concrete/Brick/Stone | 13,772 | 13,020 | 58 | 67 |
| Wood | 1,267 | 972 | 2 | 39 |
| Half Concrete/Brick/Stone and Half Wood | 3,289 | 2,595 | 18 | 602 |
| Galvanized Iron/Aluminum | 143 | 105 | 6 | 22 |
| Bamboo/Sawali/Cogon/Nipa | 150 | 69 | - | 5 |
| Asbestos | - | - | - | - |
| Glass | 7 | 1 | - | - |
| Makeshift/Salvaged/Improvised Materials | 11 | 3 | - | - |
| Others/Not Reported | 153 | 49 | - | 2 |
| No Walls | - | - | - | - |
| ARAYAT | | | | |
| Total | 21,593 | 17,776 | 176 | 2,469 |
| Concrete/Brick/Stone | 13,225 | 12,837 | 115 | 173 |
| Wood | 1,294 | 910 | 17 | 71 |
| Half Concrete/Brick/Stone and Half Wood | 5,348 | 3,023 | 17 | 2,052 |
| Galvanized Iron/Aluminum | 221 | 144 | 24 | 34 |
| Bamboo/Sawali/Cogon/Nipa | 1,306 | 796 | - | 131 |
| Asbestos | 1 | 1 | - | - |
| Glass | 6 | 3 | 1 | 1 |
| Makeshift/Salvaged/Improvised Materials | 47 | 23 | - | 2 |
| Others/Not Reported | 145 | 39 | 2 | 5 |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|-------------------------|--|
| | | Galvanized Iron/Aluminum | Tile Concrete/Clay Tile | Half Galvanized Iron and Half Concrete |

BACOLOR

| | | | | |
|---|-------|-------|----|-----|
| Total | 5,418 | 4,456 | 74 | 691 |
| Concrete/Brick/Stone | 3,770 | 3,581 | 57 | 114 |
| Wood | 455 | 316 | 1 | 60 |
| Half Concrete/Brick/Stone and Half Wood | 867 | 389 | 10 | 451 |
| Galvanized Iron/Aluminum | 65 | 33 | 2 | 26 |
| Bamboo/Sawali/Cogon/Nipa | 209 | 121 | - | 39 |
| Asbestos | 1 | 1 | - | - |
| Glass | 11 | 7 | 3 | - |
| Makeshift/Salvaged/Improvised Materials | 2 | 1 | - | - |
| Others/Not Reported | 38 | 7 | 1 | 1 |
| No Walls | - | - | - | - |

CANDABA

| | | | | |
|---|--------|--------|----|-----|
| Total | 18,191 | 17,122 | 64 | 556 |
| Concrete/Brick/Stone | 9,373 | 9,274 | 31 | 19 |
| Wood | 1,920 | 1,767 | 15 | 16 |
| Half Concrete/Brick/Stone and Half Wood | 5,629 | 5,145 | 16 | 438 |
| Galvanized Iron/Aluminum | 60 | 38 | - | 15 |
| Bamboo/Sawali/Cogon/Nipa | 1,003 | 825 | - | 64 |
| Asbestos | - | - | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 43 | 35 | - | 2 |
| Others/Not Reported | 163 | 38 | 2 | 2 |
| No Walls | - | - | - | - |

FLORIDABLANCA

| | | | | |
|---|--------|--------|-----|-------|
| Total | 21,632 | 16,943 | 101 | 1,603 |
| Concrete/Brick/Stone | 13,127 | 12,675 | 60 | 172 |
| Wood | 347 | 232 | 1 | 31 |
| Half Concrete/Brick/Stone and Half Wood | 4,933 | 3,397 | 28 | 1,230 |
| Galvanized Iron/Aluminum | 335 | 264 | 10 | 51 |
| Bamboo/Sawali/Cogon/Nipa | 2,563 | 244 | - | 106 |
| Asbestos | 1 | 1 | - | - |
| Glass | 13 | 5 | 2 | 6 |
| Makeshift/Salvaged/Improvised Materials | 14 | 2 | - | - |
| Others/Not Reported | 299 | 123 | - | 7 |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |
| GUAGUA | | | | |
| Total | 21,037 | 17,131 | 121 | 2,890 |
| Concrete/Brick/Stone | 11,853 | 11,423 | 67 | 279 |
| Wood | 1,895 | 1,496 | 39 | 120 |
| Half Concrete/Brick/Stone and Half Wood | 6,168 | 3,756 | 14 | 2,301 |
| Galvanized Iron/Aluminum | 142 | 80 | 1 | 46 |
| Bamboo/Sawali/Cogon/Nipa | 635 | 234 | - | 133 |
| Asbestos | - | - | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 128 | 90 | - | 7 |
| Others/Not Reported | 216 | 52 | - | 4 |
| No Walls | - | - | - | - |
| LUBAO | | | | |
| Total | 28,823 | 23,993 | 437 | 2,088 |
| Concrete/Brick/Stone | 17,642 | 16,982 | 361 | 81 |
| Wood | 2,060 | 1,539 | 7 | 17 |
| Half Concrete/Brick/Stone and Half Wood | 6,504 | 4,440 | 56 | 1,816 |
| Galvanized Iron/Aluminum | 361 | 179 | 3 | 112 |
| Bamboo/Sawali/Cogon/Nipa | 1,957 | 711 | - | 56 |
| Asbestos | 6 | 5 | - | - |
| Glass | 1 | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 101 | 64 | - | 3 |
| Others/Not Reported | 191 | 73 | 10 | 3 |
| No Walls | - | - | - | - |
| MABALACAT | | | | |
| Total | 42,032 | 37,155 | 331 | 2,627 |
| Concrete/Brick/Stone | 31,986 | 31,160 | 229 | 115 |
| Wood | 1,389 | 1,052 | 31 | 22 |
| Half Concrete/Brick/Stone and Half Wood | 7,617 | 4,444 | 64 | 2,445 |
| Galvanized Iron/Aluminum | 128 | 79 | 2 | 28 |
| Bamboo/Sawali/Cogon/Nipa | 303 | 147 | - | 5 |
| Asbestos | 1 | 1 | - | - |
| Glass | 1 | 1 | - | - |
| Makeshift/Salvaged/Improvised Materials | 68 | 38 | - | - |
| Others/Not Reported | 539 | 233 | 5 | 12 |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |
| MACABEBE | | | | |
| Total | 13,283 | 10,930 | 76 | 1,893 |
| Concrete/Brick/Stone | 6,686 | 6,546 | 29 | 67 |
| Wood | 2,150 | 1,641 | 15 | 352 |
| Half Concrete/Brick/Stone and Half Wood | 4,100 | 2,588 | 28 | 1,453 |
| Galvanized Iron/Aluminum | 42 | 25 | 4 | 10 |
| Bamboo/Sawali/Cogon/Nipa | 87 | 63 | - | 3 |
| Asbestos | - | - | - | - |
| Glass | 1 | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 16 | 15 | - | - |
| Others/Not Reported | 201 | 52 | - | 8 |
| No Walls | - | - | - | - |
| MAGALANG | | | | |
| Total | 19,894 | 17,657 | 174 | 935 |
| Concrete/Brick/Stone | 14,966 | 14,616 | 101 | 126 |
| Wood | 306 | 182 | 2 | 18 |
| Half Concrete/Brick/Stone and Half Wood | 3,004 | 2,157 | 49 | 681 |
| Galvanized Iron/Aluminum | 151 | 77 | 6 | 59 |
| Bamboo/Sawali/Cogon/Nipa | 1,113 | 418 | - | 50 |
| Asbestos | - | - | - | - |
| Glass | 11 | 7 | 1 | - |
| Makeshift/Salvaged/Improvised Materials | 1 | - | - | - |
| Others/Not Reported | 342 | 200 | 15 | 1 |
| No Walls | - | - | - | - |
| MASANTOL | | | | |
| Total | 9,908 | 8,566 | 132 | 655 |
| Concrete/Brick/Stone | 4,094 | 3,900 | 55 | 115 |
| Wood | 2,377 | 1,854 | 34 | 148 |
| Half Concrete/Brick/Stone and Half Wood | 3,161 | 2,665 | 35 | 382 |
| Galvanized Iron/Aluminum | 49 | 35 | 5 | 5 |
| Bamboo/Sawali/Cogon/Nipa | 53 | 34 | - | - |
| Asbestos | - | - | - | - |
| Glass | 2 | - | 2 | - |
| Makeshift/Salvaged/Improvised Materials | 52 | 44 | - | - |
| Others/Not Reported | 120 | 34 | 1 | 5 |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |
| MEXICO | | | | |
| Total | 26,563 | 23,563 | 203 | 1,813 |
| Concrete/Brick/Stone | 17,254 | 16,813 | 153 | 167 |
| Wood | 1,039 | 845 | 10 | 61 |
| Half Concrete/Brick/Stone and Half Wood | 6,496 | 4,792 | 25 | 1,466 |
| Galvanized Iron/Aluminum | 302 | 240 | 14 | 33 |
| Bamboo/Sawali/Cogon/Nipa | 1,171 | 737 | - | 78 |
| Asbestos | - | - | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 78 | 48 | - | 3 |
| Others/Not Reported | 223 | 88 | 1 | 5 |
| No Walls | - | - | - | - |
| MINALIN | | | | |
| Total | 7,414 | 5,924 | 61 | 494 |
| Concrete/Brick/Stone | 3,846 | 3,745 | 48 | 38 |
| Wood | 1,005 | 953 | 2 | 30 |
| Half Concrete/Brick/Stone and Half Wood | 1,483 | 1,059 | 9 | 405 |
| Galvanized Iron/Aluminum | 20 | 16 | - | 3 |
| Bamboo/Sawali/Cogon/Nipa | 137 | 106 | - | 15 |
| Asbestos | 2 | 1 | 1 | - |
| Glass | 4 | 2 | - | - |
| Makeshift/Salvaged/Improvised Materials | 36 | 29 | - | 1 |
| Others/Not Reported | 881 | 13 | 1 | 2 |
| No Walls | - | - | - | - |
| PORAC | | | | |
| Total | 20,057 | 17,708 | 66 | 669 |
| Concrete/Brick/Stone | 15,101 | 14,864 | 54 | 30 |
| Wood | 431 | 354 | 3 | 3 |
| Half Concrete/Brick/Stone and Half Wood | 2,338 | 1,661 | 7 | 613 |
| Galvanized Iron/Aluminum | 42 | 34 | - | 5 |
| Bamboo/Sawali/Cogon/Nipa | 1,767 | 647 | - | 17 |
| Asbestos | 1 | - | - | - |
| Glass | 15 | 6 | - | - |
| Makeshift/Salvaged/Improvised Materials | 175 | 81 | - | 1 |
| Others/Not Reported | 187 | 61 | 2 | - |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |
| CITY OF SAN FERNANDO (Capital) | | | | |
| Total | 53,017 | 43,760 | 721 | 6,187 |
| Concrete/Brick/Stone | 35,610 | 33,830 | 492 | 878 |
| Wood | 3,975 | 2,753 | 33 | 656 |
| Half Concrete/Brick/Stone and Half Wood | 11,479 | 6,310 | 179 | 4,470 |
| Galvanized Iron/Aluminum | 267 | 109 | 4 | 90 |
| Bamboo/Sawali/Cogon/Nipa | 541 | 323 | - | 56 |
| Asbestos | 2 | - | - | - |
| Glass | 165 | 150 | 10 | 2 |
| Makeshift/Salvaged/Improvised Materials | 264 | 86 | - | 10 |
| Others/Not Reported | 713 | 199 | 3 | 25 |
| No Walls | 1 | - | - | - |
| SAN LUIS | | | | |
| Total | 8,614 | 8,019 | 16 | 410 |
| Concrete/Brick/Stone | 5,451 | 5,196 | 13 | 216 |
| Wood | 385 | 344 | - | 17 |
| Half Concrete/Brick/Stone and Half Wood | 2,108 | 1,924 | 2 | 157 |
| Galvanized Iron/Aluminum | 27 | 20 | 1 | 4 |
| Bamboo/Sawali/Cogon/Nipa | 542 | 467 | - | 14 |
| Asbestos | - | - | - | - |
| Glass | 2 | 2 | - | - |
| Makeshift/Salvaged/Improvised Materials | 44 | 36 | - | 1 |
| Others/Not Reported | 55 | 30 | - | 1 |
| No Walls | - | - | - | - |
| SAN SIMON | | | | |
| Total | 8,985 | 8,427 | 30 | 270 |
| Concrete/Brick/Stone | 5,640 | 5,597 | 14 | 16 |
| Wood | 787 | 673 | 1 | 22 |
| Half Concrete/Brick/Stone and Half Wood | 2,189 | 1,926 | 11 | 198 |
| Galvanized Iron/Aluminum | 76 | 50 | 1 | 20 |
| Bamboo/Sawali/Cogon/Nipa | 170 | 133 | - | 3 |
| Asbestos | - | - | - | - |
| Glass | 26 | 8 | 1 | 11 |
| Makeshift/Salvaged/Improvised Materials | 8 | 7 | - | - |
| Others/Not Reported | 89 | 33 | 2 | - |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |
| SANTA ANA | | | | |
| Total | 9,034 | 8,021 | 36 | 632 |
| Concrete/Brick/Stone | 6,671 | 6,410 | 25 | 126 |
| Wood | 299 | 225 | 3 | 18 |
| Half Concrete/Brick/Stone and Half Wood | 1,552 | 1,044 | 7 | 473 |
| Galvanized Iron/Aluminum | 12 | 10 | - | - |
| Bamboo/Sawali/Cogon/Nipa | 393 | 264 | - | 12 |
| Asbestos | - | - | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 7 | 5 | - | - |
| Others/Not Reported | 100 | 63 | 1 | 3 |
| No Walls | - | - | - | - |
| SANTA RITA | | | | |
| Total | 7,172 | 6,515 | 34 | 177 |
| Concrete/Brick/Stone | 5,204 | 4,977 | 12 | 116 |
| Wood | 426 | 324 | 16 | 17 |
| Half Concrete/Brick/Stone and Half Wood | 1,076 | 1,024 | 5 | 18 |
| Galvanized Iron/Aluminum | 33 | 15 | 1 | 10 |
| Bamboo/Sawali/Cogon/Nipa | 257 | 146 | - | 16 |
| Asbestos | - | - | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 1 | 1 | - | - |
| Others/Not Reported | 174 | 27 | - | - |
| No Walls | 1 | 1 | - | - |
| SANTO TOMAS | | | | |
| Total | 7,589 | 7,372 | 9 | 103 |
| Concrete/Brick/Stone | 4,927 | 4,894 | 8 | 9 |
| Wood | 1,347 | 1,320 | - | 7 |
| Half Concrete/Brick/Stone and Half Wood | 1,149 | 1,060 | - | 82 |
| Galvanized Iron/Aluminum | 18 | 11 | 1 | 4 |
| Bamboo/Sawali/Cogon/Nipa | 65 | 59 | - | - |
| Asbestos | - | - | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 12 | 11 | - | - |
| Others/Not Reported | 71 | 17 | - | 1 |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Total Occupied Housing Units | Construction Materials of the Roof | | |
|---|------------------------------|------------------------------------|--------------------------|--|
| | | Galvanized Iron/ Aluminum | Tile Concrete/ Clay Tile | Half Galvanized Iron and Half Concrete |

SASMUAN (SEXMOAN)

| | | | | |
|---|-------|-------|----|-----|
| Total | 5,259 | 4,599 | 19 | 572 |
| Concrete/Brick/Stone | 2,913 | 2,909 | 1 | 2 |
| Wood | 745 | 637 | 14 | 88 |
| Half Concrete/Brick/Stone and Half Wood | 1,462 | 982 | 4 | 471 |
| Galvanized Iron/Aluminum | 15 | 14 | - | 1 |
| Bamboo/Sawali/Cogon/Nipa | 43 | 31 | - | 10 |
| Asbestos | - | - | - | - |
| Glass | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 16 | 14 | - | - |
| Others/Not Reported | 65 | 12 | - | - |
| No Walls | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| PAMPANGA | | | | | |
| Total | 6,840 | 7,615 | 575 | 210 | 5,180 |
| Concrete/Brick/Stone | 1,369 | 301 | 34 | 109 | 1,140 |
| Wood | 2,747 | 478 | 74 | 19 | 133 |
| Half Concrete/Brick/Stone and Half Wood | 1,686 | 649 | 41 | 42 | 365 |
| Galvanized Iron/Aluminum | 211 | 29 | 3 | 1 | 24 |
| Bamboo/Sawali/Cogon/Nipa | 776 | 6,094 | 43 | 12 | 152 |
| Asbestos | 1 | - | - | 3 | - |
| Glass | 5 | - | - | 4 | 24 |
| Makeshift/Salvaged/Improvised Materials | 33 | 27 | 375 | 4 | 22 |
| Others/Not Reported | 12 | 37 | 4 | 16 | 3,320 |
| No Walls | - | - | 1 | - | - |
| APALIT | | | | | |
| Total | 865 | 85 | 11 | 5 | 191 |
| Concrete/Brick/Stone | 565 | 3 | 1 | 2 | 56 |
| Wood | 224 | 20 | 1 | - | 9 |
| Half Concrete/Brick/Stone and Half Wood | 45 | 11 | 1 | 1 | 16 |
| Galvanized Iron/Aluminum | 7 | 1 | 1 | - | 1 |
| Bamboo/Sawali/Cogon/Nipa | 22 | 47 | 3 | - | 4 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | 6 |
| Makeshift/Salvaged/Improvised Materials | - | 3 | 4 | - | 1 |
| Others/Not Reported | 2 | - | - | 2 | 98 |
| No Walls | - | - | - | - | - |
| ARAYAT | | | | | |
| Total | 379 | 519 | 31 | 42 | 201 |
| Concrete/Brick/Stone | 11 | 25 | - | 18 | 46 |
| Wood | 232 | 46 | 3 | 1 | 14 |
| Half Concrete/Brick/Stone and Half Wood | 51 | 153 | 3 | 20 | 29 |
| Galvanized Iron/Aluminum | 15 | 1 | - | - | 3 |
| Bamboo/Sawali/Cogon/Nipa | 70 | 292 | 3 | 1 | 13 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | 1 | - |
| Makeshift/Salvaged/Improvised Materials | - | - | 22 | - | - |
| Others/Not Reported | - | 2 | - | 1 | 96 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| BACOLOR | | | | | |
| Total | 83 | 72 | 1 | 1 | 40 |
| Concrete/Brick/Stone | 7 | 3 | - | 1 | 7 |
| Wood | 61 | 13 | 1 | - | 3 |
| Half Concrete/Brick/Stone and Half Wood | 9 | 6 | - | - | 2 |
| Galvanized Iron/Aluminum | 1 | 3 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 3 | 46 | - | - | - |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | 1 |
| Makeshift/Salvaged/Improvised Materials | 1 | - | - | - | - |
| Others/Not Reported | 1 | 1 | - | - | 27 |
| No Walls | - | - | - | - | - |
| CANDABA | | | | | |
| Total | 135 | 113 | 5 | 2 | 194 |
| Concrete/Brick/Stone | 4 | - | - | 1 | 44 |
| Wood | 94 | 15 | - | - | 13 |
| Half Concrete/Brick/Stone and Half Wood | 18 | 5 | - | - | 7 |
| Galvanized Iron/Aluminum | 6 | - | - | - | 1 |
| Bamboo/Sawali/Cogon/Nipa | 11 | 92 | 1 | 1 | 9 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 1 | 1 | 4 | - | - |
| Others/Not Reported | 1 | - | - | - | 120 |
| No Walls | - | - | - | - | - |
| FLORIDABLANCA | | | | | |
| Total | 125 | 2,524 | 11 | 1 | 324 |
| Concrete/Brick/Stone | 8 | 106 | 1 | - | 105 |
| Wood | 45 | 34 | - | - | 4 |
| Half Concrete/Brick/Stone and Half Wood | 23 | 220 | - | 1 | 34 |
| Galvanized Iron/Aluminum | - | 6 | - | - | 4 |
| Bamboo/Sawali/Cogon/Nipa | 48 | 2,144 | - | - | 21 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 1 | 1 | 10 | - | - |
| Others/Not Reported | - | 13 | - | - | 156 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| GUAGUA | | | | | |
| Total | 338 | 284 | 35 | 2 | 236 |
| Concrete/Brick/Stone | 30 | 6 | 3 | - | 45 |
| Wood | 204 | 23 | 1 | 1 | 11 |
| Half Concrete/Brick/Stone and Half Wood | 46 | 34 | - | - | 17 |
| Galvanized Iron/Aluminum | 8 | 5 | - | - | 2 |
| Bamboo/Sawali/Cogon/Nipa | 49 | 214 | 1 | - | 4 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 1 | 1 | 29 | - | - |
| Others/Not Reported | - | 1 | 1 | 1 | 157 |
| No Walls | - | - | - | - | - |
| LUBAO | | | | | |
| Total | 807 | 1,201 | 43 | 23 | 231 |
| Concrete/Brick/Stone | 82 | 67 | 7 | 3 | 59 |
| Wood | 394 | 82 | - | 5 | 16 |
| Half Concrete/Brick/Stone and Half Wood | 84 | 62 | 2 | 3 | 41 |
| Galvanized Iron/Aluminum | 58 | 4 | - | - | 5 |
| Bamboo/Sawali/Cogon/Nipa | 187 | 979 | 5 | 5 | 14 |
| Asbestos | - | - | - | 1 | - |
| Glass | - | - | - | - | 1 |
| Makeshift/Salvaged/Improvised Materials | - | 2 | 29 | 3 | - |
| Others/Not Reported | 2 | 5 | - | 3 | 95 |
| No Walls | - | - | - | - | - |
| MABALACAT | | | | | |
| Total | 1,167 | 152 | 32 | 22 | 546 |
| Concrete/Brick/Stone | 268 | 4 | 1 | 22 | 187 |
| Wood | 250 | 19 | 4 | - | 11 |
| Half Concrete/Brick/Stone and Half Wood | 609 | 5 | 1 | - | 49 |
| Galvanized Iron/Aluminum | 18 | - | - | - | 1 |
| Bamboo/Sawali/Cogon/Nipa | 20 | 120 | 1 | - | 10 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 4 | 25 | - | 1 |
| Others/Not Reported | 2 | - | - | - | 287 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| MACABEBE | | | | | |
| Total | 140 | 45 | 4 | 4 | 191 |
| Concrete/Brick/Stone | 8 | 1 | 2 | 2 | 31 |
| Wood | 110 | 23 | 1 | - | 8 |
| Half Concrete/Brick/Stone and Half Wood | 15 | 3 | - | 1 | 12 |
| Galvanized Iron/Aluminum | 3 | - | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 3 | 18 | - | - | - |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | 1 | - |
| Makeshift/Salvaged/Improvised Materials | - | - | 1 | - | - |
| Others/Not Reported | 1 | - | - | - | 140 |
| No Walls | - | - | - | - | - |
| MAGALANG | | | | | |
| Total | 257 | 637 | 2 | 1 | 231 |
| Concrete/Brick/Stone | 11 | 50 | 1 | - | 61 |
| Wood | 87 | 16 | - | - | 1 |
| Half Concrete/Brick/Stone and Half Wood | 42 | 48 | - | - | 27 |
| Galvanized Iron/Aluminum | 6 | 3 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 111 | 513 | 1 | - | 20 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | 3 |
| Makeshift/Salvaged/Improvised Materials | - | 1 | - | - | - |
| Others/Not Reported | - | 6 | - | 1 | 119 |
| No Walls | - | - | - | - | - |
| MASANTOL | | | | | |
| Total | 396 | 32 | 5 | 24 | 98 |
| Concrete/Brick/Stone | 12 | - | - | 6 | 6 |
| Wood | 311 | 15 | 1 | 7 | 7 |
| Half Concrete/Brick/Stone and Half Wood | 66 | - | - | 11 | 2 |
| Galvanized Iron/Aluminum | 4 | - | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 3 | 15 | - | - | 1 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 2 | 4 | - | 2 |
| Others/Not Reported | - | - | - | - | 80 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| MEXICO | | | | | |
| Total | 457 | 295 | 19 | 2 | 211 |
| Concrete/Brick/Stone | 55 | 6 | 1 | 2 | 57 |
| Wood | 69 | 50 | - | - | 4 |
| Half Concrete/Brick/Stone and Half Wood | 180 | 15 | 5 | - | 13 |
| Galvanized Iron/Aluminum | 13 | - | - | - | 2 |
| Bamboo/Sawali/Cogon/Nipa | 124 | 219 | 4 | - | 9 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 16 | 2 | 9 | - | - |
| Others/Not Reported | - | 3 | - | - | 126 |
| No Walls | - | - | - | - | - |
| MINALIN | | | | | |
| Total | 19 | 19 | 15 | 7 | 875 |
| Concrete/Brick/Stone | 4 | - | 2 | 2 | 7 |
| Wood | 10 | 3 | 5 | 1 | 1 |
| Half Concrete/Brick/Stone and Half Wood | 2 | 3 | 2 | - | 3 |
| Galvanized Iron/Aluminum | - | - | - | 1 | - |
| Bamboo/Sawali/Cogon/Nipa | 3 | 13 | - | - | - |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | 2 | - |
| Makeshift/Salvaged/Improvised Materials | - | - | 6 | - | - |
| Others/Not Reported | - | - | - | 1 | 864 |
| No Walls | - | - | - | - | - |
| PORAC | | | | | |
| Total | 63 | 1,161 | 79 | 27 | 284 |
| Concrete/Brick/Stone | 6 | 18 | 2 | 22 | 105 |
| Wood | 37 | 29 | 2 | 1 | 2 |
| Half Concrete/Brick/Stone and Half Wood | 6 | 36 | - | - | 15 |
| Galvanized Iron/Aluminum | 1 | 2 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 12 | 1,067 | 1 | - | 23 |
| Asbestos | - | - | - | 1 | - |
| Glass | - | - | - | - | 9 |
| Makeshift/Salvaged/Improvised Materials | 1 | 5 | 73 | - | 14 |
| Others/Not Reported | - | 4 | 1 | 3 | 116 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| CITY OF SAN FERNANDO (Capital) | | | | | |
| Total | 1,192 | 124 | 259 | 28 | 746 |
| Concrete/Brick/Stone | 213 | 2 | 10 | 20 | 165 |
| Wood | 436 | 27 | 51 | 2 | 17 |
| Half Concrete/Brick/Stone and Half Wood | 413 | 13 | 25 | 2 | 67 |
| Galvanized Iron/Aluminum | 58 | 2 | 2 | - | 2 |
| Bamboo/Sawali/Cogon/Nipa | 58 | 77 | 16 | - | 11 |
| Asbestos | 1 | - | - | 1 | - |
| Glass | - | - | - | - | 3 |
| Makeshift/Salvaged/Improvised Materials | 10 | 2 | 152 | - | 4 |
| Others/Not Reported | 3 | 1 | 2 | 3 | 477 |
| No Walls | - | - | 1 | - | - |
| SAN LUIS | | | | | |
| Total | 62 | 58 | 13 | 6 | 30 |
| Concrete/Brick/Stone | 18 | - | 2 | 4 | 2 |
| Wood | 15 | 6 | 2 | - | 1 |
| Half Concrete/Brick/Stone and Half Wood | 12 | 6 | 2 | 1 | 4 |
| Galvanized Iron/Aluminum | 2 | - | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 13 | 43 | 4 | 1 | - |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | 2 | 2 | 3 | - | - |
| Others/Not Reported | - | 1 | - | - | 23 |
| No Walls | - | - | - | - | - |
| SAN SIMON | | | | | |
| Total | 140 | 41 | 3 | 3 | 71 |
| Concrete/Brick/Stone | 5 | - | 1 | - | 7 |
| Wood | 79 | 10 | 1 | - | 1 |
| Half Concrete/Brick/Stone and Half Wood | 43 | 6 | - | - | 5 |
| Galvanized Iron/Aluminum | 5 | - | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 3 | 25 | - | 3 | 3 |
| Asbestos | - | - | - | - | - |
| Glass | 5 | - | - | - | 1 |
| Makeshift/Salvaged/Improvised Materials | - | - | 1 | - | - |
| Others/Not Reported | - | - | - | - | 54 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|---|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |
| SANTA ANA | | | | | |
| Total | 64 | 107 | 1 | 2 | 171 |
| Concrete/Brick/Stone | 2 | - | - | 1 | 107 |
| Wood | 43 | 6 | - | - | 4 |
| Half Concrete/Brick/Stone and Half Wood | 8 | 4 | - | - | 16 |
| Galvanized Iron/Aluminum | - | - | - | - | 2 |
| Bamboo/Sawali/Cogon/Nipa | 11 | 96 | - | 1 | 9 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | 1 | 1 | - | - |
| Others/Not Reported | - | - | - | - | 33 |
| No Walls | - | - | - | - | - |
| SANTA RITA | | | | | |
| Total | 132 | 128 | 2 | 4 | 180 |
| Concrete/Brick/Stone | 59 | 9 | - | 1 | 30 |
| Wood | 33 | 33 | 1 | - | 2 |
| Half Concrete/Brick/Stone and Half Wood | 10 | 16 | - | 2 | 1 |
| Galvanized Iron/Aluminum | 5 | 2 | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | 25 | 68 | 1 | - | 1 |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | - | - | - | - |
| Others/Not Reported | - | - | - | 1 | 146 |
| No Walls | - | - | - | - | - |
| SANTO TOMAS | | | | | |
| Total | 17 | 11 | - | 4 | 73 |
| Concrete/Brick/Stone | 1 | 1 | - | 2 | 12 |
| Wood | 12 | 3 | - | 1 | 4 |
| Half Concrete/Brick/Stone and Half Wood | 3 | 1 | - | - | 3 |
| Galvanized Iron/Aluminum | 1 | - | - | - | 1 |
| Bamboo/Sawali/Cogon/Nipa | - | 6 | - | - | - |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | - | - | 1 | - |
| Others/Not Reported | - | - | - | - | 53 |
| No Walls | - | - | - | - | - |

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

| Construction Materials of the Outer Walls and City/Municipality | Construction Materials of the Roof | | | | |
|--|------------------------------------|-----------------------|--|---------------------|-----------------|
| | Wood | Cogon/Nipa/ Anahaw | Makeshift/ Salvaged/ Improvised materials | Asbestos/ Others | Not Reported |

SASMUAN (SEXMOAN)

| | | | | | |
|---|---|---|---|---|----|
| Total | 2 | 7 | 4 | - | 56 |
| Concrete/Brick/Stone | - | - | - | - | 1 |
| Wood | 1 | 5 | - | - | - |
| Half Concrete/Brick/Stone and Half Wood | 1 | 2 | - | - | 2 |
| Galvanized Iron/Aluminum | - | - | - | - | - |
| Bamboo/Sawali/Cogon/Nipa | - | - | 2 | - | - |
| Asbestos | - | - | - | - | - |
| Glass | - | - | - | - | - |
| Makeshift/Salvaged/Improvised Materials | - | - | 2 | - | - |
| Others/Not Reported | - | - | - | - | 53 |
| No Walls | - | - | - | - | - |