

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

PANGASINAN

Total	543,797	437,419	3,697	40,700
Concrete/Brick/Stone	243,323	233,371	2,359	4,123
Wood	36,296	28,079	213	2,129
Half Concrete/Brick/Stone and Half Wood	130,621	97,084	766	27,048
Galvanized Iron/Aluminum	8,013	5,138	244	1,902
Bamboo/Sawali/Cogon/Nipa	118,105	70,349	-	5,150
Asbestos	138	70	3	12
Glass	274	109	21	105
Makeshift/Salvaged/Improvised Materials	2,640	1,227	-	118
Others/Not Reported	4,365	1,980	91	113
No Walls	22	12	-	-

AGNO

Total	5,831	4,776	26	41
Concrete/Brick/Stone	2,119	2,081	16	3
Wood	478	463	1	2
Half Concrete/Brick/Stone and Half Wood	1,004	970	5	18
Galvanized Iron/Aluminum	25	21	-	1
Bamboo/Sawali/Cogon/Nipa	2,167	1,226	-	17
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	2	-	-
Others/Not Reported	32	12	4	-
No Walls	1	-	-	-

AGUILAR

Total	7,138	6,354	5	47
Concrete/Brick/Stone	3,627	3,604	3	8
Wood	284	260	1	-
Half Concrete/Brick/Stone and Half Wood	1,413	1,362	1	24
Galvanized Iron/Aluminum	17	12	-	2
Bamboo/Sawali/Cogon/Nipa	1,737	1,089	-	13
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	16	9	-	-
Others/Not Reported	42	16	-	-
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

CITY OF ALAMINOS

Total	17,544	15,503	35	658
Concrete/Brick/Stone	8,351	8,273	28	23
Wood	1,453	1,332	1	28
Half Concrete/Brick/Stone and Half Wood	3,298	2,799	6	457
Galvanized Iron/Aluminum	129	118	-	5
Bamboo/Sawali/Cogon/Nipa	4,141	2,880	-	137
Asbestos	1	1	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	94	64	-	2
Others/Not Reported	76	35	-	6
No Walls	-	-	-	-

ALCALA

Total	8,153	6,902	30	752
Concrete/Brick/Stone	3,743	3,595	20	121
Wood	143	110	-	21
Half Concrete/Brick/Stone and Half Wood	1,877	1,456	10	386
Galvanized Iron/Aluminum	108	54	-	32
Bamboo/Sawali/Cogon/Nipa	2,222	1,660	-	188
Asbestos	1	-	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	3	-	1
Others/Not Reported	50	24	-	2
No Walls	-	-	-	-

ANANDA

Total	7,566	6,782	5	327
Concrete/Brick/Stone	2,681	2,627	1	30
Wood	594	522	1	53
Half Concrete/Brick/Stone and Half Wood	1,437	1,235	1	167
Galvanized Iron/Aluminum	59	43	-	8
Bamboo/Sawali/Cogon/Nipa	2,727	2,312	-	69
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	4	3	-	-
Others/Not Reported	63	39	2	-
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

ASINGAN

Total	11,592	9,596	302	955
Concrete/Brick/Stone	5,079	4,752	290	35
Wood	350	276	-	10
Half Concrete/Brick/Stone and Half Wood	3,498	2,711	5	764
Galvanized Iron/Aluminum	124	104	2	14
Bamboo/Sawali/Cogon/Nipa	2,390	1,688	-	104
Asbestos	2	1	1	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	52	2	-	27
Others/Not Reported	95	61	4	1
No Walls	1	1	-	-

BALUNGAO

Total	5,706	4,858	2	71
Concrete/Brick/Stone	3,259	3,246	2	5
Wood	41	40	-	1
Half Concrete/Brick/Stone and Half Wood	651	605	-	34
Galvanized Iron/Aluminum	7	7	-	-
Bamboo/Sawali/Cogon/Nipa	1,723	947	-	31
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	12	9	-	-
Others/Not Reported	12	3	-	-
No Walls	-	-	-	-

BANI

Total	10,168	9,409	5	47
Concrete/Brick/Stone	4,708	4,691	4	1
Wood	966	926	-	5
Half Concrete/Brick/Stone and Half Wood	1,908	1,865	-	30
Galvanized Iron/Aluminum	31	28	-	2
Bamboo/Sawali/Cogon/Nipa	2,501	1,872	-	8
Asbestos	3	3	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	12	11	-	-
Others/Not Reported	39	13	1	1
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

BASISTA

Total	5,814	3,775	250	760
Concrete/Brick/Stone	1,619	1,404	171	34
Wood	117	66	-	1
Half Concrete/Brick/Stone and Half Wood	2,236	1,442	55	695
Galvanized Iron/Aluminum	161	121	23	14
Bamboo/Sawali/Cogon/Nipa	1,654	726	-	14
Asbestos	1	-	-	1
Glass	8	7	1	-
Makeshift/Salvaged/Improvised Materials	11	7	-	-
Others/Not Reported	7	2	-	1
No Walls	-	-	-	-

BAUTISTA

Total	5,531	3,315	36	1,029
Concrete/Brick/Stone	1,680	1,623	19	31
Wood	151	99	-	9
Half Concrete/Brick/Stone and Half Wood	1,565	861	11	627
Galvanized Iron/Aluminum	85	17	3	44
Bamboo/Sawali/Cogon/Nipa	1,717	689	-	265
Asbestos	2	1	-	-
Glass	4	1	-	1
Makeshift/Salvaged/Improvised Materials	278	17	-	34
Others/Not Reported	49	7	3	18
No Walls	-	-	-	-

BAYAMBANG

Total	20,835	16,182	42	2,581
Concrete/Brick/Stone	7,207	7,149	20	23
Wood	786	503	1	92
Half Concrete/Brick/Stone and Half Wood	6,033	3,819	14	2,054
Galvanized Iron/Aluminum	993	777	6	193
Bamboo/Sawali/Cogon/Nipa	5,607	3,872	-	217
Asbestos	5	5	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	20	13	-	1
Others/Not Reported	183	43	1	1
No Walls	1	1	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

BINALONAN

Total	11,406	9,111	34	1,546
Concrete/Brick/Stone	6,075	5,841	24	188
Wood	314	202	1	73
Half Concrete/Brick/Stone and Half Wood	3,042	1,843	9	1,120
Galvanized Iron/Aluminum	100	84	-	13
Bamboo/Sawali/Cogon/Nipa	1,757	1,075	-	149
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	68	55	-	-
Others/Not Reported	49	10	-	3
No Walls	-	-	-	-

BINMALEY

Total	15,078	12,632	35	622
Concrete/Brick/Stone	6,152	6,006	19	112
Wood	2,834	2,352	3	74
Half Concrete/Brick/Stone and Half Wood	3,558	3,074	11	397
Galvanized Iron/Aluminum	87	61	1	10
Bamboo/Sawali/Cogon/Nipa	2,263	1,074	-	26
Asbestos	6	6	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	142	48	-	1
Others/Not Reported	35	10	1	2
No Walls	-	-	-	-

BOLINAO

Total	14,110	11,274	152	1,047
Concrete/Brick/Stone	4,661	4,445	131	41
Wood	1,000	854	1	47
Half Concrete/Brick/Stone and Half Wood	3,300	2,474	13	752
Galvanized Iron/Aluminum	202	133	3	51
Bamboo/Sawali/Cogon/Nipa	4,572	3,279	-	151
Asbestos	19	11	-	1
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	240	29	-	2
Others/Not Reported	115	49	4	2
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

BUGALLON

Total	11,919	8,779	34	1,052
Concrete/Brick/Stone	4,339	4,179	24	89
Wood	802	498	2	156
Half Concrete/Brick/Stone and Half Wood	3,477	2,694	6	681
Galvanized Iron/Aluminum	69	43	2	20
Bamboo/Sawali/Cogon/Nipa	3,012	1,287	-	97
Asbestos	1	1	-	-
Glass	2	1	-	1
Makeshift/Salvaged/Improvised Materials	152	50	-	8
Others/Not Reported	64	25	-	-
No Walls	1	1	-	-

BURGOS

Total	4,155	3,068	28	225
Concrete/Brick/Stone	1,723	1,681	24	8
Wood	81	43	3	11
Half Concrete/Brick/Stone and Half Wood	746	583	1	149
Galvanized Iron/Aluminum	21	15	-	3
Bamboo/Sawali/Cogon/Nipa	1,556	739	-	54
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	10	4	-	-
Others/Not Reported	18	3	-	-
No Walls	-	-	-	-

CALASIAO

Total	16,834	13,684	85	1,641
Concrete/Brick/Stone	6,991	6,623	59	175
Wood	1,207	1,015	1	63
Half Concrete/Brick/Stone and Half Wood	5,228	4,093	17	979
Galvanized Iron/Aluminum	512	261	5	227
Bamboo/Sawali/Cogon/Nipa	2,674	1,559	-	190
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	53	36	-	-
Others/Not Reported	169	97	3	7
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

DAGUPAN CITY

Total	30,371	27,901	195	739
Concrete/Brick/Stone	13,747	13,511	110	78
Wood	6,270	5,866	17	38
Half Concrete/Brick/Stone and Half Wood	7,418	6,779	56	544
Galvanized Iron/Aluminum	192	163	9	15
Bamboo/Sawali/Cogon/Nipa	2,084	1,203	-	63
Asbestos	1	1	-	-
Glass	3	2	1	-
Makeshift/Salvaged/Improvised Materials	350	248	-	1
Others/Not Reported	305	127	2	-
No Walls	1	1	-	-

DASOL

Total	5,765	4,069	1	403
Concrete/Brick/Stone	2,057	2,022	-	17
Wood	119	109	-	3
Half Concrete/Brick/Stone and Half Wood	1,312	1,061	-	224
Galvanized Iron/Aluminum	36	26	-	7
Bamboo/Sawali/Cogon/Nipa	2,200	836	-	150
Asbestos	4	3	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	19	6	-	2
Others/Not Reported	17	6	1	-
No Walls	1	-	-	-

INFANTA

Total	4,970	3,434	11	396
Concrete/Brick/Stone	1,634	1,611	7	5
Wood	156	134	-	7
Half Concrete/Brick/Stone and Half Wood	1,196	961	2	207
Galvanized Iron/Aluminum	48	19	1	26
Bamboo/Sawali/Cogon/Nipa	1,910	703	-	151
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	2	-	-
Others/Not Reported	22	4	1	-
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

LABRADOR

Total	4,301	2,679	70	288
Concrete/Brick/Stone	1,998	1,444	60	138
Wood	183	109	-	-
Half Concrete/Brick/Stone and Half Wood	868	641	4	135
Galvanized Iron/Aluminum	38	21	5	9
Bamboo/Sawali/Cogon/Nipa	1,181	454	-	5
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	8	4	-	-
Others/Not Reported	25	6	1	1
No Walls	-	-	-	-

LINGAYEN (Capital)

Total	18,682	12,748	134	2,441
Concrete/Brick/Stone	6,643	6,113	111	357
Wood	2,548	1,775	5	216
Half Concrete/Brick/Stone and Half Wood	5,168	3,278	15	1,573
Galvanized Iron/Aluminum	698	403	3	158
Bamboo/Sawali/Cogon/Nipa	3,418	1,076	-	132
Asbestos	5	2	-	1
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	97	44	-	2
Others/Not Reported	103	55	-	2
No Walls	2	2	-	-

MABINI

Total	5,003	2,981	253	485
Concrete/Brick/Stone	1,931	1,568	224	130
Wood	336	139	2	16
Half Concrete/Brick/Stone and Half Wood	783	549	21	197
Galvanized Iron/Aluminum	38	27	4	5
Bamboo/Sawali/Cogon/Nipa	1,863	679	-	127
Asbestos	-	-	-	-
Glass	20	10	1	9
Makeshift/Salvaged/Improvised Materials	12	3	-	-
Others/Not Reported	20	6	1	1
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

MALASIQUI

Total	24,290	20,227	142	1,693
Concrete/Brick/Stone	9,660	9,251	101	280
Wood	776	608	5	42
Half Concrete/Brick/Stone and Half Wood	6,792	5,588	27	1,068
Galvanized Iron/Aluminum	172	105	4	47
Bamboo/Sawali/Cogon/Nipa	6,628	4,549	-	251
Asbestos	6	4	-	-
Glass	8	4	3	1
Makeshift/Salvaged/Improvised Materials	38	28	-	1
Others/Not Reported	210	90	2	3
No Walls	-	-	-	-

MANAOAG

Total	12,306	11,010	67	580
Concrete/Brick/Stone	6,008	5,927	24	40
Wood	794	539	-	93
Half Concrete/Brick/Stone and Half Wood	2,737	2,298	9	404
Galvanized Iron/Aluminum	105	64	34	7
Bamboo/Sawali/Cogon/Nipa	2,370	1,989	-	33
Asbestos	1	1	-	-
Glass	1	-	-	-
Makeshift/Salvaged/Improvised Materials	41	19	-	2
Others/Not Reported	249	173	-	1
No Walls	-	-	-	-

MANGALDAN

Total	17,964	13,108	150	3,085
Concrete/Brick/Stone	7,337	6,700	118	487
Wood	1,381	1,095	3	69
Half Concrete/Brick/Stone and Half Wood	6,263	3,926	22	2,215
Galvanized Iron/Aluminum	213	106	4	51
Bamboo/Sawali/Cogon/Nipa	2,623	1,231	-	256
Asbestos	3	1	1	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	51	30	-	3
Others/Not Reported	93	19	2	4
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

MANGATAREM

Total	13,380	10,561	22	1,273
Concrete/Brick/Stone	5,266	5,139	16	78
Wood	231	180	-	35
Half Concrete/Brick/Stone and Half Wood	3,411	2,433	4	911
Galvanized Iron/Aluminum	86	63	1	19
Bamboo/Sawali/Cogon/Nipa	4,243	2,682	-	227
Asbestos	4	2	-	2
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	36	19	-	-
Others/Not Reported	102	43	1	1
No Walls	1	-	-	-

MAPANDAN

Total	6,258	1,019	58	1,489
Concrete/Brick/Stone	1,852	465	35	332
Wood	961	190	13	124
Half Concrete/Brick/Stone and Half Wood	2,875	293	5	998
Galvanized Iron/Aluminum	69	9	5	10
Bamboo/Sawali/Cogon/Nipa	426	54	-	21
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-
Others/Not Reported	73	8	-	4
No Walls	-	-	-	-

NATIVIDAD

Total	4,741	4,060	3	54
Concrete/Brick/Stone	2,969	2,933	2	5
Wood	74	63	-	2
Half Concrete/Brick/Stone and Half Wood	605	538	-	32
Galvanized Iron/Aluminum	19	17	-	1
Bamboo/Sawali/Cogon/Nipa	966	445	-	14
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	17	11	-	-
Others/Not Reported	91	53	1	-
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

POZZORUBIO

Total	13,108	11,529	16	526
Concrete/Brick/Stone	7,962	7,633	15	183
Wood	457	393	-	17
Half Concrete/Brick/Stone and Half Wood	2,339	1,649	1	279
Galvanized Iron/Aluminum	135	120	-	6
Bamboo/Sawali/Cogon/Nipa	2,091	1,645	-	40
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	72	49	-	1
Others/Not Reported	52	40	-	-
No Walls	-	-	-	-

ROSALES

Total	12,502	8,793	175	1,122
Concrete/Brick/Stone	6,131	5,242	87	279
Wood	401	262	9	32
Half Concrete/Brick/Stone and Half Wood	3,004	1,805	46	604
Galvanized Iron/Aluminum	249	151	23	50
Bamboo/Sawali/Cogon/Nipa	2,536	1,273	-	146
Asbestos	10	4	-	3
Glass	3	2	-	-
Makeshift/Salvaged/Improvised Materials	18	4	-	5
Others/Not Reported	150	50	10	3
No Walls	-	-	-	-

SAN CARLOS CITY

Total	31,234	23,404	508	4,106
Concrete/Brick/Stone	11,912	11,476	203	158
Wood	2,426	1,301	78	516
Half Concrete/Brick/Stone and Half Wood	9,487	6,502	165	2,350
Galvanized Iron/Aluminum	790	191	29	423
Bamboo/Sawali/Cogon/Nipa	6,111	3,810	-	548
Asbestos	45	9	1	3
Glass	132	19	12	71
Makeshift/Salvaged/Improvised Materials	37	13	-	4
Others/Not Reported	287	83	20	33
No Walls	7	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SAN FABIAN

Total	15,042	12,898	51	383
Concrete/Brick/Stone	7,456	7,286	28	40
Wood	1,233	944	14	37
Half Concrete/Brick/Stone and Half Wood	2,155	1,904	7	166
Galvanized Iron/Aluminum	190	164	1	17
Bamboo/Sawali/Cogon/Nipa	3,726	2,461	-	119
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	115	58	-	3
Others/Not Reported	167	81	1	1
No Walls	-	-	-	-

SAN JACINTO

Total	7,092	6,514	10	48
Concrete/Brick/Stone	3,601	3,547	7	7
Wood	362	325	3	3
Half Concrete/Brick/Stone and Half Wood	1,338	1,279	-	31
Galvanized Iron/Aluminum	62	58	-	4
Bamboo/Sawali/Cogon/Nipa	1,580	1,201	-	3
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	55	44	-	-
Others/Not Reported	92	58	-	-
No Walls	-	-	-	-

SAN MANUEL

Total	9,943	8,437	46	596
Concrete/Brick/Stone	5,239	5,122	41	49
Wood	380	259	2	50
Half Concrete/Brick/Stone and Half Wood	2,431	1,982	3	403
Galvanized Iron/Aluminum	180	105	-	69
Bamboo/Sawali/Cogon/Nipa	1,639	947	-	25
Asbestos	4	4	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	69	17	-	-
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SAN NICOLAS

Total	7,242	6,014	29	351
Concrete/Brick/Stone	3,926	3,871	6	24
Wood	338	232	3	11
Half Concrete/Brick/Stone and Half Wood	1,194	923	2	247
Galvanized Iron/Aluminum	83	60	12	7
Bamboo/Sawali/Cogon/Nipa	1,606	863	-	59
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	12	8	-	-
Others/Not Reported	82	56	6	3
No Walls	1	1	-	-

SAN QUINTIN

Total	6,423	5,377	1	210
Concrete/Brick/Stone	3,774	3,748	1	19
Wood	180	154	-	4
Half Concrete/Brick/Stone and Half Wood	927	729	-	140
Galvanized Iron/Aluminum	19	12	-	5
Bamboo/Sawali/Cogon/Nipa	1,446	716	-	42
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	7	-	-
Others/Not Reported	68	11	-	-
No Walls	-	-	-	-

SANTA BARBARA

Total	14,815	12,366	61	1,066
Concrete/Brick/Stone	7,131	7,052	27	24
Wood	582	487	10	26
Half Concrete/Brick/Stone and Half Wood	2,971	2,162	19	687
Galvanized Iron/Aluminum	457	369	2	66
Bamboo/Sawali/Cogon/Nipa	3,403	2,123	-	238
Asbestos	1	-	-	-
Glass	73	48	2	21
Makeshift/Salvaged/Improvised Materials	52	31	-	1
Others/Not Reported	145	94	1	3
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SANTA MARIA

Total	6,497	5,805	24	395
Concrete/Brick/Stone	3,919	3,896	15	3
Wood	229	202	2	3
Half Concrete/Brick/Stone and Half Wood	1,227	845	4	372
Galvanized Iron/Aluminum	44	32	3	9
Bamboo/Sawali/Cogon/Nipa	943	740	-	7
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	24	13	-	1
Others/Not Reported	110	76	-	-
No Walls	-	-	-	-

SANTO TOMAS

Total	2,824	2,732	2	14
Concrete/Brick/Stone	1,794	1,783	2	7
Wood	36	35	-	1
Half Concrete/Brick/Stone and Half Wood	453	447	-	3
Galvanized Iron/Aluminum	11	10	-	-
Bamboo/Sawali/Cogon/Nipa	515	445	-	3
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	12	11	-	-
Others/Not Reported	3	1	-	-
No Walls	-	-	-	-

SISON

Total	8,832	7,952	38	278
Concrete/Brick/Stone	5,403	5,309	34	36
Wood	258	235	-	-
Half Concrete/Brick/Stone and Half Wood	1,461	1,143	4	220
Galvanized Iron/Aluminum	153	133	-	13
Bamboo/Sawali/Cogon/Nipa	1,396	1,018	-	8
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	52	31	-	1
Others/Not Reported	108	82	-	-
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

SUAL

Total	6,395	4,967	7	245
Concrete/Brick/Stone	2,498	2,471	7	3
Wood	612	528	-	7
Half Concrete/Brick/Stone and Half Wood	1,060	828	-	206
Galvanized Iron/Aluminum	35	21	-	4
Bamboo/Sawali/Cogon/Nipa	2,054	1,058	-	17
Asbestos	1	1	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	60	20	-	7
Others/Not Reported	74	39	-	1
No Walls	-	-	-	-

TAYUG

Total	8,220	7,304	15	486
Concrete/Brick/Stone	4,377	4,257	13	48
Wood	419	344	2	37
Half Concrete/Brick/Stone and Half Wood	1,904	1,591	-	290
Galvanized Iron/Aluminum	42	31	-	10
Bamboo/Sawali/Cogon/Nipa	1,375	1,027	-	98
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	30	19	-	2
Others/Not Reported	73	35	-	1
No Walls	-	-	-	-

UMINGAN

Total	13,883	10,179	6	912
Concrete/Brick/Stone	7,339	7,231	2	34
Wood	205	173	1	9
Half Concrete/Brick/Stone and Half Wood	2,455	1,576	2	722
Galvanized Iron/Aluminum	99	66	-	20
Bamboo/Sawali/Cogon/Nipa	3,703	1,102	-	122
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	23	12	-	4
Others/Not Reported	59	19	1	1
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

URBIZTONDO

Total	8,359	6,045	57	732
Concrete/Brick/Stone	2,467	2,389	29	36
Wood	150	112	2	6
Half Concrete/Brick/Stone and Half Wood	2,392	1,916	16	379
Galvanized Iron/Aluminum	354	255	3	63
Bamboo/Sawali/Cogon/Nipa	2,769	1,257	-	242
Asbestos	-	-	-	-
Glass	2	-	-	1
Makeshift/Salvaged/Improvised Materials	62	34	-	2
Others/Not Reported	163	82	7	3
No Walls	-	-	-	-

CITY OF URDANETA

Total	25,381	21,077	327	1,871
Concrete/Brick/Stone	13,623	13,161	130	107
Wood	1,790	1,256	23	61
Half Concrete/Brick/Stone and Half Wood	5,687	3,843	156	1,438
Galvanized Iron/Aluminum	445	319	10	92
Bamboo/Sawali/Cogon/Nipa	3,552	2,369	-	172
Asbestos	3	-	-	-
Glass	9	8	1	-
Makeshift/Salvaged/Improvised Materials	93	54	-	-
Others/Not Reported	174	62	7	1
No Walls	5	5	-	-

VILLASIS

Total	12,457	10,659	90	687
Concrete/Brick/Stone	6,454	6,306	33	96
Wood	617	307	1	15
Half Concrete/Brick/Stone and Half Wood	2,871	2,368	7	475
Galvanized Iron/Aluminum	165	74	46	41
Bamboo/Sawali/Cogon/Nipa	2,229	1,515	-	58
Asbestos	1	1	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	44	36	-	-
Others/Not Reported	74	50	3	2
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

LAOAC

Total	6,137	5,570	22	345
Concrete/Brick/Stone	3,201	3,087	16	96
Wood	191	162	2	3
Half Concrete/Brick/Stone and Half Wood	1,566	1,361	4	194
Galvanized Iron/Aluminum	56	45	-	9
Bamboo/Sawali/Cogon/Nipa	1,099	904	-	43
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	17	6	-	-
Others/Not Reported	7	5	-	-
No Walls	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

PANGASINAN

Total	13,206	43,289	1,826	767	2,893
Concrete/Brick/Stone	2,429	468	79	130	364
Wood	3,006	2,670	98	31	70
Half Concrete/Brick/Stone and Half Wood	3,885	1,232	230	124	252
Galvanized Iron/Aluminum	463	222	10	11	23
Bamboo/Sawali/Cogon/Nipa	3,312	38,214	460	315	305
Asbestos	10	-	-	29	14
Glass	12	-	-	18	9
Makeshift/Salvaged/Improvised Materials	19	304	943	14	15
Others/Not Reported	70	175	5	90	1,841
No Walls	-	4	1	5	-

AGNO

Total	17	929	2	4	36
Concrete/Brick/Stone	-	4	-	2	13
Wood	1	10	-	-	1
Half Concrete/Brick/Stone and Half Wood	4	4	-	-	3
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	904	-	1	7
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	-	3	-	1	12
No Walls	-	1	-	-	-

AGUILAR

Total	5	686	6	2	33
Concrete/Brick/Stone	-	6	-	1	5
Wood	3	19	-	1	-
Half Concrete/Brick/Stone and Half Wood	-	25	-	-	1
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	628	3	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	3	-	-
Others/Not Reported	-	1	-	-	25
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

CITY OF ALAMINOS

Total	105	1,163	18	3	59
Concrete/Brick/Stone	5	14	-	1	7
Wood	29	58	2	-	3
Half Concrete/Brick/Stone and Half Wood	6	21	1	1	7
Galvanized Iron/Aluminum	3	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	62	1,049	3	1	9
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	16	12	-	-
Others/Not Reported	-	2	-	-	33
No Walls	-	-	-	-	-

ALCALA

Total	55	378	4	1	31
Concrete/Brick/Stone	1	3	-	-	3
Wood	8	3	-	-	1
Half Concrete/Brick/Stone and Half Wood	12	12	-	-	1
Galvanized Iron/Aluminum	3	19	-	-	-
Bamboo/Sawali/Cogon/Nipa	31	338	2	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	2	-	-
Others/Not Reported	-	-	-	-	24
No Walls	-	-	-	-	-

ANDA

Total	184	228	1	7	32
Concrete/Brick/Stone	16	-	-	-	7
Wood	5	12	-	-	1
Half Concrete/Brick/Stone and Half Wood	31	2	-	-	1
Galvanized Iron/Aluminum	8	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	124	212	-	2	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	2	-	5	15
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

ASINGAN

Total	92	581	23	4	39
Concrete/Brick/Stone	-	1	-	-	1
Wood	58	4	-	2	-
Half Concrete/Brick/Stone and Half Wood	2	8	-	-	8
Galvanized Iron/Aluminum	1	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	30	563	-	1	4
Asbestos	-	-	-	-	-
Glass	1	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	23	-	-
Others/Not Reported	-	2	-	1	26
No Walls	-	-	-	-	-

BALUNGAO

Total	3	753	5	1	13
Concrete/Brick/Stone	-	3	-	1	2
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	11	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	738	3	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	2	-	-
Others/Not Reported	-	-	-	-	9
No Walls	-	-	-	-	-

BANI

Total	4	657	4	2	40
Concrete/Brick/Stone	-	5	-	-	7
Wood	1	32	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	8	4	-	1
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	611	-	2	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	-	24
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

BASISTA

Total	67	947	3	2	10
Concrete/Brick/Stone	1	8	-	-	1
Wood	43	7	-	-	-
Half Concrete/Brick/Stone and Half Wood	7	34	-	2	1
Galvanized Iron/Aluminum	1	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	15	892	2	-	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	1	-	-
Others/Not Reported	-	1	-	-	3
No Walls	-	-	-	-	-

BAUTISTA

Total	181	679	264	9	18
Concrete/Brick/Stone	1	2	1	2	1
Wood	26	14	-	3	-
Half Concrete/Brick/Stone and Half Wood	43	13	7	2	1
Galvanized Iron/Aluminum	13	7	-	-	1
Bamboo/Sawali/Cogon/Nipa	94	616	50	1	2
Asbestos	1	-	-	-	-
Glass	1	-	-	-	1
Makeshift/Salvaged/Improvised Materials	2	18	206	-	1
Others/Not Reported	-	9	-	1	11
No Walls	-	-	-	-	-

BAYAMBANG

Total	559	1,286	8	-	177
Concrete/Brick/Stone	1	4	-	-	10
Wood	145	43	-	-	2
Half Concrete/Brick/Stone and Half Wood	111	24	-	-	11
Galvanized Iron/Aluminum	7	8	-	-	2
Bamboo/Sawali/Cogon/Nipa	295	1,205	3	-	15
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	5	-	-
Others/Not Reported	-	1	-	-	137
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

BINALONAN

Total	221	442	9	2	41
Concrete/Brick/Stone	13	4	-	2	3
Wood	32	6	-	-	-
Half Concrete/Brick/Stone and Half Wood	62	5	-	-	3
Galvanized Iron/Aluminum	2	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	110	422	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	9	-	-
Others/Not Reported	2	-	-	-	34
No Walls	-	-	-	-	-

BINMALEY

Total	41	1,663	56	8	21
Concrete/Brick/Stone	1	11	1	1	1
Wood	17	384	1	2	1
Half Concrete/Brick/Stone and Half Wood	14	56	1	1	4
Galvanized Iron/Aluminum	1	13	1	-	-
Bamboo/Sawali/Cogon/Nipa	8	1,148	2	1	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	37	50	3	3
Others/Not Reported	-	14	-	-	8
No Walls	-	-	-	-	-

BOLINAO

Total	131	1,140	226	15	125
Concrete/Brick/Stone	12	8	-	4	20
Wood	46	47	1	1	3
Half Concrete/Brick/Stone and Half Wood	8	34	-	2	17
Galvanized Iron/Aluminum	7	7	1	-	-
Bamboo/Sawali/Cogon/Nipa	56	1,038	18	-	30
Asbestos	-	-	-	6	1
Glass	-	-	-	1	-
Makeshift/Salvaged/Improvised Materials	1	2	205	-	1
Others/Not Reported	1	4	1	1	53
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

BUGALLON

Total	69	1,752	158	26	49
Concrete/Brick/Stone	1	26	1	11	8
Wood	34	92	17	3	-
Half Concrete/Brick/Stone and Half Wood	19	69	1	4	3
Galvanized Iron/Aluminum	1	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	1,533	72	6	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	26	67	1	-
Others/Not Reported	-	3	-	1	35
No Walls	-	-	-	-	-

BURGOS

Total	35	779	2	-	18
Concrete/Brick/Stone	2	6	-	-	2
Wood	21	3	-	-	-
Half Concrete/Brick/Stone and Half Wood	5	8	-	-	-
Galvanized Iron/Aluminum	1	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	754	-	-	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	2	-	-
Others/Not Reported	-	2	-	-	13
No Walls	-	-	-	-	-

CALASIAO

Total	403	907	16	33	65
Concrete/Brick/Stone	117	10	2	1	4
Wood	72	50	1	2	3
Half Concrete/Brick/Stone and Half Wood	81	49	-	5	4
Galvanized Iron/Aluminum	9	10	-	-	-
Bamboo/Sawali/Cogon/Nipa	124	779	3	16	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	7	10	-	-
Others/Not Reported	-	2	-	9	51
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

DAGUPAN CITY

Total	289	930	99	11	207
Concrete/Brick/Stone	13	10	3	6	16
Wood	196	136	8	1	8
Half Concrete/Brick/Stone and Half Wood	20	10	1	-	8
Galvanized Iron/Aluminum	2	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	54	747	10	2	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	21	77	-	2
Others/Not Reported	3	3	-	2	168
No Walls	-	-	-	-	-

DASOL

Total	3	1,272	2	3	12
Concrete/Brick/Stone	-	16	-	2	-
Wood	1	6	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	25	-	-	2
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	1,207	1	-	4
Asbestos	-	-	-	1	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	10	1	-	-
Others/Not Reported	-	4	-	-	6
No Walls	-	1	-	-	-

INFANTA

Total	10	1,099	4	-	16
Concrete/Brick/Stone	-	11	-	-	-
Wood	2	13	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	25	1	-	-
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	1,047	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	2	-	-
Others/Not Reported	-	1	-	-	16
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

LABRADOR

Total	649	591	3	7	14
Concrete/Brick/Stone	337	14	1	2	2
Wood	61	13	-	-	-
Half Concrete/Brick/Stone and Half Wood	76	11	-	-	1
Galvanized Iron/Aluminum	1	1	-	1	-
Bamboo/Sawali/Cogon/Nipa	172	545	1	3	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	3	1	-	-
Others/Not Reported	2	4	-	1	10
No Walls	-	-	-	-	-

LINGAYEN (Capital)

Total	585	2,656	26	15	77
Concrete/Brick/Stone	4	36	-	15	7
Wood	96	452	3	-	1
Half Concrete/Brick/Stone and Half Wood	198	91	1	-	12
Galvanized Iron/Aluminum	124	10	-	-	-
Bamboo/Sawali/Cogon/Nipa	158	2,034	1	-	17
Asbestos	-	-	-	-	2
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	4	26	21	-	-
Others/Not Reported	1	7	-	-	38
No Walls	-	-	-	-	-

MABINI

Total	9	1,246	10	5	14
Concrete/Brick/Stone	-	5	-	4	-
Wood	1	173	1	1	3
Half Concrete/Brick/Stone and Half Wood	2	12	-	-	2
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	1,046	1	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	8	-	-
Others/Not Reported	-	7	-	-	5
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

MALASIQUI

Total	215	1,852	11	19	131
Concrete/Brick/Stone	10	8	-	3	7
Wood	79	38	2	1	1
Half Concrete/Brick/Stone and Half Wood	38	65	-	3	3
Galvanized Iron/Aluminum	8	7	-	-	1
Bamboo/Sawali/Cogon/Nipa	79	1,727	4	7	11
Asbestos	-	-	-	2	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	5	-	-
Others/Not Reported	1	3	-	3	108
No Walls	-	-	-	-	-

MANAOAG

Total	149	370	24	16	90
Concrete/Brick/Stone	6	3	1	1	6
Wood	117	44	1	-	-
Half Concrete/Brick/Stone and Half Wood	9	11	-	2	4
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	17	309	3	10	9
Asbestos	-	-	-	-	-
Glass	-	-	-	1	-
Makeshift/Salvaged/Improvised Materials	-	1	19	-	-
Others/Not Reported	-	2	-	2	71
No Walls	-	-	-	-	-

MANGALDAN

Total	312	1,180	20	9	100
Concrete/Brick/Stone	13	12	-	3	4
Wood	123	80	1	1	9
Half Concrete/Brick/Stone and Half Wood	53	27	3	2	15
Galvanized Iron/Aluminum	49	2	-	1	-
Bamboo/Sawali/Cogon/Nipa	73	1,052	4	2	5
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	6	11	-	-
Others/Not Reported	-	1	1	-	66
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

MANGATAREM

Total	28	1,382	23	10	81
Concrete/Brick/Stone	1	19	2	5	6
Wood	7	9	-	-	-
Half Concrete/Brick/Stone and Half Wood	10	39	5	1	8
Galvanized Iron/Aluminum	-	2	-	-	1
Bamboo/Sawali/Cogon/Nipa	10	1,303	7	4	10
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	8	9	-	-
Others/Not Reported	-	1	-	-	56
No Walls	-	1	-	-	-

MAPANDAN

Total	3,431	190	1	1	69
Concrete/Brick/Stone	988	11	-	-	21
Wood	594	37	1	-	2
Half Concrete/Brick/Stone and Half Wood	1,561	8	-	1	9
Galvanized Iron/Aluminum	44	-	-	-	1
Bamboo/Sawali/Cogon/Nipa	215	134	-	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	-	-	-	-
Others/Not Reported	27	-	-	-	34
No Walls	-	-	-	-	-

NATIVIDAD

Total	7	522	5	60	30
Concrete/Brick/Stone	1	17	-	8	3
Wood	1	7	-	-	1
Half Concrete/Brick/Stone and Half Wood	-	29	1	5	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	465	-	32	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	4	-	1
Others/Not Reported	-	3	-	15	19
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

POZZORUBIO

Total	576	414	17	4	26
Concrete/Brick/Stone	115	4	-	1	11
Wood	14	31	1	-	1
Half Concrete/Brick/Stone and Half Wood	401	5	-	-	4
Galvanized Iron/Aluminum	8	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	36	364	4	2	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	7	12	-	1
Others/Not Reported	-	2	-	1	9
No Walls	-	-	-	-	-

ROSALES

Total	1,443	814	17	64	74
Concrete/Brick/Stone	495	17	1	5	5
Wood	72	19	2	3	2
Half Concrete/Brick/Stone and Half Wood	506	30	1	2	10
Galvanized Iron/Aluminum	21	3	-	-	1
Bamboo/Sawali/Cogon/Nipa	321	738	7	45	6
Asbestos	1	-	-	1	1
Glass	-	-	-	1	-
Makeshift/Salvaged/Improvised Materials	2	1	6	-	-
Others/Not Reported	25	6	-	7	49
No Walls	-	-	-	-	-

SAN CARLOS CITY

Total	1,447	1,395	25	74	275
Concrete/Brick/Stone	23	6	-	5	41
Wood	443	81	1	-	6
Half Concrete/Brick/Stone and Half Wood	359	62	2	4	43
Galvanized Iron/Aluminum	87	47	2	7	4
Bamboo/Sawali/Cogon/Nipa	516	1,176	10	13	38
Asbestos	8	-	-	17	7
Glass	9	-	-	15	6
Makeshift/Salvaged/Improvised Materials	-	5	7	3	5
Others/Not Reported	2	17	2	5	125
No Walls	-	1	1	5	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

SAN FABIAN

Total	131	1,313	135	31	100
Concrete/Brick/Stone	15	33	39	4	11
Wood	82	119	31	1	5
Half Concrete/Brick/Stone and Half Wood	17	36	21	2	2
Galvanized Iron/Aluminum	2	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	1,089	13	18	12
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	23	30	-	-
Others/Not Reported	-	7	1	6	70
No Walls	-	-	-	-	-

SAN JACINTO

Total	57	373	7	16	67
Concrete/Brick/Stone	21	2	-	1	16
Wood	12	14	1	2	2
Half Concrete/Brick/Stone and Half Wood	7	5	-	4	12
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	17	347	1	7	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	5	2	-
Others/Not Reported	-	1	-	-	33
No Walls	-	-	-	-	-

SAN MANUEL

Total	86	715	1	-	62
Concrete/Brick/Stone	11	10	-	-	6
Wood	19	48	1	-	1
Half Concrete/Brick/Stone and Half Wood	13	28	-	-	2
Galvanized Iron/Aluminum	3	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	40	625	-	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	51
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

SAN NICOLAS

Total	24	783	3	16	22
Concrete/Brick/Stone	3	13	-	2	7
Wood	7	83	-	1	1
Half Concrete/Brick/Stone and Half Wood	-	17	-	1	4
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	659	1	8	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	2	-	-
Others/Not Reported	-	5	-	4	8
No Walls	-	-	-	-	-

SAN QUINTIN

Total	76	697	1	3	58
Concrete/Brick/Stone	-	6	-	-	-
Wood	13	9	-	-	-
Half Concrete/Brick/Stone and Half Wood	34	22	-	1	1
Galvanized Iron/Aluminum	1	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	28	657	-	2	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	1	-	-	56
No Walls	-	-	-	-	-

SANTA BARBARA

Total	153	1,057	27	16	69
Concrete/Brick/Stone	5	10	-	1	12
Wood	15	42	-	2	-
Half Concrete/Brick/Stone and Half Wood	61	33	-	-	9
Galvanized Iron/Aluminum	16	3	-	-	1
Bamboo/Sawali/Cogon/Nipa	54	956	9	7	16
Asbestos	-	-	-	1	-
Glass	1	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	2	18	-	-
Others/Not Reported	1	11	-	5	30
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

SANTA MARIA

Total	31	187	8	8	39
Concrete/Brick/Stone	-	-	-	1	4
Wood	18	4	-	-	-
Half Concrete/Brick/Stone and Half Wood	1	4	-	-	1
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	11	174	3	5	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	3	5	-	1
Others/Not Reported	-	2	-	2	30
No Walls	-	-	-	-	-

SANTO TOMAS

Total	2	71	1	-	2
Concrete/Brick/Stone	1	-	-	-	1
Wood	-	-	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	3	-	-	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	67	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	1	-	-	1
No Walls	-	-	-	-	-

SISON

Total	85	261	17	185	16
Concrete/Brick/Stone	-	-	-	21	3
Wood	15	5	2	1	-
Half Concrete/Brick/Stone and Half Wood	8	8	1	76	1
Galvanized Iron/Aluminum	-	6	-	1	-
Bamboo/Sawali/Cogon/Nipa	61	227	2	76	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	7	12	-	-
Others/Not Reported	-	8	-	10	8
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

SUAL

Total	19	890	191	36	40
Concrete/Brick/Stone	1	9	-	3	4
Wood	2	66	5	2	2
Half Concrete/Brick/Stone and Half Wood	1	14	8	-	3
Galvanized Iron/Aluminum	3	1	6	-	-
Bamboo/Sawali/Cogon/Nipa	11	776	160	23	9
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	16	12	5	-
Others/Not Reported	1	8	-	3	22
No Walls	-	-	-	-	-

TAYUG

Total	99	253	8	4	51
Concrete/Brick/Stone	39	7	-	-	13
Wood	34	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	14	8	-	-	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	12	231	-	4	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	8	-	-
Others/Not Reported	-	3	-	-	34
No Walls	-	-	-	-	-

UMINGAN

Total	166	2,510	54	7	49
Concrete/Brick/Stone	-	57	2	1	12
Wood	1	20	-	1	-
Half Concrete/Brick/Stone and Half Wood	4	101	44	-	6
Galvanized Iron/Aluminum	6	6	-	-	1
Bamboo/Sawali/Cogon/Nipa	154	2,310	7	5	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	1	-	-
Others/Not Reported	1	10	-	-	27
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

URBIZTONDO

Total	118	1,282	20	8	97
Concrete/Brick/Stone	-	5	-	-	8
Wood	9	20	1	-	-
Half Concrete/Brick/Stone and Half Wood	10	58	1	2	10
Galvanized Iron/Aluminum	16	9	-	-	8
Bamboo/Sawali/Cogon/Nipa	81	1,174	2	5	8
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	10	16	-	-
Others/Not Reported	2	6	-	1	62
No Walls	-	-	-	-	-

CITY OF URDANETA

Total	573	1,126	238	9	160
Concrete/Brick/Stone	156	6	25	5	33
Wood	214	217	13	-	6
Half Concrete/Brick/Stone and Half Wood	66	48	126	1	9
Galvanized Iron/Aluminum	10	12	-	1	1
Bamboo/Sawali/Cogon/Nipa	126	835	42	-	8
Asbestos	-	-	-	1	2
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	6	32	-	-
Others/Not Reported	-	2	-	1	101
No Walls	-	-	-	-	-

VILLASIS

Total	221	749	10	11	30
Concrete/Brick/Stone	-	6	-	5	8
Wood	200	92	1	-	1
Half Concrete/Brick/Stone and Half Wood	6	13	-	-	2
Galvanized Iron/Aluminum	2	1	-	-	1
Bamboo/Sawali/Cogon/Nipa	12	633	3	3	5
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	6	-	-
Others/Not Reported	1	2	-	3	13
No Walls	-	-	-	-	-

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported

LAOAC

Total	40	139	13	-	8
Concrete/Brick/Stone	-	-	-	-	2
Wood	17	6	-	-	1
Half Concrete/Brick/Stone and Half Wood	5	1	-	-	1
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	18	130	2	-	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	11	-	-
Others/Not Reported	-	-	-	-	2
No Walls	-	-	-	-	-