

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

QUIRINO

Total	35,793	30,695	70	1,232
Concrete/Brick/Stone	10,565	10,454	36	17
Wood	12,971	11,045	8	336
Half Concrete/Brick/Stone and Half Wood	7,955	6,989	25	693
Galvanized Iron/Aluminum	382	290	-	43
Bamboo/Sawali/Cogon/Nipa	3,627	1,768	-	135
Asbestos	2	1	-	-
Glass	8	6	1	1
Makeshift/Salvaged/Improvised Materials	111	55	-	1
Others/Not Reported	172	87	-	6
No Walls	-	-	-	-

AGLIPAY

Total	5,507	4,608	3	232
Concrete/Brick/Stone	1,617	1,613	2	1
Wood	1,940	1,624	1	20
Half Concrete/Brick/Stone and Half Wood	1,234	1,090	-	124
Galvanized Iron/Aluminum	42	34	-	7
Bamboo/Sawali/Cogon/Nipa	585	214	-	76
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	46	14	-	1
Others/Not Reported	43	19	-	3
No Walls	-	-	-	-

CABARROGUIS (Capital)

Total	5,879	5,413	10	19
Concrete/Brick/Stone	2,067	2,050	8	-
Wood	2,488	2,200	-	7
Half Concrete/Brick/Stone and Half Wood	795	778	2	9
Galvanized Iron/Aluminum	57	56	-	-
Bamboo/Sawali/Cogon/Nipa	431	298	-	3
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	8	6	-	-
Others/Not Reported	32	24	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

DIFFUN

Total	9,716	7,823	40	273
Concrete/Brick/Stone	3,143	3,070	21	10
Wood	2,954	2,337	4	82
Half Concrete/Brick/Stone and Half Wood	2,089	1,735	14	131
Galvanized Iron/Aluminum	141	81	-	23
Bamboo/Sawali/Cogon/Nipa	1,344	570	-	25
Asbestos	-	-	-	-
Glass	8	6	1	1
Makeshift/Salvaged/Improvised Materials	15	10	-	-
Others/Not Reported	22	14	-	1
No Walls	-	-	-	-

MADDELA

Total	7,360	6,337	13	679
Concrete/Brick/Stone	1,921	1,913	4	3
Wood	2,577	2,227	1	222
Half Concrete/Brick/Stone and Half Wood	2,405	1,976	8	412
Galvanized Iron/Aluminum	61	44	-	12
Bamboo/Sawali/Cogon/Nipa	346	157	-	28
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	14	8	-	-
Others/Not Reported	35	12	-	2
No Walls	-	-	-	-

SAGUDAY

Total	3,049	2,580	2	22
Concrete/Brick/Stone	1,092	1,087	1	3
Wood	321	275	1	2
Half Concrete/Brick/Stone and Half Wood	658	641	-	14
Galvanized Iron/Aluminum	53	47	-	1
Bamboo/Sawali/Cogon/Nipa	882	506	-	2
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	25	16	-	-
Others/Not Reported	18	8	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

NAGTIPUNAN

Total	4,282	3,934	2	7
Concrete/Brick/Stone	725	721	-	-
Wood	2,691	2,382	1	3
Half Concrete/Brick/Stone and Half Wood	774	769	1	3
Galvanized Iron/Aluminum	28	28	-	-
Bamboo/Sawali/Cogon/Nipa	39	23	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	1	-	-
Others/Not Reported	22	10	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
QUIRINO					
Total	474	3,169	13	39	101
Concrete/Brick/Stone	38	9	-	1	10
Wood	96	1,446	5	21	14
Half Concrete/Brick/Stone and Half Wood	198	38	-	6	6
Galvanized Iron/Aluminum	36	13	-	-	-
Bamboo/Sawali/Cogon/Nipa	104	1,604	4	8	4
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	51	4	-	-
Others/Not Reported	1	8	-	3	67
No Walls	-	-	-	-	-
AGLIPAY					
Total	5	612	1	28	18
Concrete/Brick/Stone	-	-	-	-	1
Wood	3	279	-	12	1
Half Concrete/Brick/Stone and Half Wood	-	13	-	6	1
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	283	-	7	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	30	1	-	-
Others/Not Reported	-	6	-	3	12
No Walls	-	-	-	-	-
CABARROGUIS (Capital)					
Total	9	405	1	4	18
Concrete/Brick/Stone	-	2	-	1	6
Wood	4	269	1	2	5
Half Concrete/Brick/Stone and Half Wood	1	5	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	125	-	1	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	1	-	-	7
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
DIFFUN					
Total	415	1,150	2	2	11
Concrete/Brick/Stone	38	2	-	-	2
Wood	62	465	-	2	2
Half Concrete/Brick/Stone and Half Wood	193	15	-	-	1
Galvanized Iron/Aluminum	31	6	-	-	-
Bamboo/Sawali/Cogon/Nipa	90	658	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	1	-	-
Others/Not Reported	1	-	-	-	6
No Walls	-	-	-	-	-
MADDELA					
Total	29	265	4	5	28
Concrete/Brick/Stone	-	-	-	-	1
Wood	14	105	-	5	3
Half Concrete/Brick/Stone and Half Wood	3	3	-	-	3
Galvanized Iron/Aluminum	5	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	152	2	-	1
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	2	-	-
Others/Not Reported	-	1	-	-	20
No Walls	-	-	-	-	-
SAGUDAY					
Total	2	431	1	-	11
Concrete/Brick/Stone	-	1	-	-	-
Wood	-	43	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	2	-	-	1
Galvanized Iron/Aluminum	-	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	371	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	9	-	-	-
Others/Not Reported	-	-	-	-	10
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
NAGTIPUNAN					
Total	14	306	4	-	15
Concrete/Brick/Stone	-	4	-	-	-
Wood	13	285	4	-	3
Half Concrete/Brick/Stone and Half Wood	1	-	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	15	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	2	-	-	-
Others/Not Reported	-	-	-	-	12
No Walls	-	-	-	-	-