

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

TARLAC

Total	254,218	207,167	2,114	20,740
Concrete/Brick/Stone	137,249	133,632	837	1,579
Wood	9,042	6,283	206	717
Half Concrete/Brick/Stone and Half Wood	61,867	43,247	804	15,425
Galvanized Iron/Aluminum	3,783	2,692	59	667
Bamboo/Sawali/Cogon/Nipa	39,733	20,180	-	2,276
Asbestos	36	17	-	-
Glass	69	41	7	2
Makeshift/Salvaged/Improvised Materials	734	368	-	38
Others/Not Reported	1,703	706	201	36
No Walls	2	1	-	-

ANAO

Total	2,410	2,203	-	81
Concrete/Brick/Stone	1,357	1,348	-	5
Wood	41	29	-	6
Half Concrete/Brick/Stone and Half Wood	506	470	-	27
Galvanized Iron/Aluminum	4	4	-	-
Bamboo/Sawali/Cogon/Nipa	482	340	-	43
Asbestos	-	-	-	-
Glass	7	7	-	-
Makeshift/Salvaged/Improvised Materials	2	1	-	-
Others/Not Reported	11	4	-	-
No Walls	-	-	-	-

BAMBAN

Total	11,221	9,586	49	669
Concrete/Brick/Stone	6,447	6,203	22	120
Wood	783	628	8	35
Half Concrete/Brick/Stone and Half Wood	2,907	2,319	5	477
Galvanized Iron/Aluminum	144	106	10	10
Bamboo/Sawali/Cogon/Nipa	855	290	-	25
Asbestos	1	-	-	-
Glass	1	-	1	-
Makeshift/Salvaged/Improvised Materials	5	2	-	1
Others/Not Reported	77	38	3	1
No Walls	1	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
CAMILING				
Total	17,342	15,393	78	811
Concrete/Brick/Stone	7,883	7,703	56	64
Wood	376	334	9	10
Half Concrete/Brick/Stone and Half Wood	4,502	3,925	8	509
Galvanized Iron/Aluminum	127	79	3	35
Bamboo/Sawali/Cogon/Nipa	4,322	3,281	-	188
Asbestos	1	1	-	-
Glass	2	2	-	-
Makeshift/Salvaged/Improvised Materials	39	21	-	3
Others/Not Reported	90	47	2	2
No Walls	-	-	-	-
CAPAS				
Total	23,553	19,957	42	497
Concrete/Brick/Stone	15,654	15,486	25	59
Wood	474	371	1	27
Half Concrete/Brick/Stone and Half Wood	3,481	2,996	10	336
Galvanized Iron/Aluminum	101	81	2	13
Bamboo/Sawali/Cogon/Nipa	3,760	991	-	62
Asbestos	-	-	-	-
Glass	4	2	-	-
Makeshift/Salvaged/Improvised Materials	25	11	-	-
Others/Not Reported	54	19	4	-
No Walls	-	-	-	-
CONCEPCION				
Total	25,148	20,742	162	2,173
Concrete/Brick/Stone	13,261	13,007	69	96
Wood	1,278	772	10	44
Half Concrete/Brick/Stone and Half Wood	7,284	4,982	73	1,945
Galvanized Iron/Aluminum	969	897	5	47
Bamboo/Sawali/Cogon/Nipa	2,161	1,002	-	35
Asbestos	1	-	-	-
Glass	8	4	3	-
Makeshift/Salvaged/Improvised Materials	81	11	-	2
Others/Not Reported	104	66	2	4
No Walls	1	1	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
GERONA				
Total	17,653	12,672	757	2,102
Concrete/Brick/Stone	8,666	8,296	246	69
Wood	513	285	63	44
Half Concrete/Brick/Stone and Half Wood	4,714	2,571	261	1,701
Galvanized Iron/Aluminum	350	227	13	66
Bamboo/Sawali/Cogon/Nipa	3,095	1,213	-	213
Asbestos	3	1	-	-
Glass	6	2	-	1
Makeshift/Salvaged/Improvised Materials	5	-	-	-
Others/Not Reported	301	77	174	8
No Walls	-	-	-	-
LA PAZ				
Total	11,659	7,713	55	2,212
Concrete/Brick/Stone	5,515	5,117	42	287
Wood	496	240	1	64
Half Concrete/Brick/Stone and Half Wood	3,553	1,540	12	1,672
Galvanized Iron/Aluminum	95	41	-	42
Bamboo/Sawali/Cogon/Nipa	1,930	749	-	143
Asbestos	1	1	-	-
Glass	5	4	-	1
Makeshift/Salvaged/Improvised Materials	25	12	-	1
Others/Not Reported	39	9	-	2
No Walls	-	-	-	-
MAYANTOC				
Total	6,145	5,142	15	326
Concrete/Brick/Stone	2,873	2,842	9	9
Wood	237	189	1	8
Half Concrete/Brick/Stone and Half Wood	1,233	1,018	3	192
Galvanized Iron/Aluminum	143	127	2	2
Bamboo/Sawali/Cogon/Nipa	1,629	953	-	115
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	3	2	-	-
Others/Not Reported	27	11	-	-
No Walls	-	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MONCADA				
Total	11,588	9,491	8	1,261
Concrete/Brick/Stone	5,903	5,587	2	226
Wood	172	124	-	24
Half Concrete/Brick/Stone and Half Wood	2,612	1,905	2	619
Galvanized Iron/Aluminum	50	42	1	7
Bamboo/Sawali/Cogon/Nipa	2,692	1,723	-	383
Asbestos	3	3	-	-
Glass	7	4	3	-
Makeshift/Salvaged/Improvised Materials	36	23	-	2
Others/Not Reported	113	80	-	-
No Walls	-	-	-	-
PANIQUE				
Total	18,281	15,021	350	1,031
Concrete/Brick/Stone	9,697	9,561	30	65
Wood	1,162	626	18	230
Half Concrete/Brick/Stone and Half Wood	3,858	2,913	290	546
Galvanized Iron/Aluminum	336	101	4	103
Bamboo/Sawali/Cogon/Nipa	3,107	1,775	-	86
Asbestos	6	2	-	-
Glass	7	5	-	-
Makeshift/Salvaged/Improvised Materials	57	24	-	1
Others/Not Reported	51	14	8	-
No Walls	-	-	-	-
PURA				
Total	4,836	3,829	2	381
Concrete/Brick/Stone	2,888	2,783	2	38
Wood	55	45	-	1
Half Concrete/Brick/Stone and Half Wood	1,107	763	-	294
Galvanized Iron/Aluminum	25	13	-	12
Bamboo/Sawali/Cogon/Nipa	699	202	-	32
Asbestos	-	-	-	-
Glass	9	6	-	-
Makeshift/Salvaged/Improvised Materials	11	6	-	3
Others/Not Reported	42	11	-	1
No Walls	-	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
RAMOS				
Total	4,117	2,319	28	832
Concrete/Brick/Stone	1,450	1,392	26	14
Wood	49	29	-	3
Half Concrete/Brick/Stone and Half Wood	1,723	770	2	763
Galvanized Iron/Aluminum	46	34	-	8
Bamboo/Sawali/Cogon/Nipa	818	89	-	40
Asbestos	-	-	-	-
Glass	1	1	-	-
Makeshift/Salvaged/Improvised Materials	10	1	-	1
Others/Not Reported	20	3	-	3
No Walls	-	-	-	-
SAN CLEMENTE				
Total	2,667	2,497	14	28
Concrete/Brick/Stone	1,463	1,445	10	4
Wood	151	147	-	1
Half Concrete/Brick/Stone and Half Wood	436	419	3	10
Galvanized Iron/Aluminum	17	11	-	3
Bamboo/Sawali/Cogon/Nipa	579	469	-	10
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	1	-	-
Others/Not Reported	20	5	1	-
No Walls	-	-	-	-
SAN MANUEL				
Total	4,798	3,990	9	507
Concrete/Brick/Stone	2,543	2,533	3	2
Wood	90	66	-	5
Half Concrete/Brick/Stone and Half Wood	1,165	690	3	461
Galvanized Iron/Aluminum	69	39	2	26
Bamboo/Sawali/Cogon/Nipa	866	606	-	12
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	9	7	-	-
Others/Not Reported	56	49	1	1
No Walls	-	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
SANTA IGNACIA				
Total	9,569	7,749	44	957
Concrete/Brick/Stone	4,856	4,794	43	16
Wood	68	59	-	1
Half Concrete/Brick/Stone and Half Wood	2,136	1,457	1	663
Galvanized Iron/Aluminum	85	51	-	31
Bamboo/Sawali/Cogon/Nipa	2,356	1,354	-	245
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	10	8	-	-
Others/Not Reported	57	25	-	1
No Walls	-	-	-	-
CITY OF TARLAC (Capital)				
Total	64,445	54,823	414	5,446
Concrete/Brick/Stone	37,438	36,505	223	446
Wood	2,816	2,122	95	197
Half Concrete/Brick/Stone and Half Wood	17,071	12,204	75	4,170
Galvanized Iron/Aluminum	1,030	724	16	195
Bamboo/Sawali/Cogon/Nipa	5,250	2,893	-	404
Asbestos	18	7	-	-
Glass	10	3	-	-
Makeshift/Salvaged/Improvised Materials	357	195	-	22
Others/Not Reported	455	170	5	12
No Walls	-	-	-	-
VICTORIA				
Total	12,161	9,673	79	934
Concrete/Brick/Stone	7,006	6,735	22	45
Wood	176	138	-	13
Half Concrete/Brick/Stone and Half Wood	2,444	1,587	55	685
Galvanized Iron/Aluminum	95	44	1	42
Bamboo/Sawali/Cogon/Nipa	2,295	1,121	-	146
Asbestos	-	-	-	-
Glass	2	1	-	-
Makeshift/Salvaged/Improvised Materials	51	40	-	2
Others/Not Reported	92	7	1	1
No Walls	-	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/ Aluminum	Tile Concrete/ Clay Tile	Half Galvanized Iron and Half Concrete

SAN JOSE

Total	6,625	4,367	8	492
Concrete/Brick/Stone	2,349	2,295	7	14
Wood	105	79	-	4
Half Concrete/Brick/Stone and Half Wood	1,135	718	1	355
Galvanized Iron/Aluminum	97	71	-	25
Bamboo/Sawali/Cogon/Nipa	2,837	1,129	-	94
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	7	3	-	-
Others/Not Reported	94	71	-	-
No Walls	-	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
TARLAC					
Total	4,150	17,511	402	295	1,839
Concrete/Brick/Stone	293	264	12	64	568
Wood	1,150	600	27	5	54
Half Concrete/Brick/Stone and Half Wood	1,070	910	52	44	315
Galvanized Iron/Aluminum	286	65	4	2	8
Bamboo/Sawali/Cogon/Nipa	1,313	15,552	63	118	231
Asbestos	5	-	-	14	-
Glass	7	-	-	6	6
Makeshift/Salvaged/Improvised Materials	14	63	242	4	5
Others/Not Reported	12	57	2	37	652
No Walls	-	-	-	1	-
ANAPO					
Total	10	104	5	1	6
Concrete/Brick/Stone	1	3	-	-	-
Wood	1	1	4	-	-
Half Concrete/Brick/Stone and Half Wood	5	4	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	3	95	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	-	-	-
Others/Not Reported	-	-	-	1	6
No Walls	-	-	-	-	-
BAMBAN					
Total	212	586	16	1	102
Concrete/Brick/Stone	39	11	2	-	50
Wood	42	60	7	-	3
Half Concrete/Brick/Stone and Half Wood	41	48	2	-	15
Galvanized Iron/Aluminum	16	1	1	-	-
Bamboo/Sawali/Cogon/Nipa	72	463	3	-	2
Asbestos	1	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	1	-	-
Others/Not Reported	-	3	-	-	32
No Walls	-	-	-	1	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
CAMILING					
Total	105	795	17	1	142
Concrete/Brick/Stone	4	5	-	-	51
Wood	10	4	-	-	9
Half Concrete/Brick/Stone and Half Wood	9	21	-	-	30
Galvanized Iron/Aluminum	8	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	71	760	2	-	20
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	15	-	-
Others/Not Reported	3	3	-	1	32
No Walls	-	-	-	-	-
CAPAS					
Total	86	2,879	18	5	69
Concrete/Brick/Stone	2	47	1	2	32
Wood	29	43	1	-	2
Half Concrete/Brick/Stone and Half Wood	13	116	2	-	8
Galvanized Iron/Aluminum	2	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	38	2,659	4	2	4
Asbestos	-	-	-	-	-
Glass	2	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	9	-	-
Others/Not Reported	-	7	-	1	23
No Walls	-	-	-	-	-
CONCEPCION					
Total	717	1,103	104	6	141
Concrete/Brick/Stone	14	16	1	1	57
Wood	379	54	8	2	9
Half Concrete/Brick/Stone and Half Wood	142	84	22	2	34
Galvanized Iron/Aluminum	8	8	1	1	2
Bamboo/Sawali/Cogon/Nipa	169	934	15	-	6
Asbestos	1	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	4	6	57	-	1
Others/Not Reported	-	1	-	-	31
No Walls	-	-	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
GERONA					
Total	587	1,352	22	9	152
Concrete/Brick/Stone	8	13	-	2	32
Wood	89	23	2	-	7
Half Concrete/Brick/Stone and Half Wood	58	70	6	3	44
Galvanized Iron/Aluminum	32	12	-	-	-
Bamboo/Sawali/Cogon/Nipa	398	1,225	10	1	35
Asbestos	-	-	-	2	-
Glass	-	-	-	-	3
Makeshift/Salvaged/Improvised Materials	-	1	4	-	-
Others/Not Reported	2	8	-	1	31
No Walls	-	-	-	-	-
LA PAZ					
Total	449	1,093	13	1	123
Concrete/Brick/Stone	5	9	2	-	53
Wood	114	74	1	-	2
Half Concrete/Brick/Stone and Half Wood	236	65	2	1	25
Galvanized Iron/Aluminum	11	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	82	936	3	-	17
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	5	5	-	1
Others/Not Reported	-	3	-	-	25
No Walls	-	-	-	-	-
MAYANTOC					
Total	49	587	-	-	26
Concrete/Brick/Stone	3	3	-	-	7
Wood	3	35	-	-	1
Half Concrete/Brick/Stone and Half Wood	4	14	-	-	2
Galvanized Iron/Aluminum	7	3	-	-	2
Bamboo/Sawali/Cogon/Nipa	30	527	-	-	4
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	1
Others/Not Reported	2	5	-	-	9
No Walls	-	-	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported
MONCADA					
Total	24	555	7	31	211
Concrete/Brick/Stone	-	9	-	-	79
Wood	13	10	-	-	1
Half Concrete/Brick/Stone and Half Wood	1	26	-	4	55
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	10	501	1	25	49
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	6	-	-
Others/Not Reported	-	4	-	2	27
No Walls	-	-	-	-	-
PANIKUI					
Total	427	1,355	24	1	72
Concrete/Brick/Stone	10	16	-	-	15
Wood	130	153	1	-	4
Half Concrete/Brick/Stone and Half Wood	49	45	4	-	11
Galvanized Iron/Aluminum	111	15	-	-	2
Bamboo/Sawali/Cogon/Nipa	120	1,112	3	-	11
Asbestos	3	-	-	1	-
Glass	2	-	-	-	-
Makeshift/Salvaged/Improvised Materials	2	14	16	-	-
Others/Not Reported	-	-	-	-	29
No Walls	-	-	-	-	-
PURA					
Total	12	522	1	-	89
Concrete/Brick/Stone	-	18	-	-	47
Wood	3	6	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	44	-	-	6
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	452	-	-	7
Asbestos	-	-	-	-	-
Glass	3	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	1	-	-	29
No Walls	-	-	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported
RAMOS					
Total	23	807	2	63	43
Concrete/Brick/Stone	2	12	-	-	4
Wood	4	11	-	2	-
Half Concrete/Brick/Stone and Half Wood	2	148	-	18	20
Galvanized Iron/Aluminum	1	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	626	-	32	17
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	4	2	2	-
Others/Not Reported	-	3	-	9	2
No Walls	-	-	-	-	-
SAN CLEMENTE					
Total	8	99	2	2	17
Concrete/Brick/Stone	-	2	-	1	1
Wood	1	2	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	3	1	-	-
Galvanized Iron/Aluminum	3	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	4	92	1	1	2
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	14
No Walls	-	-	-	-	-
SAN MANUEL					
Total	24	249	1	9	9
Concrete/Brick/Stone	1	1	-	1	2
Wood	10	9	-	-	-
Half Concrete/Brick/Stone and Half Wood	5	4	-	-	2
Galvanized Iron/Aluminum	-	2	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	232	-	7	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	-	-	1	4
No Walls	-	-	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SANTA IGNACIA					
Total	25	747	4	1	42
Concrete/Brick/Stone	-	2	-	-	1
Wood	3	5	-	-	-
Half Concrete/Brick/Stone and Half Wood	7	6	-	-	2
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	15	729	3	1	9
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	1	-	-
Others/Not Reported	-	1	-	-	30
No Walls	-	-	-	-	-
CITY OF TARLAC (Capital)					
Total	1,039	2,025	150	106	442
Concrete/Brick/Stone	48	43	4	54	115
Wood	303	81	3	-	15
Half Concrete/Brick/Stone and Half Wood	422	125	12	11	52
Galvanized Iron/Aluminum	84	8	1	1	1
Bamboo/Sawali/Cogon/Nipa	172	1,740	11	8	22
Asbestos	-	-	-	11	-
Glass	-	-	-	6	1
Makeshift/Salvaged/Improvised Materials	6	14	117	1	2
Others/Not Reported	4	14	2	14	234
No Walls	-	-	-	-	-
VICTORIA					
Total	300	1,054	12	3	106
Concrete/Brick/Stone	150	41	-	1	12
Wood	15	9	-	-	1
Half Concrete/Brick/Stone and Half Wood	51	58	1	2	5
Galvanized Iron/Aluminum	3	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	80	936	6	-	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	1
Makeshift/Salvaged/Improvised Materials	-	4	5	-	-
Others/Not Reported	1	1	-	-	81
No Walls	-	-	-	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported

SAN JOSE

Total	53	1,599	4	55	47
Concrete/Brick/Stone	6	13	2	2	10
Wood	1	20	-	1	-
Half Concrete/Brick/Stone and Half Wood	25	29	-	3	4
Galvanized Iron/Aluminum	-	-	-	-	1
Bamboo/Sawali/Cogon/Nipa	21	1,533	-	41	19
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	1	2	1	-
Others/Not Reported	-	3	-	7	13
No Walls	-	-	-	-	-