

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

TAWI-TAWI

Total	69,541	42,773	220	758
Concrete/Brick/Stone	3,863	3,726	52	44
Wood	51,391	35,708	153	534
Half Concrete/Brick/Stone and Half Wood	1,453	1,262	8	146
Galvanized Iron/Aluminum	56	24	2	3
Bamboo/Sawali/Cogon/Nipa	12,236	1,967	-	31
Asbestos	10	7	-	-
Glass	2	-	-	-
Makeshift/Salvaged/Improvised Materials	35	6	-	-
Others/Not Reported	495	73	5	-
No Walls	-	-	-	-

PANGLIMA SUGALA (BALIMBING) (Capital)

Total	7,909	3,134	16	65
Concrete/Brick/Stone	69	53	-	5
Wood	5,432	2,918	16	48
Half Concrete/Brick/Stone and Half Wood	70	43	-	11
Galvanized Iron/Aluminum	8	2	-	1
Bamboo/Sawali/Cogon/Nipa	2,235	108	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	95	10	-	-
No Walls	-	-	-	-

BONGAO

Total	15,576	10,795	50	491
Concrete/Brick/Stone	1,711	1,640	30	30
Wood	11,548	8,430	16	332
Half Concrete/Brick/Stone and Half Wood	677	539	4	122
Galvanized Iron/Aluminum	7	3	-	-
Bamboo/Sawali/Cogon/Nipa	1,428	145	-	7
Asbestos	4	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	12	2	-	-
Others/Not Reported	189	34	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
MAPUN (CAGAYAN DE TAWI-TAWI)				
Total	4,783	2,960	4	12
Concrete/Brick/Stone	251	250	-	1
Wood	1,401	1,283	2	3
Half Concrete/Brick/Stone and Half Wood	175	174	-	-
Galvanized Iron/Aluminum	14	9	1	-
Bamboo/Sawali/Cogon/Nipa	2,910	1,240	-	8
Asbestos	1	1	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	31	3	1	-
No Walls	-	-	-	-
SIMUNUL				
Total	3,257	2,595	32	5
Concrete/Brick/Stone	669	656	10	-
Wood	2,105	1,836	22	2
Half Concrete/Brick/Stone and Half Wood	89	87	-	2
Galvanized Iron/Aluminum	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	375	15	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	18	1	-	-
No Walls	-	-	-	-
SITANGKAI				
Total	6,172	5,119	21	17
Concrete/Brick/Stone	170	159	3	3
Wood	5,249	4,707	17	7
Half Concrete/Brick/Stone and Half Wood	132	123	1	7
Galvanized Iron/Aluminum	3	3	-	-
Bamboo/Sawali/Cogon/Nipa	598	121	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	20	6	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
SOUTH UBIAN				
Total	6,059	3,796	6	8
Concrete/Brick/Stone	95	94	-	-
Wood	5,216	3,583	5	7
Half Concrete/Brick/Stone and Half Wood	49	47	1	-
Galvanized Iron/Aluminum	4	1	-	-
Bamboo/Sawali/Cogon/Nipa	657	67	-	1
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	38	4	-	-
No Walls	-	-	-	-
TANDUBAS				
Total	5,335	3,837	21	3
Concrete/Brick/Stone	76	74	-	-
Wood	4,796	3,649	19	3
Half Concrete/Brick/Stone and Half Wood	32	31	-	-
Galvanized Iron/Aluminum	2	1	-	-
Bamboo/Sawali/Cogon/Nipa	397	71	-	-
Asbestos	-	-	-	-
Glass	2	-	-	-
Makeshift/Salvaged/Improvised Materials	9	3	-	-
Others/Not Reported	21	8	2	-
No Walls	-	-	-	-
TURTLE ISLANDS				
Total	1,173	914	1	7
Concrete/Brick/Stone	22	22	-	-
Wood	979	771	1	7
Half Concrete/Brick/Stone and Half Wood	89	89	-	-
Galvanized Iron/Aluminum	3	2	-	-
Bamboo/Sawali/Cogon/Nipa	73	30	-	-
Asbestos	-	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	6	-	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
LANGUYAN				
Total	8,618	1,851	26	128
Concrete/Brick/Stone	29	27	-	-
Wood	5,788	1,658	24	108
Half Concrete/Brick/Stone and Half Wood	16	9	-	4
Galvanized Iron/Aluminum	11	2	-	2
Bamboo/Sawali/Cogon/Nipa	2,732	154	-	14
Asbestos	1	-	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	12	1	-	-
Others/Not Reported	29	-	2	-
No Walls	-	-	-	-
SAPA-SAPA				
Total	6,170	3,992	16	22
Concrete/Brick/Stone	205	189	5	5
Wood	5,383	3,743	8	17
Half Concrete/Brick/Stone and Half Wood	48	45	2	-
Galvanized Iron/Aluminum	3	1	1	-
Bamboo/Sawali/Cogon/Nipa	488	6	-	-
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	1	-	-	-
Others/Not Reported	40	6	-	-
No Walls	-	-	-	-
SIBUTU				
Total	4,489	3,780	27	-
Concrete/Brick/Stone	566	562	4	-
Wood	3,494	3,130	23	-
Half Concrete/Brick/Stone and Half Wood	76	75	-	-
Galvanized Iron/Aluminum	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	343	10	-	-
Asbestos	2	2	-	-
Glass	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-
Others/Not Reported	8	1	-	-
No Walls	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
TAWI-TAWI					
Total	205	24,999	38	167	381
Concrete/Brick/Stone	1	26	2	7	5
Wood	106	14,666	18	142	64
Half Concrete/Brick/Stone and Half Wood	7	19	-	8	3
Galvanized Iron/Aluminum	5	22	-	-	-
Bamboo/Sawali/Cogon/Nipa	83	10,130	10	3	12
Asbestos	-	-	-	2	1
Glass	2	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	20	8	1	-
Others/Not Reported	1	116	-	4	296
No Walls	-	-	-	-	-
PANGLIMA SUGALA (BALIMBING) (Capital)					
Total	34	4,482	1	88	89
Concrete/Brick/Stone	-	3	-	7	1
Wood	15	2,360	-	72	3
Half Concrete/Brick/Stone and Half Wood	3	5	-	7	1
Galvanized Iron/Aluminum	2	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	14	2,107	1	2	3
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	4	-	-	81
No Walls	-	-	-	-	-
BONGAO					
Total	37	4,055	19	15	114
Concrete/Brick/Stone	-	8	-	-	3
Wood	28	2,691	14	9	28
Half Concrete/Brick/Stone and Half Wood	3	6	-	1	2
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	1,267	-	1	2
Asbestos	-	-	-	2	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	5	5	-	-
Others/Not Reported	-	74	-	2	79
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported
MAPUN (CAGAYAN DE TAWI-TAWI)					
Total	1	1,774	-	2	30
Concrete/Brick/Stone	-	-	-	-	-
Wood	-	108	-	2	3
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	4	-	-	-
Bamboo/Sawali/Cogon/Nipa	1	1,655	-	-	6
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	6	-	-	21
No Walls	-	-	-	-	-
SIMUNUL					
Total	4	602	1	-	18
Concrete/Brick/Stone	-	2	-	-	1
Wood	2	241	-	-	2
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	356	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	2	-	-	15
No Walls	-	-	-	-	-
SITANGKAI					
Total	15	985	1	-	14
Concrete/Brick/Stone	1	4	-	-	-
Wood	7	509	1	-	1
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	7	470	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	1	-	-	13
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
SOUTH UBIAN					
Total	12	2,205	2	1	29
Concrete/Brick/Stone	-	1	-	-	-
Wood	10	1,609	1	1	-
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	3	-	-	-
Bamboo/Sawali/Cogon/Nipa	2	586	1	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	5	-	-	29
No Walls	-	-	-	-	-
TANDUBAS					
Total	26	1,435	-	-	13
Concrete/Brick/Stone	-	2	-	-	-
Wood	17	1,104	-	-	4
Half Concrete/Brick/Stone and Half Wood	1	-	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	5	321	-	-	-
Asbestos	-	-	-	-	-
Glass	2	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	6	-	-	-
Others/Not Reported	1	1	-	-	9
No Walls	-	-	-	-	-
TURTLE ISLANDS					
Total	5	239	1	-	6
Concrete/Brick/Stone	-	-	-	-	-
Wood	4	196	-	-	-
Half Concrete/Brick/Stone and Half Wood	-	-	-	-	-
Galvanized Iron/Aluminum	1	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	-	43	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	1	-	-
Others/Not Reported	-	-	-	-	6
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and City/Municipality: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
LANGUYAN					
Total	46	6,521	9	16	21
Concrete/Brick/Stone	-	2	-	-	-
Wood	12	3,960	-	16	10
Half Concrete/Brick/Stone and Half Wood	-	3	-	-	-
Galvanized Iron/Aluminum	2	5	-	-	-
Bamboo/Sawali/Cogon/Nipa	32	2,525	7	-	-
Asbestos	-	-	-	-	1
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	9	2	-	-
Others/Not Reported	-	17	-	-	10
No Walls	-	-	-	-	-
SAPA-SAPA					
Total	13	2,041	4	45	37
Concrete/Brick/Stone	-	4	2	-	-
Wood	7	1,554	2	42	10
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	1	-	-	-
Bamboo/Sawali/Cogon/Nipa	6	475	-	-	1
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	1	-
Others/Not Reported	-	6	-	2	26
No Walls	-	-	-	-	-
SIBUTU					
Total	12	660	-	-	10
Concrete/Brick/Stone	-	-	-	-	-
Wood	4	334	-	-	3
Half Concrete/Brick/Stone and Half Wood	-	1	-	-	-
Galvanized Iron/Aluminum	-	-	-	-	-
Bamboo/Sawali/Cogon/Nipa	8	325	-	-	-
Asbestos	-	-	-	-	-
Glass	-	-	-	-	-
Makeshift/Salvaged/Improvised Materials	-	-	-	-	-
Others/Not Reported	-	-	-	-	7
No Walls	-	-	-	-	-