

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete

BAGUIO CITY

Total	69,685	62,816	3,048	2,093
Concrete/Brick/Stone	34,739	31,127	2,566	508
Wood	5,026	4,366	41	194
Half Concrete/Brick/Stone and Half Wood	19,886	17,891	395	1,282
Galvanized Iron/Aluminum	8,844	8,665	30	101
Bamboo/Sawali/Cogon/Nipa	31	19	-	-
Asbestos	16	4	2	-
Glass	116	95	4	-
Makeshift/Salvaged/Improvised Materials	371	292	-	-
Others/Not Reported	651	354	10	8
No Walls	5	3	-	-

Table 9. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/Anahaw	Makeshift/Salvaged/Improvised materials	Asbestos/Others	Not Reported
<b>BAGUIO CITY</b>					
Total	598	19	117	573	421
Concrete/Brick/Stone	103	3	29	307	96
Wood	263	6	1	152	3
Half Concrete/Brick/Stone and Half Wood	177	1	13	87	40
Galvanized Iron/Aluminum	33	2	1	4	8
Bamboo/Sawali/Cogon/Nipa	3	7	-	-	2
Asbestos	-	-	-	10	-
Glass	14	-	-	1	2
Makeshift/Salvaged/Improvised Materials	4	-	70	4	1
Others/Not Reported	1	-	3	7	268
No Walls	-	-	-	1	1