

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls and City/Municipality	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
<b>ZAMBOANGA CITY</b>				
Total	149,622	102,611	1,093	6,706
Concrete/Brick/Stone	29,275	28,001	587	369
Wood	58,169	45,115	197	1,611
Half Concrete/Brick/Stone and Half Wood	23,023	18,367	228	3,397
Galvanized Iron/Aluminum	1,233	598	29	412
Bamboo/Sawali/Cogon/Nipa	35,607	9,740	-	870
Asbestos	255	230	3	7
Glass	39	23	12	1
Makeshift/Salvaged/Improvised Materials	498	125	-	3
Others/Not Reported	1,513	407	37	36
No walls	10	5	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls: 2007

Construction Materials of the Outer Walls and City/Municipality	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
ZAMBOANGA CITY					
Total	3,935	33,685	449	258	885
Concrete/Brick/Stone	88	118	66	16	30
Wood	2,527	8,386	127	171	35
Half Concrete/Brick/Stone and Half Wood	536	419	33	20	23
Galvanized Iron/Aluminum	122	70	-	1	1
Bamboo/Sawali/Cogon/Nipa	596	24,264	58	26	53
Asbestos	7	-	-	8	-
Glass	2	-	-	1	-
Makeshift/Salvaged/Improvised Materials	26	179	161	2	2
Others/Not Reported	31	248	-	13	741
No walls	-	1	4	-	-